



**Technical Service
Information Bulletin**

June 8, 2007

Title:

INNER REAR VIEW MIRROR VIBRATION

Models:

'06 GS 300, '06 - '07 GS 430, & '07 GS 350/450h

NVH
NV007-07

Introduction Some 2006 and 2007 model year GS 300/350/430/450h vehicle customers may complain of a vibration from the inner rear view mirror while driving, most noticeably with the moon roof open. A new mirror assembly is available to improve this condition.

Applicable Vehicles

- **2006** model year **GS 300** vehicles.
- **2006 - 2007** model year **GS 430** vehicles produced **BEFORE** the Production Change Effective VIN shown below.
- **2007** model year **GS 350/450h** vehicles produced **BEFORE** the Production Change Effective VIN shown below.

Production Change Information

MODEL	PLANT	PRODUCTION CHANGE EFFECTIVE VIN
GS 350	Tahara	JTHBE96S870018438
		JTHCE96S170007222
GS 430		JTHBN96S775017266
GS 450h		JTHBC96S375009333

Parts Information

PREVIOUS PART NUMBER	CURRENT PART NUMBER	PART NAME	QTY
87810-30340	Same	Mirror Assembly, Inner Rear View	1

Repair Procedure

Remove and replace the inner rear view mirror assembly. Refer to the Technical Information System (TIS), 2006 or 2007 model year GS 300, GS 350, GS 430, or GS 450h Repair Manual:

- *Vehicle Interior - Mirror (Int) - "Mirror: Inner Rear View Mirror: Installation"*.
- *Vehicle Interior - Mirror (Int) - "Mirror: Inner Rear View Mirror: Removal"*.

Warranty Information

OP CODE	DESCRIPTION	TIME	OFP	T1	T2
752021	R & R Inner Rear View Mirror	0.2	87810-#####	62	43

Applicable Warranty*:

This repair is covered under the Lexus Comprehensive Warranty. This warranty is in effect for 48 months or 50,000 miles, whichever occurs first, from the vehicle's in-service date.

* Warranty application is limited to correction of a problem based upon a customer's specific complaint.

