Technical Service Information Bulletin

January 7, 2004

Title:

TILT/TELESCOPIC STEERING NOISE/SMOOTHNESS IMPROVEMENT

Models:

'98 – '03 LX 470

Introduction

Some 1998 – 2003 model year LX470 vehicles may experience steering column noise. The cable has been replaced with a universal joint to reduce the steering column noise. Follow the repair procedures described below.

Applicable Vehicles

• 1998 - 2003 model year LX 470 vehicles.

MODEL	MODEL APPLICABLE VEHICLE VIN RANGE	
'02 – '03 LX 470	JTJHT00W#23514198 to JTJHT00W#33530604	А
'98 – '02 LX 470	JT6HT00W#W0001038 to JTJHT00W#23514197	A and B

^{*} Refer to Parts Information Table.

Parts Information

PROCEDURE PARTS	PREVIOUS PART NUMBER	CURRENT PART NUMBER	PARTNAME	QTY
А	N/A	45230–50020	Joint Assembly, Steering Shaft Universal	1
В	45766–60011	Same	Support, Telescopic Steering Slider	1
	45898–60020	Same	Bolt, Support Stopper	2

Warranty Information


OP CODE	DESCRIPTION	TIME	OFP	T1	T2
ST3004	Steering Shaft Universal Joint Assembly Replacement	0.9	45767–60010	4.4	44
ST3005	Telescopic Steering Slider Support/ Steering Shaft Universal Joint	1.0		44	44

Applicable Warranty*:


This repair is covered under the Lexus Comprehensive Warranty. This warranty is in effect for 48 months or 50,000 miles, whichever occurs first, from the vehicle's in-service date.

^{*} Warranty application is limited to correction of a problem based upon a customer's specific complaint.

Steering Column Components



Steering Column Components (Continued)



Repair Procedure: Preparation

1. Remove Lower No. 1 Panel.

- A. Remove the 2 screws and disconnect the hood lock release lever from the panel.
- B. Remove the 2 screws and disconnect the fuel lid release lever from the panel.
- C. Remove the pad set screw.

NOTE:

Tape up the screwdriver tip before use.

2. Remove LH Lower Panel.

A. Remove the 4 bolts and the LH lower panel.

3. Remove No. 2 Heater to Register Duct.

A. Remove the screw and the No. 2 heater to register duct.


4. Remove Column Cover.

A. Remove the 3 screws and the column cover.

Repair Procedure A


1. Remove Power Telescopic Motor.


A. Remove the 2 bolts and the power telescopic motor.



2. Remove Telescopic Steering Column Cable Assembly.

A. Remove the telescopic steering column cable.






Repair Procedure A (Continued)

3. Install Steering Shaft Universal Joint Assembly.

- A. Install the steering shaft universal joint assembly.
- B. Tighten the power telescopic motor with 2 bolts.

Torque: 9 N·m (90 kgf·cm, 78 in.•lbf)



Repair Procedure B

Replace Telescopic Steering Support and Support Stopper Bolts.

- A. Check the VIN number.
- B. If necessary, replace the telescopic steering support and support stopper bolts.

Torque: 11 N•m (110 kgf•cm, 8 ft•lbf)

2. Inspect Power Telescopic Function.

- A. Connect the negative battery terminal.
- B. Check that the power telescopic function operates properly.
- C. Disconnect the negative battery terminal.
- 3. Install Column Cover.
- 4. Install No. 2 Heater to Register Duct.
- 5. Install LH Lower Panel.
- 6. Install Lower No. 1 Panel.
- 7. Connect Negative Battery Terminal.

