



**Technical Service  
Information Bulletin**

November 10, 2004

Title:  
**NAVIGATION SYSTEM  
DOOR REPLACEMENT**

Models:  
**'02 – '05 SC 430**

**BODY**  
**BO011-04**

**Introduction** The navigation system door can now be replaced without having to replace the complete instrument cluster with multi-display unit. Use the following procedures to replace the navigation system door.

- Applicable Vehicles**
- **2002 – 2005** model year **SC 430** vehicles equipped with **Lexus Navigation System**.

**Parts  
Information**

PREVIOUS PART NUMBER	CURRENT PART NUMBER	INTERIOR COLOR	PART NAME	QTY
N/A	55412-24050-B0	Ecru Brown	Panel, Instrument Cluster Finish, CTR	1
	55412-24050-D0	Red		
	55412-24050-E0	Saddle/Black		

**Warranty  
Information**

OP CODE	DESCRIPTION	TIME	OFFP	T1	T2
BD4016	R & R Navigation Door	0.4	55401-24100-C0	99	99

**Applicable Warranty\*:**

This repair is covered under the Lexus Comprehensive Warranty. This warranty is in effect for 48 months or 50,000 miles, whichever occurs first, from the vehicle's in-service date.

\* Warranty application is limited to correction of a problem based upon a customer's specific complaint.

**Precaution**


**NOTE:**

- Refer to the Technical Information System (TIS), applicable model year SC 430 Repair Manual for the procedure for removing the instrument cluster finish panel sub-assembly center with multi-display.
- Be careful not to install improper types of screws.




**Preparation Procedure**

1. Remove Air Conditioner Control Assembly.
2. Remove Instrument Panel Safety Pad Garnish Sub-assembly.
3. Remove Instrument Panel Garnish Sub-assembly No. 2.
4. Remove Instrument Cluster Finish Panel Sub-assembly Center.
  - A. Remove the 2 bolts and 2 screws.
  - B. Disconnect the connector, then remove the multi-display (Center Display) display and instrument cluster finish panel sub-assembly center and clip.




**Components**




**Repair Procedure**

1. Remove Instrument Panel Upper Bracket No. 2 (2005 model year only).
  - A. Remove the 4 screws from the instrument panel upper bracket No. 2.
  - B. Remove the instrument panel upper bracket No. 2.




2. Remove Instrument Panel Finish Panel Upper.
  - A. Remove the 4 screws from the instrument panel finish panel upper.
  - B. Remove the instrument panel finish panel upper.



3. Loosen Instrument Panel Finish Panel No. 1 Retainer.
  - A. Loosen the 5 screws which secure the instrument panel finish panel No. 1 retainer.


**NOTE:**  
Do not loosen ground screw.



**Repair Procedure**  
(Continued)


4. Remove Instrument Cluster Finish Panel Center Sub-assembly.
  - A. Pull the shaft of the instrument cluster finish lower panel sub-assembly backward to fully open the instrument cluster finish panel center.
  - B. Separate the 2 clamps, and then carefully remove the instrument cluster finish panel center sub-assembly.

**NOTE:**  
Increase the width of the instrument panel finish panel No. 1 and No. 2 retainers by pushing them outward by approximately 2 mm (0.079 in.), and then remove the instrument cluster finish panel center sub-assembly.



5. Replace Instrument Cluster Finish Panel Center.
  - A. Remove the 3 screws, and then remove the instrument cluster finish panel center.
  - B. Install a new instrument cluster finish panel center on the instrument cluster finish lower panel sub-assembly.


**CAUTION:**  
Be careful not to damage the 3 positioning claws in area A.



- C. Tighten the 3 screws.  
Torque: 0.67 to 0.71 N•m  
(6.83 to 7.24 kgf•cm, 0.49 to 0.52 ft•lbf)

**Repair Procedure**  
(Continued)

6. Install Instrument Cluster Finish Panel Center Sub-assembly.
  - A. Install the instrument cluster finish panel center sub-assembly.
  - B. Fit the shaft of the instrument cluster finish lower panel sub-assembly into the 2 clamps.
  - C. Pull the shaft of the instrument cluster finish lower panel sub-assembly backward.





**NOTE:**

Increase the width of the instrument panel finish panel No. 1 and No. 2 retainers by pushing them outward by approximately 2 mm (0.079 in.), and then fit the rollers into the rail grooves.

- D. Tighten the 5 screws on the instrument panel finish panel No. 1 retainer with the specified amount of torque.

**Torque: 0.67 to 0.71 N•m**  
(6.83 to 7.24 kgf•cm,  
0.49 to 0.52 ft•lbf)




**HINT:**

Fit the rollers into the rail grooves as shown in the illustration.

**Repair Procedure**  
(Continued)

7. Install Instrument Panel Finish Panel Upper.
  - A. Install the instrument panel finish panel upper.
  - B. Tighten the 4 screws.
 

**Torque: 0.67 to 0.71 N•m  
(6.83 to 7.24 kgf•cm,  
0.49 to 0.52 ft•lbf)**
  - C. Check to make sure the instrument finish panel center sub-assembly slides smoothly by moving the motor assembly forward and rearward.



**NOTE:**  
Motor assembly must be moved to the end of its travel prior to reassembly in vehicle (panel open position).

8. Install Instrument Panel Upper Bracket No. 2 (2005 model year only).
  - A. Install the instrument panel upper bracket No. 2.
  - B. Tighten the 4 screws.
 

**Torque: 0.67 to 0.71 N•m  
(6.83 to 7.24 kgf•cm,  
0.49 to 0.52 ft•lbf)**
9. Check Operation.
  - A. After assembling the instrument cluster finish panel sub-assembly center with multi-display, visually check the appearance to make sure that the instrument cluster finish panel center is centered.
  - B. Check that instrument cluster finish panel center operates properly.
10. Reinstallation is the Reverse Order of Removal.
11. Function Test Operation of the Navigation Unit.

