

Fix Finder™ Report

Powered by Innova

2008 LEXUS RX

VIN
JTJHW31U582*****

Odometer
198503 mi

Report # 347821345184534260

Store # 3478 December 11, 2021, 1:45 PM



Power Train System



Anti-Lock Brake System



Service Interval Light

MOST LIKELY SOLUTION

Anti-Lock Brake System

Replace Steering Angle Sensor

Suggested Parts: 1

Additional Part Required

DIAGNOSTIC TROUBLE CODES



Anti-Lock Brake System

C1336	Zero point calibration of yaw rate sensor undone
C1345	Not learning linear valve offset abnormality
U0073	Control Module Communication Bus OFF
U0123	Lost Communication with Yaw Rate Sensor Module
U0124	Lost Communication with Lateral Acceleration Sensor Module
U0126	Lost Communication With Steering Angle Sensor Module
U0293	Lost Communication with Hybrid Vehicle Control System

NEXT SCHEDULED MAINTENANCE

At 200,000 mi

▶ Change Engine Oil and Filter

▶ Inspect CV Joints & Boots