

2010 Lexus RX 350

2T2BK1BA6AC067736

Odometer: 205,281 km

0 Confirmed Codes

0 Pending Codes

0 Permanent Codes

1 Smart Start Unit Code

C1241 Low or High Power Supply Voltage

CURRENT /
HISTORY

2 Antilock Brake System Codes

C1201 Check report for description.

CURRENT /
HISTORY

C1241 Low or High Power Supply Voltage

CURRENT /
HISTORY

1 Four Wheel Drive Code

C1241 Low or High Power Supply Voltage

CURRENT /
HISTORY

Disclaimer: This information is provided without warranty and is subject to the Terms of Use posted at www.bluedriver.com/eula.html. Reproduction of this information or any portion thereof constitutes infringement of copyright.

2010 Lexus RX 350

Odometer: 205,281 km

Code Definition

Low or High Power Supply Voltage

Top Reported Fix

- REPLACED BATTERY

1 Frequently Reported Fix

- CLEANED BATTERY TERMINAL

Disclaimer: The Possible Causes outlined above may or may not be the cause of your vehicle trouble code(s) being triggered. The Reported Fixes listed are suggestions only, and a fix is not guaranteed by performing any of the above potential solutions. The trouble code summary data may help you pinpoint the type of repair facility that should be consulted. It is strongly recommended that you consult with a knowledgeable professional repair facility for proper diagnosis and repair of trouble code issues. This information is provided without warranty and is subject to the Terms of Use posted at www.bluedriver.com/eula.html. Reproduction of this information or any portion thereof constitutes infringement of copyright.

2010 Lexus RX 350

Odometer: 205,281 km

Code Definition

Check report for description.

1 Possible Causes

- C1201 indicates that the vehicle has disabled its ABS/VSC system(s) due to a detected fault.

Review and fix any other powertrain and ABS codes and this code will be cleared.

1 Frequently Reported Fix

- SEE OTHER POWERTRAIN AND ABS CODES FOR MORE DETAILS

Disclaimer: The Possible Causes outlined above may or may not be the cause of your vehicle trouble code(s) being triggered. The Reported Fixes listed are suggestions only, and a fix is not guaranteed by performing any of the above potential solutions. The trouble code summary data may help you pinpoint the type of repair facility that should be consulted. It is strongly recommended that you consult with a knowledgeable professional repair facility for proper diagnosis and repair of trouble code issues. This information is provided without warranty and is subject to the Terms of Use posted at www.bluedriver.com/eula.html. Reproduction of this information or any portion thereof constitutes infringement of copyright.

2010 Lexus RX 350

Odometer: 205,281 km

Code Definition

Low or High Power Supply Voltage

Top Reported Fix

- REPLACED BATTERY

1 Frequently Reported Fix

- CLEANED BATTERY TERMINAL

Disclaimer: The Possible Causes outlined above may or may not be the cause of your vehicle trouble code(s) being triggered. The Reported Fixes listed are suggestions only, and a fix is not guaranteed by performing any of the above potential solutions. The trouble code summary data may help you pinpoint the type of repair facility that should be consulted. It is strongly recommended that you consult with a knowledgeable professional repair facility for proper diagnosis and repair of trouble code issues. This information is provided without warranty and is subject to the Terms of Use posted at www.bluedriver.com/eula.html. Reproduction of this information or any portion thereof constitutes infringement of copyright.

2010 Lexus RX 350

Odometer: 205,281 km

Code Definition

Low or High Power Supply Voltage

Top Reported Fix

- REPLACED BATTERY

1 Frequently Reported Fix

- CLEANED BATTERY TERMINAL

Disclaimer: The Possible Causes outlined above may or may not be the cause of your vehicle trouble code(s) being triggered. The Reported Fixes listed are suggestions only, and a fix is not guaranteed by performing any of the above potential solutions. The trouble code summary data may help you pinpoint the type of repair facility that should be consulted. It is strongly recommended that you consult with a knowledgeable professional repair facility for proper diagnosis and repair of trouble code issues. This information is provided without warranty and is subject to the Terms of Use posted at www.bluedriver.com/eula.html. Reproduction of this information or any portion thereof constitutes infringement of copyright.