# WIRING DIAGRAMS

## Fig. 5: TCCS ECU (4.0L), Engine Sensors, EFI Main Rly (Grid 16-19)

1992 Lexus SC 400

For Lextreme

Copyright © 1998 Mitchell Repair Information Company, LLC

Tuesday, January 13, 2004 10:17AM




93G03431

PDF created with pdfFactory trial version www.pdffactory.com