

Last Modified: 7-13-2007		1.7 A
Service Category: Vehicle Interior	Section: Heating/Air Conditioning	
Model Year: 2008	Model: ES350	Doc ID: RM0000026PU00GX
Title: AIR CONDITIONING: AIR CONDITIONING AMPLIFIER: REMOVAL (2008 ES350)		

REMOVAL

1. DISCONNECT CABLE FROM NEGATIVE BATTERY TERMINAL

NOTICE:

Wait for 90 seconds after disconnecting the cable to prevent airbag deployment [INFO](#) .

2. REMOVE FRONT DOOR SCUFF PLATE RH [INFO](#)

3. REMOVE FRONT DOOR OPENING TRIM COVER RH [INFO](#)


4. REMOVE NO. 2 INSTRUMENT PANEL UNDER COVER SUB-ASSEMBLY [INFO](#)

5. REMOVE SIDE INSTRUMENT PANEL RH [INFO](#)

6. REMOVE FRONT PASSENGER SIDE KNEE AIR BAG ASSEMBLY [INFO](#)

7. REMOVE LOWER INSTRUMENT PANEL RH [INFO](#)

8. REMOVE AIR CONDITIONING AMPLIFIER ASSEMBLY



(a) Disconnect the 3 connectors.

(b) Remove the 2 bolts and air conditioning amplifier assembly.

