

Copyright © 2008 AutoZone, Inc. All rights reserved. This document is the property of AutoZone, Inc. and is not to be distributed outside of the company.



Wed Oct 29 13:35:10 2008

# AutoZone #2982

480 SUFFOLK AVE  
BRENTWOOD, NY 11717  
(631)436-7013

DEM Number to Cross:P0430	CATALOG	PART#	PRICE
	WARRANTY	CORE	
TROUBLESHOOTING P0430			0.00
OEM Brand: DOMESTIC			

**Definition**  
Catalyst efficiency low-bank 2

**Explanation**  
The oxygen sensors monitor the catalytic converters ability to store oxygen.

**Probable Causes**

- 1.-Catalytic Converter defective (Failure possibly due to #2, 3, or 4)
- 2.-Engine misfire or running condition
- 3.-Large vacuum leak
- 4.-Engine oil leakage into exhaust-valve guide seals, piston rings

TROUBLESHOOTING P0430	0.00
OEM Brand: OBDII	

The PCM has determined that the catalyst system