



**Technical Service
Information Bulletin**

August 2, 2005

Title:

DSIB
DOME LAMP IMPROVEMENT

Models:

'06 GS 300 & GS 430

BODY
B0006-05

Introduction The rear dome lamp assembly retaining clips for the 2006 model year GS 300 and GS 430 have been improved in order to ensure positive attachment of the lamp to the dome lamp opening in the headliner.

Applicable Vehicles

- 2006 model year **GS 300** and **GS 430** vehicles produced **BEFORE** the Production Change Effective VINs shown below.

**Production
Change
Information**

MODEL	PRODUCTION CHANGE EFFECTIVE VIN
GS 300	JTHBH96SX05009398
GS 300 AWD	JTHCH96S6600049
GS 430	JTHBN96S505003856

**Parts
Information**

PREVIOUS PART NUMBER	CURRENT PART NUMBER	COLOR	PART NAME	QTY
81250-30200-A0	Same	Ivory	Lamp Assembly, Room, No. 2	1
81250-30200-B0	Same	Gray		1

**Warranty
Information**

OP CODE	DESCRIPTION	TIME	OFF	T1	T2
EL5058	R & R Room Lamp Assembly No. 2	0.2	81250-30200-#0	9A	83

Applicable Warranty*:

This repair is covered under the Lexus Comprehensive Warranty. This warranty is in effect for 48 months or 50,000 miles, whichever occurs first, from the vehicle's in-service date.

* Warranty application is limited to correction of a problem based upon a customer's specific complaint.