

**SERVICE HISTORY FOR:** GX**VIN:** JTJBT20X680155427**109224 MILES****DATE:** 11/30/2018**REPAIR#** 0509075**REPORTED BY:** Lexus of Northborough

**SERVICE:** LEXUS MULTI POINT  
INSPECTION  
**DESCRIPTION:** LEXUS MULTI POINT  
INSPECTION ~|~LEXUS MULTI POINT  
INSPECTION ~|~

**SERVICE:** PIPE, EXHAUST - FRONT -  
REPLACE  
**DESCRIPTION:** PIPE, EXHAUST -  
FRONT - REPLACE ~|~ ~|~,CUSTOMER  
DECLINED SERVICE

**SERVICE:** TRANSMISSION  
DIAGNOSIS: CUSTOMER STATES THE  
TRANSMISSION IS SLIPPING  
**DESCRIPTION:** TRANSMISSION  
DIAGNOSIS: CUSTOMER STATES THE  
TRANSMISSION IS SLIPPING  
~|~TRANSMISSION DIAGNOSIS:  
CUSTOMER STATES THE  
TRANSMISSION IS SLIPPING ~|~  
~|~109224 ROAD TESTED CAN FEEL  
TRANSLY SLIPPING, CHECKED FOR  
CODES HAS CODES P0776 SOLENOID B  
PERFORMANCE OR STUCK OFF, P0894  
TRANSMISSION COMPONENT  
SLIPPING, P2714 SOLENOID D  
PERFORMANCE OR STUCK OFF. HAS  
INTERNAL PROBLEMS REC NEW  
TRANSMISSION

**SERVICE:** MANIFOLD, EXHAUST -  
REPLACE  
**DESCRIPTION:** MANIFOLD,  
EXHAUST - REPLACE ~|~  
~|~,CUSTOMER DECLINED SERVICE

**SERVICE:** SHAFT, DRIVE AXLE  
(FRONT) - REPLACE LEAKING  
**DESCRIPTION:** SHAFT, DRIVE AXLE  
(FRONT) - REPLACE LEAKING ~|~  
~|~,CUSTOMER DECLINED SERVICE

**SERVICE:** TRANSMISSION,  
AUTOMATIC - REPLACE  
**DESCRIPTION:** TRANSMISSION,  
AUTOMATIC - REPLACE ~|~  
~|~,CUSTOMER DECLINED SERVICE

**101439 MILES****DATE: 02/24/2018****REPAIR#** 0290407**REPORTED BY:** Lexus of Northborough

**SERVICE:** LEXUS MULTI-POINT INSPECTION  
**DESCRIPTION:** LEXUS MULTI-POINT INSPECTION ~|~LEXUS MULTI-POINT INSPECTION ~|~

**SERVICE:** REPLACE EXHAUST MUFFLER & HARDWARE  
**DESCRIPTION:** REPLACE EXHAUST MUFFLER & HARDWARE ~|~REPLACE EXHAUST MUFFLER & HARDWARE ~|~ ~|~101439 REPLACED MUFFLER AND HARDWARE

**SERVICE:** SEE LINE (D)  
**DESCRIPTION:** SEE LINE (D)  
 ~|~CUSTOMER STATES MUFFLER REQUIRES RELACEMENT, PLEASE CHECK AND ADVISE. ~|~ ~|~101439 PROVIDED ESTIMATE

**SERVICE:** LOANER VEHICLE  
**DESCRIPTION:** LOANER VEHICLE ~|~LEXUS CUSTOMER CARE SERVICES SURCHARGE ~|~

**SERVICE:** REPLACE REAR BRAKE PADS & ROTORS  
**DESCRIPTION:** REPLACE REAR BRAKE PADS & ROTORS ~|~ ~|~CUSTOMER DECLINED SERVICE - CUSTOMER DECLINED

**90537 MILES****DATE: 10/12/2016****REPAIR#** 0260950**REPORTED BY:** Lexus of Northborough

**SERVICE:**  
**DESCRIPTION:** SECONDARY AIR INJECTION PUMP AND VALVES. EXTREMELY RUSTY OTHER PARTS MAY BE REQUIRED ~|~ ~|~CUSTOMER DECLINED SERVICE -A SECONDARY AIR INJECTION PUMP AND VALVES.

**SERVICE:** DIAGNOSIS ONLY  
**DESCRIPTION:** DIAGNOSIS ONLY ~|~CUSTOMER STATES:C/S THE CEL, VSC, TRAC, & VSC OFF LIGHTS ARE ON. CHECK. ~|~ ~|~90537 P1442 SECONDARY AIR INJECTION VALVE

EXTREMELY RUSTY OTHER PARTS  
MAY BE REQUIRED

**SERVICE:** LEXUS CUSTOMER CARE  
SERVICES/FUEL SURCHARGE  
**DESCRIPTION:** LEXUS CUSTOMER  
CARE SERVICES/FUEL SURCHARGE  
~|~LEXUS CUSTOMER CARE  
SERVICES/FUEL SURCHARGE ~|~

STUCK OPEN OR CLOSED. REC NEW  
VALVES AND PUMP

**SERVICE:** LEXUS MULTI POINT  
INSPECTION  
**DESCRIPTION:** LEXUS MULTI POINT  
INSPECTION ~|~LEXUS MULTI POINT  
INSPECTION ~|~

**74680 MILES**

**DATE: 12/22/2014**

**REPAIR#** 0221596

**REPORTED BY:** Lexus of Northborough

**SERVICE:**

**DESCRIPTION:** QUALITY CONTROL  
INSPECTION. SEE REPAIR HISTORY.  
SIGN OFF BY SHOP  
FOREMAN \_\_\_\_\_  
~|~QUALITY CONTROL INSPECTION.  
SEE REPAIR HISTORY. SIGN OFF BY  
SHOP  
FOREMAN \_\_\_\_\_  
DATE \_\_\_\_\_ ~|~ QUALITY  
CONTROL INSPECTION. SEE REPAIR  
HISTORY. SIGN OFF BY SHOP  
FOREMAN \_\_\_\_\_

**SERVICE:** TECHNICIAN NOTES

BELOW

**DESCRIPTION:** TECHNICIAN NOTES  
BELOW ~|~CUSTOMER STATES CHECK  
ENGINE LIGHT WAS REPAIRED HERE  
2 DAYS AGO, LIGHT IS ON AGAIN ~|~  
~|~74680 THE VEHICLE WAS TESTED  
FOR CODES P0138 OXYGEN SENSOR  
CIRCUIT HIGH VOLTAGE BANK 1  
SENSOR 2 PERFORMED AN ACTIVE  
TEST ON A/F SENSOR BANK 1 SENSOR  
1 THE VOLTAGE READING WAS OVER  
4 VOLTS REPLACED BANK 1 SENSOR 1

**SERVICE:** LEXUS CUSTOMER CARE  
SERVICES/FUEL SURCHARGE

**DESCRIPTION:** LEXUS CUSTOMER  
CARE SERVICES/FUEL SURCHARGE  
~|~CUSTOMER REQUESTED A  
LOANER ~|~

**SERVICE:** [OTHER]: A/F SENSOR

BANK 1 SENSOR 1 (115086976)

**DESCRIPTION:** [OTHER]: A/F SENSOR  
BANK 1 SENSOR 1 (115086976) ~|~  
[OTHER]: A/F SENSOR BANK 1 SENSOR  
1 (115086976) ~|~ ~|~74679 1:REPLACED  
BANK 1 SENSOR 1

---

**74633 MILES****DATE: 12/16/2014****REPAIR#** 0221432**REPORTED BY:** Lexus of Northborough**SERVICE:** ?**DESCRIPTION:** ? ~|~CUSTOMERSTATES CHECK ENGINE LIGHT IS ON.  
CHECK AND ADVISE ~|~ ~|~74631  
BANK1 SENSOR 2 OXYGEN SENSOR  
HIGH CIRCUIT VOLTAGE.**SERVICE:** OXYGEN SENSORREPLACEMENT: BANK 1 SENSOR 2  
(114398807)**DESCRIPTION:** OXYGEN SENSORREPLACEMENT: BANK 1 SENSOR 2  
(114398807) ~|~OXYGEN SENSOR  
REPLACEMENT: BANK 1 SENSOR 2  
(114398807) ~|~ ~|~74631 BANK 1  
SENOR 2 HAS HIGH CIRCUIT  
VOLTAGE (P0138) REPLACED AND  
REPLACED FAILED OXYGEN SENSOR.  
CLEARED TROUBLE CODES AND  
EXAMINED THE DATA LIST. ALL  
SENSORS ARE OPERATING AS  
DESIGNED AT THIS TIME.**SERVICE:** LEXUS CUSTOMER CARE  
SERVICES/FUEL SURCHARGE**DESCRIPTION:** LEXUS CUSTOMER  
CARE SERVICES/FUEL SURCHARGE  
~|~CUSTOMER REQUESTED A  
LOANER ~|~**SERVICE:** TIRE PRESSURES SET/OK**DESCRIPTION:** TIRE PRESSURES  
SET/OK ~|~CUSTOMER STATES SET  
TIRE PRESSURE ~|~

---

**58181 MILES****DATE: 06/03/2013****REPAIR#** 0190264**REPORTED BY:** Lexus of Northborough**SERVICE:** ALTERNATOR - REPLACE**DESCRIPTION:** ALTERNATOR -  
REPLACE ~|~ALTERNATOR - REPLACE**SERVICE:** BATTERY - REPLACE  
(VEHICLE BATTERY)**DESCRIPTION:** BATTERY - REPLACE  
(VEHICLE BATTERY) ~|~BATTERY -

~|~ ~|~58180 OUTPUT BELOW SPEC  
REPLACED ALTERNATOR

**SERVICE:** FOUR WHEEL TIRE  
ROTATION WITH VISUAL BRAKE  
INSPECTION  
**DESCRIPTION:** FOUR WHEEL TIRE  
ROTATION WITH VISUAL BRAKE  
INSPECTION ~|~FOUR WHEEL TIRE  
ROTATION WITH VISUAL BRAKE  
INSPECTION ~|~ ~|~58180 ROTATED  
TIRES AT 3-4/32 ON EDGE CENTER 4-  
5/32 - MAY NEED TIRES BY NEXT  
SERVICE INTERVAL DUE TO  
EDGEWEAR. NOTE: FRONT AND REAR  
BRAKES WORN 2-3MM - WILL NEED  
REPLACEMENT BY NEXT SERVICE.

**SERVICE:** REFER TO LINES B AND C  
FOR REPAIRS

**DESCRIPTION:** REFER TO LINES B  
AND C FOR REPAIRS ~|~CUSTOMER  
STATES THE BATTERY LIGHT IS  
SHOWING ON THE INSTRUMENT  
CLUSTER. CHECK AND ADVISE. ~|~  
~|~58179 FOUND ALTERNATOR  
OUTPUT BELOW SPEC REPLACED  
BATTERY AND ALTERNATOR

REPLACE (VEHICLE BATTERY) ~|~  
~|~58179 FAIL CODE COPP REPLACED  
BATTERY

**SERVICE:** LEXUS CUSTOMER CARE  
SERVICES/FUEL SURCHARGE  
**DESCRIPTION:** LEXUS CUSTOMER  
CARE SERVICES/FUEL SURCHARGE  
~|~LEXUS CUSTOMER CARE  
SERVICES/FUEL SURCHARGE

---

**54373 MILES**

**DATE:** 01/29/2013

**REPAIR#** 0183437

**REPORTED BY:** Lexus of Northborough

**SERVICE:** LEXUS CUSTOMER CARE  
SERVICES/FUEL SURCHARGE  
**DESCRIPTION:** LEXUS CUSTOMER  
CARE SERVICES/FUEL SURCHARGE  
~|~LEXUS CUSTOMER CARE  
SERVICES/FUEL SURCHARGE

**SERVICE:** SEE NOTES  
**DESCRIPTION:** SEE NOTES  
~|~CUSTOMER STATES AUTO BAHN  
ON HOOD ~|~ ~|~54373 AUTO BAHN  
REPLACED HOOD ONLY

---

**51316 MILES**
**DATE: 11/01/2012****REPAIR#** 0178596**REPORTED BY:** Lexus of Northborough**SERVICE:** LEXUS VEHICLE

INSPECTION

**DESCRIPTION:** LEXUS VEHICLE

INSPECTION ~|~LEXUS VEHICLE

INSPECTION

**SERVICE:** SEE TECHNICIAN NOTES

BELOW

**DESCRIPTION:** SEE TECHNICIAN

NOTES BELOW ~|~CUSTOMER STATES:

THERE IS A HUMMING NOISE AT IDLE

PLEASE CHECK AND ADVISE ~|~

~|~51316 INSPECTED VEHICLE WITH

SHOP FORMAN AND HEARD NOISE

COMING FROM BOTH THE POWER

STEERING PUMP AND THE

ALTERNATOR AS WELL. COMPARED

TO OTHER GX AND THIS CUSTOMERS

SEEMS MUCH LOUDER, BOTH ALT

AND PUMP. SUPPLIED QUOTE FOR

BOTH PARTS AND RECOMMEND

CUSTOME

---

**40984 MILES**
**DATE: 11/10/2011****REPAIR#** 0157491**REPORTED BY:** Lexus of Northborough**SERVICE:** CUSTOMER STATES**DESCRIPTION:** CUSTOMER STATES

~|~CUSTOMER STATES:CUSTOMER

STATED THAR CLADDING KEEPS

POPPING OFF DRIVERS SIDE ~|~(NO

CHARGE ) ~|~40984 WESTBORO GMC

BUICK A/B INSTALLED NEW CLIPS ON

DOOR CLADDING

**SERVICE:** LEXUS CUSTOMER CARE

SERVICES/FUEL SURCHARGE

**DESCRIPTION:** LEXUS CUSTOMER

CARE SERVICES/FUEL SURCHARGE

~|~LEXUS CUSTOMER CARE

SERVICES/FUEL SURCHARGE

**SERVICE:** LEXUS QUALITY VEHICLE

INSPECTION

**DESCRIPTION:** LEXUS QUALITY  
VEHICLE INSPECTION ~|~LEXUS  
QUALITY VEHICLE INSPECTION

**40762 MILES**

**DATE:** 11/01/2011

**REPAIR#** 0156978

**REPORTED BY:** Lexus of Northborough

**SERVICE:** COMPLETED

**DESCRIPTION:** COMPLETED

~|~CUSTOMER STATES: CUSTOMER STATES REMOVE STAINS FROM DRIVER SIDE REAR CARPET, PASSENGER SIDE FRONT CARPET AND DRIVER SIDE REAR FOLDING SEAT. CUSTOMER HAS A STAIN PROTECTION MAINTENANCE CONTRACT. ~|~ ~|~40761 ADVISED CUSTOMER STAINS CAN NOT BE REMOVED. CUSTOMER WILL NEED TO PROCESS CLAIM WITH RESIST ALL. COMPLETED ~|~CUSTOMER REQUESTED A LOANER COMPLETED ~|~CUSTOMER STATES CLIPS KEEP FALLING OFF WHEN CLOSING DOOR BAG OF CLIPS IN CAR COMING FROM DRIVER SIDE REAR DOOR CHECK AND ADVISE. ~|~ ~|~40761 MISSING CLIPS ON STEP PANEL ON DRIVERS SIDE CLEANED STEP PANEL AND REPLACED CLIPS SUPPLIED BY CUSTOMER...CLIPS WHERE MISSING ON BOTH SIDES REPLACED ALL BUT ONE, SHORT ONE... ADVISED CUSTOMER CLIPS MAY NEED TO BE REPLACE IF IT BECOMES LOOSE AGAIN AS

**SERVICE:** STATE INSPECTION

**DESCRIPTION:** STATE INSPECTION

~|~STATE INSPECTION ~|~ ~|~40761  
MASS. INSPECTION STICKER

**40433 MILES**

**DATE:** 10/24/2011

**REPAIR#** 0156374**REPORTED BY:** Lexus of Northborough**SERVICE:** CUSTOMER WILL

RESCHEDULE.

**DESCRIPTION:** CUSTOMER WILL RESCHEDULE. ~|~CUSTOMER STATES REMOVE STAINS FROM PASSENGER SIDE FRONT CARPET, DRIVER SIDE REAR CARPET, REMOVE STAIN FROM DRIVER SIDE REAR FOLDING SEAT.**SERVICE:** OTHERS R&R\***DESCRIPTION:** OTHERS R&R\*

~|~CUSTOMER STATES CHECK FOR RATTLE NOISE WHEN STARTING VEHICLE SEEMS TO BE COMING FROM UNDERNEATH CAR. ~|~HEAT SHIELD DEFORMED ~|~40432 FOUND REAR MUFFLER HAD FALLEN OUT OF THE HANGER AND HEATSHIELD ON TOP OF EXHAUST HAD ROTTED OUT. REINSTALLED MUFFLER INTO HANGER AND RESECURED HEATSHIELD FOR EXHAUST. RATTLE IS NO LONGER THERE

**SERVICE:** PROVIDED ESTIMATE FOR REPAIR.**DESCRIPTION:** PROVIDED ESTIMATE FOR REPAIR. ~|~CUSTOMER STATES CHECK DRIVER SIDE FRONT AND REAR DOOR MOULDINGS LOOSE AND CLIPS ARE FALLING OFF. ~|~ ~|~40432 FOUND IMPACT DAMAGE TO MOULDINGS, WILL NEED NEW CLIPS AND MOULDING WILL NEED TO BE RESECURE. ESTIMATE FOR REPAIR \$271.85**SERVICE:** WILL NEED NEW CLIPS**DESCRIPTION:** WILL NEED NEW CLIPS ~|~CUSTOMER STATES CHECK DRIVER SIDE RUNNING BOARD LOOSE. ~|~ ~|~40432 DRIVER SIDE AND PASSENGER SIDE RUNNING BOARD CLIPS ARE MISSING AND BROKEN \$41.85

---

**24405 MILES****DATE:** 05/05/2010**REPAIR#** 0124312**REPORTED BY:** Lexus of Northborough**SERVICE:** 25,000 MILES OR 30 MONTHS MINIMUM SERVICE REQUIREMENTS



**DESCRIPTION:** 25,000 MILES OR 30  
MONTHS MINIMUM SERVICE  
REQUIREMENTS ~|~25,000 MILES OR 30  
MONTHS MINIMUM SERVICE  
REQUIREMENTS ~|~ ~|~24405  
CHANGE OIL AND FILTER ROTATED  
TIRES SET ALL TIRE PRESSURES  
INCLUDING SPARE TIRES ALL  
7/32NDS FRONT BRAKES 8MM REAR  
BRAKES 7MM CHECKED BATTERY  
AND CHARGING SYSTEM (PASSED)

**20061 MILES**

**DATE:** 11/27/2009

**REPAIR#** 0114112

**REPORTED BY:** Lexus of Northborough

**SERVICE:** LEXUS CUSTOMER CARE  
SERVICES/FUEL SURCHARGE  
**DESCRIPTION:** LEXUS CUSTOMER  
CARE SERVICES/FUEL SURCHARGE  
~|~LEXUS CUSTOMER CARE  
SERVICES/FUEL SURCHARGE

**SERVICE:** REMOTE STARTER SPECIAL  
**DESCRIPTION:** REMOTE STARTER  
SPECIAL ~|~INSTALL NEW REMOTE  
START NO LCD

**19345 MILES**

**DATE:** 11/02/2009

**REPAIR#** 0112868

**REPORTED BY:** Lexus of Northborough

**SERVICE:** 20,000 MILES OR 24  
MONTHS MINIMUM SERVICE  
REQUIREMENTS  
**DESCRIPTION:** 20,000 MILES OR 24  
MONTHS MINIMUM SERVICE  
REQUIREMENTS ~|~20,000 MILES OR 24  
MONTHS MINIMUM SERVICE  
REQUIREMENTS ~|~ ~|~19345  
PERFORMED 20,000 MILE SERVICE

**SERVICE:** STATE INSPECTION  
**DESCRIPTION:** STATE INSPECTION  
~|~STATE INSPECTION ~|~ ~|~19345  
STATE INSPECTION

BRAKES F=7MM R=7MM TIRES  
 ALL=9/32 CHANGE OIL AND FILTER  
 ROTATED TIRES SET ALL TIRE  
 PRESSURES CHECKED BATTERY AND  
 CHARGING SYSTEM (PASSED)  
 CHECKED ANTI FREEZE CHECKED  
 BELTS AND HOSES

**18739 MILES**

**DATE: 10/20/2009**

**REPAIR#** 0112009

**REPORTED BY:** Lexus of Northborough

**SERVICE:** CUSTOMER STATES:HAD  
 ELECTRIC STARTER REPLACED AND  
 NOW WH EN USING THE BUTTON  
 THE

**DESCRIPTION:** CUSTOMER  
 STATES:HAD ELECTRIC STARTER  
 REPLACED AND NOW WH EN USING  
 THE BUTTON THE ~|~CUSTOMER  
 STATES:HAD ELECTRIC STARTER  
 REPLACED AND NOW WH EN USING  
 THE BUTTON THE LIGHTS GO ON  
 AND IT SOUND LIKE I TS GOING TO  
 TURN OVER BUT IT DOESNT START.

**17645 MILES**

**DATE: 09/25/2009**

**REPAIR#** 0109927

**REPORTED BY:** Lexus of Northborough

**SERVICE:** CUSTOMER REQUESTED A  
 LOANER

**DESCRIPTION:** CUSTOMER  
 REQUESTED A LOANER  
 ~|~CUSTOMER REQUESTED A  
 LOANER

**SERVICE:** CUSTOMER STATES:SHE  
 SAID THAT SHE HAD A STARTED PUT  
 IN A ND IT IS NOT WORKING.

**DESCRIPTION:** CUSTOMER  
 STATES:SHE SAID THAT SHE HAD A  
 STARTED PUT IN A ND IT IS NOT  
 WORKING. ~|~CUSTOMER

STATES:SHE SAID THAT SHE HAD A  
STARTED PUT IN A ND IT IS NOT  
WORKING. ~|~E

**14100 MILES**

**DATE: 05/09/2009**

**REPAIR#** 0102313

**REPORTED BY:** Lexus of Northborough

**SERVICE:** 15,000 MILES OR 18

MONTHS MINIMUM SERVICE  
REQUIREMENTS

**DESCRIPTION:** 15,000 MILES OR 18  
MONTHS MINIMUM SERVICE  
REQUIREMENTS ~|~15,000 MILES OR 18  
MONTHS MINIMUM SERVICE

REQUIREMENTS ~|~ ~|~14100 15K  
SERVICE TECH PERFORMED 15K  
SERVICE.REPLACED CABIN AIR  
FILTER. REPLACED OIL AND FILTER.  
TOPPED FLUIDS OFF. RESET TIRE  
PRESSURES. BATTERY TEST GOOD.  
COOLANT GOOD. AIR FILTER CAN  
WAIT TIL NEXT SERVICE.

**SERVICE:** REPLACED CABIN AIR  
FILTER

**DESCRIPTION:** REPLACED CABIN  
AIR FILTER ~|~REPLACED CABIN AIR  
FILTER ~|~ ~|~14100 REPLACE CABIN  
AIR FILTER TECH REPLACED CABIN  
AIR FILTER

**SERVICE:** COMPLETED

**DESCRIPTION:** COMPLETED

~|~CUSTOMER  
STATES:MAINTENANCE LIGHT IS ON  
~|~ ~|~14100 MAINTENANCE LIGHT IS  
ON TECH RESET MAINT LIGHT

**8984 MILES**

**DATE: 11/18/2008**

**REPAIR#** 0093249

**REPORTED BY:** Lexus of Northborough

**SERVICE:** 10,000 MILES OR 12 MONTHS MINIMUM SERVICE REQUIREMENTS  
**DESCRIPTION:** 10,000 MILES OR 12 MONTHS MINIMUM SERVICE REQUIREMENTS ~|~10,000 MILES OR 12 MONTHS MINIMUM SERVICE REQUIREMENTS ~|~|~8984 PERFORMED 10K MILE SERVICE.

**SERVICE:** LEXUS CUSTOMER CARE SERVICES/FUEL SURCHARGE  
**DESCRIPTION:** LEXUS CUSTOMER CARE SERVICES/FUEL SURCHARGE ~|~LEXUS CUSTOMER CARE SERVICES/FUEL SURCHARGE

**SERVICE:** REMOTE STARTER SPECIAL  
**DESCRIPTION:** REMOTE STARTER SPECIAL ~|~REMOTE STARTER SPECIAL

**SERVICE:** STATE INSPECTION  
**DESCRIPTION:** STATE INSPECTION ~|~STATE INSPECTION ~|~|~8984 PASSED.

**5280 MILES**

**DATE:** 07/16/2008

**REPAIR#** 0086297

**REPORTED BY:** Lexus of Northborough

**SERVICE:** 5,000 MILE SERVICE  
**DESCRIPTION:** 5,000 MILE SERVICE ~|~5,000 MILE SERVICE ~|~5 K ~|~5280 5K SERVICE PERFORMED A 5,000 MILE SERVICE. REAR HEADLINER VENMTS ARE FOR A/C ONLY, REAR FLOOR VENTS ARE FORE HEAT,

**2817 MILES**

**DATE:** 04/09/2008

**REPAIR#** 0081073

**REPORTED BY:** Lexus of Northborough

**SERVICE:** COMPLETED  
**DESCRIPTION:** COMPLETED ~|~INSTALL TOW HITCH, CHARGING

**SERVICE:** LEXUS CUSTOMER CARE SERVICES/FUEL SURCHARGE

HALF TO SALES DEPARTMENT ~|~  
 ~|~2817 SALES PAYING FOR 1/2 PARTS  
 AND INSTALLATION PER MATT  
 PETICE. 4/9 INSTALL TOW HITCH

**DESCRIPTION:** LEXUS CUSTOMER  
 CARE SERVICES/FUEL SURCHARGE  
 ~|~LEXUS CUSTOMER CARE  
 SERVICES/FUEL SURCHARGE

**1140 MILES**

**DATE:** 01/30/2008

**REPAIR#** 0077705

**REPORTED BY:** Lexus of Northborough

**SERVICE:** 1,000 MILE SERVICE

**DESCRIPTION:** 1,000 MILE SERVICE

~|~1,000 MILE SERVICE ~|~1K SERVICE

~|~1140 PERFORMED 1K SERVICE.

**13 MILES**

**DATE:** 01/22/2008

**REPAIR#** 0077271

**REPORTED BY:** Lexus of Northborough

**SERVICE:** RETAIL ACCESSORIES

**DESCRIPTION:** RETAIL

ACCESSORIES ~|~AUTOBAHN

**12 MILES**

**DATE:** 12/26/2007

**REPAIR#** 0075944

**REPORTED BY:** Lexus of Northborough

**SERVICE:** STATE INSPECTION

**DESCRIPTION:** STATE INSPECTION

~|~STATE INSPECTION

**11 MILES****DATE: 12/18/2007****REPAIR#** 0075344**REPORTED BY:** Lexus of Northborough**SERVICE:** PRE-DELIVERY SERVICE

FOR USA ALL ALTITUDES

**DESCRIPTION:** PRE-DELIVERY

SERVICE FOR USA ALL ALTITUDES

~|~PRE-DELIVERY SERVICE FOR USA

ALL ALTITUDES ~|~PDS ~|~11

REQUEST BY NEW CAR DEPT. PDS

COMPLETED.

---

## TERMS AND CONDITIONS

---

### INFORMATION ACCURACY

Information presented on this website is summarized and standardized from repair orders completed at the time of service and submitted by Lexus dealers. When reviewing a vehicle's service history, please note that all information is provided by the Lexus Dealer that conducted the service, and that dealer is solely responsible for the accuracy, completeness or authenticity of any information contained in this site. Lexus provides this site and all information and materials contained herein ?as is? without warranty of any kind. Any questions or concerns regarding this information should be addressed to the applicable Lexus dealer.

### L/CERTIFIED OWNER INFORMATION

Dealer-reported service history records are linked to a vehicle's Vehicle Identification Number (VIN). All owner-reported service history records will be made available to the person who input the information on the site, but will not be shared with future owners of the vehicle.

### OWNER-REPORTED INFORMATION AND PRIVACY TERMS

Lexus makes every effort to ensure the secure collection and transmission of sensitive user information using industry-accepted data collection and encryption methodologies. The information you provide is used by Lexus and its vendors and dealers to help improve the services we render. It is occasionally provided to Lexus dealers for their marketing use. Lexus will never sell your personally identifiable information to any other company. To learn more about our privacy policies and practices with respect to this website, please [click here](http://www.lexus.com/privacy/online-statement) (<http://www.lexus.com/privacy/online-statement>).