

TEXAS AUTO GLASS
15957 KUYKENDAHL ROAD
Houston, TX 77068

Customer Copy

PH:(281) 943-0698 FAX:(281) 943-0710

P/O#:	Cust State Tax ID:	Quote: Q001249
Taken By:	Cust Fed Tax ID:	
Installer:	Ship Via:	
SalesRep:	Adv. Code:	Date: 8/28/2019 Time: 05:03 PM

*DEM Quote
Windshield*

Vehicle Information

Make: Lexus		Model Style: GX 460 4 Door Utility	Year: 2013		
Odometer:		VIN:	License:		
Qty	Part Number	Description	List	Sell	Total
1	56101-60810	Windshield-(Electrochromic Mirror,Rain Sensor,Heated Wiper Park,3rd Visor Frit,LDWS,Solar)	\$960.76	\$960.76	\$960.76
1	25H	Hourly Labor (4.7 Hours)	\$125.00	\$125.00	\$125.00
1	HAH000004	Adhesive-(2.0,Urethane,Dam,Primer)	\$25.00	\$25.00	\$25.00
10	75545-53011	Clip(S)	\$6.57	\$6.57	\$65.70
1	MISC	Recalibration	\$584.50	\$584.50	\$584.50

Thank You for your business

May require specialized equipment; refer to Manufacturer's Service Manual for specific procedures. Labor time does not include calibration or programming. Coordinate any required calibration or programming as needed with the vehicle owner.

Total:

Sub Total: \$1,760.96

Tax: \$134.97

Total: \$1,895.93

TEXAS AUTO GLASS
 15957 KUYKENDAHL ROAD
 Houston, TX 77068

Customer Copy

PH:(281) 943-0698 FAX:(281) 943-0710

P/O#:	Cust State Tax ID:	Quote: Q001249
Taken By:	Cust Fed Tax ID:	
Installer:	Ship Via:	
SalesRep:	Adv. Code:	Date: 8/28/2019 Time: 05:05 PM

*After market
 Pilkington Glass Quote*

Vehicle Information

Qty	Part Number	Description	List	Sell	Total
	Make: Lexus Odometer:	Model Style: GX 460 4 Door Utility VIN:		Year: 2013 License:	
1	25H	Hourly Labor (4.7 Hours)	\$125.00	\$125.00	\$125.00
1	HAH000004	Adhesive-(2.0,Urethane,Dam,Primer)	\$25.00	\$25.00	\$25.00
10	75545-53011	Clip(S)	\$6.57	\$6.57	\$65.70
1	MISC	Recalibration	\$584.50	\$584.50	\$584.50
1	FW03229GGYNCOM	Windshield-(Electrochromic Mirror,Rain Sensor,Heated Wiper Park,3rd Visor Frit,LDWS,Solar)	*\$450.00	\$450.00	\$450.00

** Indicates User Altered List Price

May require specialized equipment; refer to Manufacturer's Service Manual for specific procedures. Labor time does not include calibration or programming. Coordinate any required calibration or programming as needed with the vehicle owner.

Thank You for your business

Total:

Sub Total: \$1,250.20

Tax: \$92.83

Total: \$1,343.03