

SERVICE HISTORY FOR: 2010 GX460

VIN: JTJJM7FX5A5002267

234858 MILES

DATE: 10/03/2019

REPAIR# 0569711

REPORTED BY: Stevinson Lexus of Lakewood

SERVICE:

DESCRIPTION: STEVINSON LEXUS WILL PROVIDE A COURTESY RENTAL VEHICLE FOR VIRTUALLY ANY SERVICE VISIT. IN AN EFFORT TO OFFSET FUEL COSTS, A \$9.75 FEE WILL BE ADDED TO THIS INVOICE FOR THE PERIOD THE RENTAL IS USED. ~|~ ~|~234858 STEVINSON LEXUS WILL PROVIDE A COURTESY RENTAL VEHICLE FOR VIRTUALLY ANY SERVICE VISIT. IN AN EFFORT

SERVICE: NO MAINTENANCE INTERVAL DUE AT THIS TIME
DESCRIPTION: NO MAINTENANCE INTERVAL DUE AT THIS TIME ~|~*NO INTERVAL DUE VEHICLE HISTORY INDICATES NO MAINTENANCE INTERVAL DUE *CHECK INSTALLATION OF DRIVER'S FLOOR MAT *COURTESY CAR WASH VACUUM ~|~

SERVICE: MULTI-POINT INSPECTION

DESCRIPTION: MULTI-POINT INSPECTION ~|~*LEXUS MULTI-POINT INSPECTION ~|~

SERVICE: REPLACED AIR INJ. MOTOR
DESCRIPTION: REPLACED AIR INJ. MOTOR ~|~CUSTOMER STATES THE CHECK ENGINE . VSC , ALL WHEEL DRIVE , TRAC OFF LIGHTS ARE ON . VEHICLE WILL NOT SPEED UP OVER 65MPH ~|~ ~|~234851 P2445 AIR INJECTION MOTOR IS SIEZED AND WILL NOT TURN 100 REPLACED AIR INJECTION MOTOR

233136 MILES

DATE: 08/24/2019

REPAIR# 0566401

REPORTED BY: Stevinson Lexus of Lakewood

SERVICE: BATTERY FAILED LOAD

TESTING - REPLACE BATTERY

DESCRIPTION: BATTERY FAILED

LOAD TESTING - REPLACE BATTERY

~|~CUST STATES CK ENGINE LIGHT IS ON. STATES CAR MAY BE SLUGGISH TO ACCELERATE. PERF DIAG ND ADV . SEE HIST T832 ~|~ ~|~233136 60 REPLACE BATTERY

SERVICE: MULTI-POINT INSPECTION

DESCRIPTION: MULTI-POINT

INSPECTION ~|~*LEXUS MULTI-POINT INSPECTION ~|~

SERVICE: LOANER

DESCRIPTION: LOANER

~|~STEVINSON LEXUS WILL PROVIDE A COURTESY RENTAL VEHICLE FOR VIRTUALLY ANY SERVICE VISIT. IN AN EFFORT TO OFFSET FUEL COSTS, A \$9.75 FEE WILL BE ADDED TO THIS INVOICE FOR THE PERIOD THE RENTAL IS USED. ~|~ ~|~233136

SERVICE: NO MAINTENANCE

INTERVAL DUE AT THIS TIME

DESCRIPTION: NO MAINTENANCE

INTERVAL DUE AT THIS TIME ~|~*NO

INTERVAL DUEVEHICLE HISTORY

INDICATESNO MAINTENANCE

INTERVAL DUE *CHECK INSTALLATION

OF DRIVER'S FLOOR MAT *COURTESY

CAR WASH VACUUM ~|~

232201 MILES

DATE: 07/31/2019

REPAIR# 0563943

REPORTED BY: Stevinson Lexus of Lakewood

SERVICE:

DESCRIPTION: STEVINSON LEXUS

WILL PROVIDE A COURTESY RENTAL VEHICLE FOR VIRTUALLY ANY SERVICE VISIT. IN AN EFFO

~|~STEVINSON LEXUS WILL PROVIDE A COURTESY RENTAL VEHICLE FOR VIRTUALLY ANY SERVICE VISIT. IN AN EFFORT TO OFFSET FUEL COSTS, A \$9.75 FEE WILL BE ADDED TO THIS INVOICE FOR THE PERIOD THE RENTAL

SERVICE: FULL SYNTHETIC OIL AND FILTER CHANGE

DESCRIPTION: FULL SYNTHETIC OIL

AND FILTER CHANGE ~|~*LOF SILVER PACKAGE *CHANGE ENGINE OIL

FILTER 0W-20 FULL SYNTHETIC OIL

RESET SERVICE INTERVAL INDICATOR

*CHECK INSTALLATION OF DRIVER'S

FLOOR MAT *COURTESY CAR WASH

VACUUM ~|~ ~|~232190 30 CHANGE

ENGINE OIL AND OIL FILTER. FILL

IS USED. ~|~STEVINSON LEXUS WILL PROVIDE A COURTESY RENTAL VEHICLE FOR VIRTUALLY ANY SERVICE VISIT. IN AN EFFO

SERVICE: MULTI-POINT INSPECTION

DESCRIPTION: MULTI-POINT INSPECTION ~|~*LEXUS MULTI-POINT INSPECTION ~|~

SPECIFIED ENGINE OIL. SET TIRE PRESSURE, FILL WASHER FLUID, BRIEF VISUAL UNDER-HOOD INSPECTION. RESET OIL MAINT LAMP IF APPLICABLE.

SERVICE: OTHER INSPECTION

DESCRIPTION: OTHER INSPECTION ~|~HAD JLG RECALL DONE RECENTLY NOW GETTING ERROR MSG SECONDARY AIR INJECTION SYSTEM CONTROL A CIRCUIT - CODES PULLED FROM AUTO ZONE. CODE P0418 ~|~ ~|~232201 DIAG - NO CK ENGINE LIGHTS ON AT THIS TIME - ONLY HAD CODE IN HISTORY - CK AIR CK VALVES ALL OPERATING OK AT THIS TIME - TEST DRIVE SEVERAL TIMES - OK CODE DID NOT RE OCCUROTHOR INSPECTION ~|~GUEST WOULD LIKE US TO CHECK THE FUNCTIONALITY OF PARKING SENSORS ~|~ ~|~232201 WORKING PROPERLY AT THIS TIME

229118 MILES

DATE: 06/04/2019

REPAIR# 0558671

REPORTED BY: Stevinson Lexus of Lakewood

SERVICE:

DESCRIPTION: STEVINSON LEXUS WILL PROVIDE A COURTESY RENTAL VEHICLE FOR VIRTUALLY ANY SERVICE VISIT. IN AN EFFO ~|~STEVINSON LEXUS WILL PROVIDE A COURTESY RENTAL VEHICLE FOR VIRTUALLY ANY SERVICE VISIT. IN AN EFFORT TO OFFSET FUEL COSTS, A \$9.75 FEE WILL BE ADDED TO THIS INVOICE FOR THE PERIOD THE RENTAL IS USED. ~|~STEVINSON LEXUS WILL PROVIDE A COURTESY RENTAL

SERVICE: GUEST DECLINED

RECOMMENDED MAINTENANCE AT THIS TIME.

DESCRIPTION: GUEST DECLINED RECOMMENDED MAINTENANCE AT THIS TIME. ~|~*DEFERRED MAINTENANCE INTERVAL CUSTOMER HAS BEEN INFORMED THAT A MAINTENANCE INTERVAL IS NOW DUE *CHECK INSTALLATION OF DRIVER'S FLOOR MAT *COURTESY CAR WASH VACUUM ~|~

VEHICLE FOR VIRTUALLY ANY
SERVICE VISIT. IN AN EFFO

SERVICE: JLG - INSTALL THE AIR PUMP
REPAIR KIT AND REPLACE THE AIR

DESCRIPTION: JLG - INSTALL THE AIR
PUMP REPAIR KIT AND REPLACE THE
AIR ~|~SPECIAL SERVICE CAMPAIGN -
JLG CERTAIN 2010 MODEL YEAR LEXUS
GX460 AIR INJECTION PUMPS AND AIR
SWITCHING VALVES. ~|~JLG CAMPAIGN
~|~229118 JLG001 240 PERF JLG CAMP

SERVICE: OTHER INSPECTION

DESCRIPTION: OTHER INSPECTION
~|~GUEST STATES VEHICLE HAS NO
POWER IN THE ENGINE WHEN TRYING
TO ACCELERATE, VEHICLE WAS IN FOR
SAME ISSUE A YEAR AGO CHECK AND
ADVISE CODE WAS CLEARED AND
CODE WAS A P0445 EVAP CODE ~|~
~|~229118 TEST DRIVE VEH OPERATING
AS DESIGNED - CK CODES - OK - NEED
MORE INFO FROM CUST

SERVICE: MULTI-POINT INSPECTION

DESCRIPTION: MULTI-POINT
INSPECTION ~|~*LEXUS MULTI-POINT
INSPECTION ~|~

227459 MILES

DATE: 04/13/2019

REPAIR# 0555594

REPORTED BY: Stevinson Lexus of Lakewood

SERVICE:

DESCRIPTION: STEVINSON LEXUS
WILL PROVIDE A COURTESY RENTAL
VEHICLE FOR VIRTUALLY ANY
SERVICE VISIT. IN AN EFFO
~|~STEVINSON LEXUS WILL PROVIDE A
COURTESY RENTAL VEHICLE FOR
VIRTUALLY ANY SERVICE VISIT. IN AN
EFFORT TO OFFSET FUEL COSTS, A
\$9.75 FEE WILL BE ADDED TO THIS
INVOICE FOR THE PERIOD THE RENTAL
IS USED. ~|~STEVINSON LEXUS WILL

SERVICE: GUEST DECLINED

RECOMMENDED MAINTENANCE AT
THIS TIME.

DESCRIPTION: GUEST DECLINED
RECOMMENDED MAINTENANCE AT
THIS TIME. ~|~*DEFERRED
MAINTENANCE INTERVAL CUSTOMER
HAS BEEN INFORMED THAT A
MAINTENANCE INTERVAL IS NOW DUE
*CHECK INSTALLATION OF DRIVER'S
FLOOR MAT *COURTESY CAR WASH
VACUUM ~|~

PROVIDE A COURTESY RENTAL
VEHICLE FOR VIRTUALLY ANY
SERVICE VISIT. IN AN EFFO

SERVICE: HLA-REPL PANEL AIRBAG
MODULE-IS250/350/F

DESCRIPTION: HLA-REPL PANEL
AIRBAG MODULE-IS250/350/F
~|~MANUFACTURER SAFETY RECALL
ISSUED NHTSA #19V005 RECALL #HLA
SAFETY RECALL HLA - REMEDY
NOTICE MULTIPLE MODELS AND
MODEL YEARS TAKATA FRONT
PASSENGER AIRBAG INFLATOR ZONE C
STATUS: REMEDY AVAILABLE ~|~HLA
RECALL ~|~227459 BDC23X 360
PERFORMED HLA RECALL.
AUTHORIZATION #30B14470.

SERVICE: TECH COULD NOT
DUPLICATE CONCERN AT THIS TIME

DESCRIPTION: TECH COULD NOT
DUPLICATE CONCERN AT THIS TIME
~|~CUST STATES THE SEAT BELT
SENSOR GOES OFF WHEN NO ONE IS
SITTING IN THE FRONT PASS SEAT,
CHECK AND ADVISE ~|~ ~|~227459
OCCUPANT DETECTION WORKING
PROPERLY AT THIS TIME NO CODES
STORED.

SERVICE: MULTI-POINT INSPECTION

DESCRIPTION: MULTI-POINT
INSPECTION ~|~*LEXUS MULTI-POINT
INSPECTION ~|~

SERVICE: TECH REMOVED SEAT AND
INSTALLED ROD

DESCRIPTION: TECH REMOVED SEAT
AND INSTALLED ROD ~|~CUST STATES
THAT THE FRONT PASS SEAT
MECHANICAL DEVICE DOES NOT
WORK TO RECLINE THE SEAT, CHECK
AND ADVISE ~|~ ~|~227459 200
PERFORMED INSPECTION AND FOUND
ROD SLID OUT OF POSITION THAT
CONNECTS SEAT BACK AND BOTTOM,
REMOVED SEAT AND INSTALLED ROD...
PROPER OPERATION AFTER.

206913 MILES

DATE: 04/30/2018

REPAIR# 0526843

REPORTED BY: Stevinson Lexus of Lakewood

SERVICE: GUEST DECLINED
RECOMMENDED MAINTENANCE AT
THIS TIME.

SERVICE: MULTI-POINT INSPECTION

DESCRIPTION: MULTI-POINT
INSPECTION ~|~MULTI-POINT
INSPECTION ~|~

DESCRIPTION: GUEST DECLINED
RECOMMENDED MAINTENANCE AT
THIS TIME. ~|~GUEST DECLINED
RECOMMENDED MAINTENANCE AT
THIS TIME. ~|~

SERVICE: REPLAVED RIGHT REAR
WHEEL SPEED SENSOR AND HARNESS

DESCRIPTION: REPLAVED RIGHT
REAR WHEEL SPEED SENSOR AND
HARNESS ~|~VEHICLE TOWED IN,
TURNED OFF WHILE DRIVING - NO
START - CHECK AND ADVISE ~|~
~|~206913 250 CK CODES- NEEDS RIGHT
REAR WHEEL SPEED SENSOR AND
HARNESS - REPLACE HARNESS AND
SENSOR -

206815 MILES

DATE: 04/20/2018

REPAIR# 0525871

REPORTED BY: Stevinson Lexus of Lakewood

SERVICE:

DESCRIPTION: SPEED SENSOR CODE
IN HISTORY NOT PRESENT AFTER
RESET AND TEST DROVE VEHICLE AND
CODES DID NOT RETU ~|~GUEST
STATES WHEN IT IS COLD OUT, THE
CEL, 4WD, AND BATTERY IIGHT COME
ON AND THE VEHICLE GOING INTO
LIMP MODE CHECK AND ADVISE ~|~
~|~206815 100 CK FOR CODES - - RIGHT
REAR WHEEL SPEED SENSOR CODE IN
HISTORY- NO LIGHTS ON AT THIS TIME-
TEST DRIVE FOR SEVERAL DAYS LIGHT
DID NOT COME BACK ON - CUST
DECLINED POS TERMINAL- CK SPEED
SENSORS AND WIRING HARNESS -OK -
NO VISIBLE DAMAGE- RECC CUSPEED
SENSOR CODE IN HISTORY NOT
PRESENT AFTER RESET AND TEST

SERVICE: GUEST DECLINED

RECOMMENDED MAINTENANCE AT
THIS TIME.
DESCRIPTION: GUEST DECLINED
RECOMMENDED MAINTENANCE AT
THIS TIME. ~|~*DEFERRED
MAINTENANCE INTERVAL CUSTOMER
HAS BEEN INFORMED THAT A
MAINTENANCE INTERVAL IS NOW DUE
*CHECK INSTALLATION OF DRIVER'S
FLOOR MAT *CAR WASH INCLUDING:
HAND CAR WASH INTERIOR VACUUM
CLEAN WINDOWS TIRE SHINE ~|~

DROVE VEHICLE AND CODES DID NOT
RETURNT STEVINSON LEXUS WILL
PROVIDE A COURTESY RENTAL
VEHICLE FOR VIRTUALLY ANY
SERVICE VISIT. IN AN EFFORT
~|~ STEVINSON LEXUS WILL PROVIDE A
COURTESY RENTAL VEHICLE FOR
VIRTUALLY ANY SERVICE VISIT. IN AN
EFFORT TO OFFSET FUEL COSTS, A
\$9.75 FEE WILL BE ADDED TO THIS
INVOICE FOR THE PERIOD THE RENTAL
IS USED. ~|~ STEVINSON LEXUS WILL
PROVIDE A COURTESY RENTAL
VEHICLE FOR VIRTUALLY ANY
SERVICE VISIT. IN AN EFFORT

SERVICE: MULTI-POINT INSPECTION

DESCRIPTION: MULTI-POINT
INSPECTION ~|~*LEXUS MULTI-POINT
INSPECTION ~|~

203805 MILES

DATE: 03/08/2018

REPAIR# 0522924

REPORTED BY: Stevinson Lexus of Lakewood

SERVICE:

DESCRIPTION: DIAG AND INSTALL
NEW EVAP AIR PUMP DRIVER,
CLEARED CODES, TEST DROVE
VEHICLE, VEHICLE PASSED EVAP
~|~ CUSTOMER STATES CHECK ENGINE
AND OTHER WARNING LIGHT PRESENT.
PLEASE CHECK AND ADVISE. ~|~
~|~ 203805 250 DIAG AND INSTALL NEW
EVAP AIR PUMP DRIVER - CLEAR
CODES - PERF EVAP TEST - PASSES -
TEST DRIVE - OKDIAG AND INSTALL
NEW EVAP AIR PUMP DRIVER,
CLEARED CODES, TEST DROVE
VEHICLE, VEHICLE PASSED EVAP

SERVICE: CHECK ENGINE LIGHT IS ON

DESCRIPTION: CHECK ENGINE LIGHT
IS ON ~|~ CHECK ENGINE LIGHT IS ON
~|~

SERVICE: GUEST DECLINED
RECOMMENDED MAINTENANCE AT
THIS TIME.

DESCRIPTION: GUEST DECLINED
RECOMMENDED MAINTENANCE AT
THIS TIME. ~|~*DEFERRED
MAINTENANCE INTERVAL CUSTOMER
HAS BEEN INFORMED THAT A
MAINTENANCE INTERVAL IS NOW DUE
*CHECK INSTALLATION OF DRIVER'S
FLOOR MAT *CAR WASH INCLUDING:
HAND CAR WASH INTERIOR VACUUM
CLEAN WINDOWS TIRE SHINE ~|~

SERVICE: MULTI-POINT INSPECTION

DESCRIPTION: MULTI-POINT
INSPECTION ~|~*LEXUS MULTI-POINT
INSPECTION ~|~

139124 MILES

DATE: 08/28/2015

REPAIR# 0456741

REPORTED BY: Stevinson Lexus of Lakewood

SERVICE:

DESCRIPTION: STEVINSON LEXUS
WILL PROVIDE A COURTESY RENTAL
VEHICLE FOR VIRTUALLY ANY
SERVICE VISIT. IN AN EFFO
~|~STEVINSON LEXUS WILL PROVIDE A
COURTESY RENTAL VEHICLE FOR
VIRTUALLY ANY SERVICE VISIT. IN AN
EFFORT TO OFFSET FUEL COSTS, A
\$9.75 FEE WILL BE ADDED TO THIS
INVOICE FOR THE PERIOD THE RENTAL
IS USED. ~|~STEVINSON LEXUS WILL
PROVIDE A COURTESY RENTAL
VEHICLE FOR VIRTUALLY ANY
SERVICE VISIT. IN AN EFFO

SERVICE: INSPECTION

DESCRIPTION: INSPECTION
~|~CUSTOMER STATES WHEN YOU
COME TO A SLOW STOP THE BRAKE
PEDAL SEEMS TO BLEED OUT. WAS
TOLD THERE WERE CODES C1201M

SERVICE: CLEANED SEAT BELT

DESCRIPTION: CLEANED SEAT BELT
~|~CUSTOMER STATES THE PASS REAR
SEAT BELT DOES NOT RETRACT. CHK
AND ADV ~|~ ~|~139124 50 CLEANED LR
SEATBELT AS BEST POSSIBLE.
RETRACTING BETTER AFTER.
RECOMMEND REPLACING SEATBELT,
CUSTOMER DECLINED AT THIS TIME.

SERVICE: LEFT SIDE FORWARD SEAT
BUTTON

DESCRIPTION: LEFT SIDE FORWARD
SEAT BUTTON ~|~CUSTOMER STATES
THE DRIVER SIDE 3RD ROW SEAT IS
STUCK FOLDED DOWN. CHK AND ADV

C1241, AND C1452 IN THE SYSTEM. CHK AND ADV ~|~ ~|~139124 ALL CODES RELATED TO LOW BATTERY VOLTAGE, CLEAR CODES AND ROAD TEST VEH NO CODES AFTER. VEHICLE STOPS SAFELY WHEN BRAKING. FRONT BRAKES 10MM REAR 10MM. NO REPAIR MADE AT THIS TIME.

SERVICE: MULTI-POINT INSPECTION

DESCRIPTION: MULTI-POINT INSPECTION ~|~MULTI-POINT INSPECTION ~|~

~|~ ~|~139124 50 LEFT SIDE 3RD ROW SEAT STUCK CLOSE, UNFOLDED 3RD ROW SEAT BY PUSHING UP ON IT. ALSO FOUND LEFT SIDE 3RD ROW SEAT BACK AND FORWARD BUTTON STICKING, REPLACED BUTTON SEAT WORKING PROPERLY AFTER.

SERVICE: RADIO KNOB

DESCRIPTION: RADIO KNOB ~|~CUSTOMER STATES THE RADIO KNOB NEEDS PUT BACK ON. CHK AND ADV ~|~ ~|~139124 20 INSTALLED NEW RADIO KNOB.

126556 MILES

DATE: 02/27/2015

REPAIR# 0445273

REPORTED BY: Stevinson Lexus of Lakewood

SERVICE: LOANER

DESCRIPTION: LOANER ~|~STEVINSON LEXUS WILL PROVIDE A COURTESY RENTAL VEHICLE FOR VIRTUALLY ANY SERVICE VISIT. IN AN EFFORT TO OFFSET FUEL COSTS, A \$9.75 FEE WILL BE ADDED TO THIS INVOICE FOR THE PERIOD THE RENTAL IS USED. ~|~

SERVICE: MULTI-POINT INSPECTION

DESCRIPTION: MULTI-POINT INSPECTION ~|~MULTI-POINT INSPECTION ~|~

SERVICE: LUBE, OIL & FILTER CHANGE SPECIAL - \$69.95

DESCRIPTION: LUBE, OIL & FILTER CHANGE SPECIAL - \$69.95 ~|~LUBE, OIL & FILTER CHANGE SPECIAL - \$69.95 ~|~ ~|~126556 30 CHANGE ENGINE OIL AND OIL FILTER. FILL SPECIFIED ENGINE OIL. SET TIRE PRESSURE, FILL WASHER FLUID, BRIEF VISUAL UNDER-HOOD INSPECTION. RESET OIL MAINT LAMP IF APPLICABLE.

SERVICE: REPLACED ENGINE AND CABIN AIR FILTERS

DESCRIPTION: REPLACED ENGINE AND CABIN AIR FILTERS ~|~ENGINE AND CABIN FILTERS DIRTY - REPLACED AS NEEDED ~|~ ~|~126556 ENGINE AND CABIN FILTERS ARE RESTRICTED 30 REPLACED FILTERS

SERVICE: REPLACED SECONDARY AIR INJECTION PUMP AND SWITCHING VALVE ASSEMBLIES 1 AND 2
DESCRIPTION: REPLACED SECONDARY AIR INJECTION PUMP AND SWITCHING VALVE ASSEMBLIES 1 AND 2 ~|~CUST STATES THE VEHICLE IS DOWN ON POWER - IS NOT ACCELERATING PROPERLY // CHECK AND ADVISE ~|~ ~|~126556 P0418 P2240 P2442 P2445 AIR PUMP FILTER DEBRIS L-SB-0028-14 EG1403 230 R&R SECONDARY AIR INJECTION PUMP ASSEMBLY , AIR SWITCHING VALVE ASSEMBLY NO 1 AND NUMBER 2 PERFORMED ECU UPDATE FOR HESITATION. PROVIDED 1 TIME GOODWILL SERVICE CREDIT OF \$500.0

SERVICE: REPLACED WIPERS FRONT AND REAR
DESCRIPTION: REPLACED WIPERS FRONT AND REAR ~|~WIPERS STREAKING - REPLACED FRONT AND REAR ~|~ ~|~126556 WIPERS ARE STREAKING AND TORN REPLACED WIPER INSERTS

123449 MILES

DATE: 12/29/2014

REPAIR# 0442426

REPORTED BY: Stevinson Lexus of Lakewood

SERVICE: COMPLIMENTARY MULTI-POINT INSPECTION

DESCRIPTION: COMPLIMENTARY MULTI-POINT INSPECTION ~|~COMPLIMENTARY MULTI-POINT INSPECTION ~|~

SERVICE: LOANER

DESCRIPTION: LOANER

~|~STEVINSON LEXUS WILL PROVIDE A COURTESY RENTAL VEHICLE FOR VIRTUALLY ANY SERVICE VISIT. IN AN EFFORT TO OFFSET FUEL COSTS, A \$9.75 FEE WILL BE ADDED TO THIS INVOICE FOR THE PERIOD THE RENTAL IS USED. ~|~

SERVICE: DIAGNOSTICS

DESCRIPTION: DIAGNOSTICS ~|~CUST STATES THAT THE CHECK ENGINE LIGHT IS ON, PLEASE ADVISE. ~|~ ~|~123449 50 FAILED AIR INJECTION PUMP AND VALVES. CUSTOMER DECLINED - EST TO REPLACE \$2147.20

SERVICE: PROVIDED ESTIMATE FOR REPLACEMENT

DESCRIPTION: PROVIDED ESTIMATE FOR REPLACEMENT ~|~CUST STATES THE DRIVER SEAT BELT IS SLOW TO RETRACT / CHECK AND ADVISE ~|~ ~|~123449 PRICED SEAT BELT ASSY. CUSTOMER DECLINED - EST TO REPLACE \$500.00

SERVICE: PROVIDED ESTIMATES

DESCRIPTION: PROVIDED ESTIMATES

~|~CUST STATES THE REAR RIGHT SEAT
BELT FOR PASSENGER IS SLOW TO
RETRACT / CHECK AND ADVISE ~|~
~|~123449 PRICED SEAT BELT ASSY.
CUSTOMER DECLINED - EST \$580.00

85917 MILES

DATE: 06/28/2013

REPAIR# 0410810

REPORTED BY: Stevinson Lexus of Lakewood

SERVICE: CLEANED A/C FILTER-
FOUND LEAVES- LIKELY CAUSE OF
WHISTLE

DESCRIPTION: CLEANED A/C FILTER-
FOUND LEAVES- LIKELY CAUSE OF
WHISTLE ~|~C/S THE A/C HAS AN
INTERMITTANT WHISTLE- PLEASE
CHECK AND ADVISE ~|~ ~|~85917
FOUND IN A/C FILTER LIVES CLEAN A/C
FILTER

SERVICE: REPLACED 2 PASSENGER
FRONT SEATBACK CLIPS

DESCRIPTION: REPLACED 2
PASSENGER FRONT SEATBACK CLIPS
~|~C/S THE BACK OF PASSENGER
FRONT SEAT HAS FALLEN OFF- PLEASE
CHECK AND ADVISE ~|~ ~|~85917 30
FOUND BROKEN CLIPS, REPLACED
CLIPS AND REINSTALL SEAT BACK

81138 MILES

DATE: 04/23/2013

REPAIR# 0406613

REPORTED BY: Stevinson Lexus of Lakewood

SERVICE: COULD NOT DUPLICATE THE
A/C VENT NOISE

DESCRIPTION: COULD NOT
DUPLICATE THE A/C VENT NOISE
~|~CUSTOMER STATES THERE IS A
WHISTLE COMING FROM A/C SYSTEM-
PLEASE CHK&ADV, HIGH PITCHED
NOISE FROM THE VENTS.

SERVICE: LOANER

DESCRIPTION: LOANER ~|~TO AVOID
SCHEDULING CONFLICTS & TO
PROVIDE THE BEST SERVICE POSSIBLE,
RENTAL VEHICLES MUST BE
RETURNED BY THE SPECIFIED DAY
AND TIME. FAILURE TO RETURN THE
VEHICLE ON TIME WILL RESULT IN A

\$75 CHARGE FOR EACH DAY THE VEHICLE IS PAST DUE.

SERVICE: REPLACED LEFT INNER SENSOR, BY LICENCE PLATE
DESCRIPTION: REPLACED LEFT INNER SENSOR, BY LICENCE PLATE
~|~CUSTOMER STATES THE CHECK SONAR SYSTEM WARNING IS ON- PLEASE CHK&ADV.ERROR MESSAGE SAYS FRONT NOT WORKING, CHECK FRONT AND BACK ~|~ ~|~81138 200
REPLACED LF CENTER SONAR SENSOR

SERVICE: STEVINSON LEXUS WILL PROVIDE A COURTESY RENTAL VEHICLE FOR VIRTUALLY ANY SERVICE
DESCRIPTION: STEVINSON LEXUS WILL PROVIDE A COURTESY RENTAL VEHICLE FOR VIRTUALLY ANY SERVICE ~|~STEVINSON LEXUS WILL PROVIDE A COURTESY RENTAL VEHICLE FOR VIRTUALLY ANY SERVICE VISIT. IN AN EFFORT TO OFFSET FUEL & MAINTENANCE COSTS, A \$9.75 FEE WILL BE ADDED TO THIS INVOICE FOR THE PERIOD THE RENTAL IS USED.

SERVICE: WIPERS ARE OPERATING AS DESIGNED
DESCRIPTION: WIPERS ARE OPERATING AS DESIGNED
~|~CUSTOMER STATES: CHECK WIPER OPERATION ON AUTO SET AND INTERMITTANT. CHECK AND REPORT ~|~ ~|~81135 UNABLE TO DUPLICATE CUSTOMER CONCERN NO REPAIR ATTEMPT MADE AT THIS TIME

SERVICE: RESET REMINDER.
DESCRIPTION: RESET REMINDER.
~|~PLEASE RESET THE MAINTENANCE REMINDER MESSAGE

SERVICE: SWITCH SNAPPED BACK IN PLACE.
DESCRIPTION: SWITCH SNAPPED BACK IN PLACE. ~|~CUSTOMER STATES THE SIDE MIRROR CONTROLS ARE PUSHED INTO DASH- CHK&ADV ~|~ ~|~81135 REINSTALLED MIRROR SWITCH

REPAIR# 0351727

REPORTED BY: Stevinson Lexus of Lakewood

SERVICE: 10,000 MILE FULL SERVICE

DESCRIPTION: 10,000 MILE FULL SERVICE ~10,000 MILE FULL SERVICE ~10K ~14441 10K 00110F 60 COMPLETED 10K BRAKES AT F9MM R8MM TIRES AT 6/32 ALL AROUND

SERVICE: GENERAL

DESCRIPTION: GENERAL ~1~GUEST STATE THE REAR POWER OUTLET 115 VOLTS DOES NOT WORK ADVISE ~1~ ~1~14441 CUST STATES REAR POWER OUTLET INOP REAR POWER OUTLET WORKING AS DEISGNEED

6130 MILES

DATE: 05/03/2010

REPAIR# 0343842

REPORTED BY: Stevinson Lexus of Lakewood

SERVICE: 6 MO/ 5K MILE LIGHT

MAINTENANCE SERVICE (INCL. CHECKING OIL & OTHER FLUIDS, TIRE

DESCRIPTION: 6 MO/ 5K MILE LIGHT

MAINTENANCE SERVICE (INCL. CHECKING OIL & OTHER FLUIDS, TIRE

~1~6 MO/ 5K MILE LIGHT

MAINTENANCE SERVICE (INCL. CHECKING OIL & OTHER FLUIDS, TIRE ROTATION, BRAKE INSPECTION, LPS IF REQUESTED, NO OIL CHANGE). ~1~.

~1~6130 5K F 10/MM R 9/MM 00105L 4

CHECKING OIL OK 5K DONE

SERVICE: LOANER

DESCRIPTION: LOANER

~1~STEVINSON LEXUS WILL PROVIDE A COURTESY LOANER VEHICLE FOR VIRTUALLY ANY SERVICE VISIT. IN AN EFFORT TO OFFSET FUEL & MAINTENANCE COSTS, A \$6.80 FEE WILL BE ADDED TO THIS INVOICE FOR THE PERIOD THE LOANER IS USED.

SERVICE: NO CHARGES

DESCRIPTION: NO CHARGES ~1~TO AVOID SCHEDULING CONFLICTS & TO PROVIDE THE BEST SERVICE POSSIBLE, LOANER VEHICLES MUST BE RETURNED BY THE SPECIFIED DAY AND TIME. FAILURE TO RETURN THE VEHICLE ON TIME WILL RESULT IN A \$75 CHARGE FOR EACH DAY THE VEHICLE IS PAST DUE.

SERVICE: SPECIAL SERVICE

CAMPAIGN - ALB

DESCRIPTION: SPECIAL SERVICE

CAMPAIGN - ALB ~1~CUSTOMER IS CONCERNED WITH CONSUMER REPORT RECOMMENDATION FOR THE 2010GX. A LOANER WAS PROVIDED WHILE THE VEHICLE IS HELD FOR INVESTIGATION ~1~. ~1~6130 PERFORMED ALB SERVICE CAMPAIGN

1339 MILES

DATE: 02/08/2010

REPAIR# 0339912

REPORTED BY: Stevinson Lexus of Lakewood

SERVICE: 1,000 MILE SERVICE

DESCRIPTION: 1,000 MILE SERVICE

~1,000 MILE SERVICE ~1~MT ~1~1339
001010 40 PERFORMED 1K CHECKED
FLUIDS AND TIRES

14 MILES

DATE: 01/12/2010

REPAIR# 0338322

REPORTED BY: Stevinson Lexus of Lakewood

SERVICE: NEW CAR DETAIL

DESCRIPTION: NEW CAR DETAIL

~1~NEW CAR DETAIL ~1~ ~1~14 NCD
COMPLETED 130

SERVICE: NITROGEN TIRE INFLATION

DESCRIPTION: NITROGEN TIRE

INFLATION ~1~NITROGEN TIRE
INFLATION ~1~ ~1~14 30 FILLED TIRES
WITH NITROGEN

SERVICE: PRE-DELIVERY SERVICE FOR
USA ALL ALTITUDES

DESCRIPTION: PRE-DELIVERY

SERVICE FOR USA ALL ALTITUDES
~1~PRE-DELIVERY SERVICE FOR USA
ALL ALTITUDES ~1~PDI ~1~14 PDS 001013
200 COMPLETED

TERMS AND CONDITIONS

INFORMATION ACCURACY

Information presented on this website is summarized and standardized from repair orders completed at the time of service and submitted by Lexus dealers. When reviewing a vehicle's service history, please note that all information is provided by the Lexus Dealer that conducted the service, and that dealer is solely responsible for the accuracy, completeness or authenticity of any information contained in this site. Lexus provides this site and all information and materials contained herein "as is" without warranty of any kind. Any questions or concerns regarding this information should be addressed to the applicable Lexus dealer.

L/CERTIFIED OWNER INFORMATION

Dealer-reported service history records are linked to a vehicle's Vehicle Identification Number (VIN). All owner-reported service history records will be made available to the person who input the information on the site, but will not be shared with future owners of the vehicle.

OWNER-REPORTED INFORMATION AND PRIVACY TERMS

Lexus makes every effort to ensure the secure collection and transmission of sensitive user information using industry-accepted data collection and encryption methodologies. The information you provide is used by Lexus and its vendors and dealers to help improve the services we render. It is occasionally provided to Lexus dealers for their marketing use. Lexus will never sell your personally identifiable information to any other company. To learn more about our privacy policies and practices with respect to this website, please [click here](http://www.lexus.com/privacy/online-statement) ([//www.lexus.com/privacy/online-statement](http://www.lexus.com/privacy/online-statement)).