

2023 LEXUS RX 2.4L L4

[VIN]

Odometer: 43 miles

3 Confirmed Codes

U11B9 No description available

U11BF No description available

U1156 No description available

1 Pending Code

P2C90 No description available

1 Engine Control Module Code

P2C90- No description available

00

PENDING

1 Rear Motor Generator Code

U11B9- No description available

00

CONFIRMED

4 Motor Generator Codes

U11B9- No description available

00

CONFIRMED

U1156- No description available

87

CONFIRMED

U11B9- No description available

87

CONFIRMED

U11BF- No description available

87

CONFIRMED

1 Electric Motor Power Steering Code

C14FE- Steering Angle Sensor Supply Voltage: Circuit Short To Ground or Open

14

CONFIRMED

3 Advanced Parking Guidance System Codes

U114F- No description available

87

CONFIRMED

U0151- Lost Communication With Restraints Control Module: Missing Message

87

CONFIRMED

U0155- Lost Communication With Instrument Panel Cluster (IPC) Control Module: Missing Message

87

CONFIRMED

2 Antilock Brake System Codes

C14FE- Steering Angle Sensor Supply Voltage: Circuit Short To Ground or Open

14

CONFIRMED

C137B- Brake System Control Module "A" System Voltage: System Voltage Low

A2

CONFIRMED

7 Main Body Codes

U0126- Lost Communication With Steering Angle Sensor Module: Missing Message

87

CONFIRMED

U0155- Lost Communication With Instrument Panel Cluster (IPC) Control Module: Missing Message

87

CONFIRMED

U0199- Lost Communication With "Door Control Module A": Missing Message

87

CONFIRMED

U0200- Lost Communication With "Door Control Module B": Missing Message

87

CONFIRMED

U0208- Lost Communication With "Seat Control Module A": Missing Message

87

CONFIRMED

U0230- Lost Communication With Rear Gate Module: Missing Message

87

CONFIRMED

U1115- Lost Communication with Tilt and Telescopic Module: Missing Message

87

CONFIRMED

3 Entry and Start Codes

B27C0- No description available

87

CONFIRMED

U0155- Lost Communication With Instrument Panel Cluster (IPC) Control Module: Missing Message

87

CONFIRMED

U0230- Lost Communication With Rear Gate Module: Missing Message

87

CONFIRMED

1 Back Door Code

B2204- No description available

87

CONFIRMED

1 Telematics Code

U0155- Lost Communication With Instrument Panel Cluster (IPC) Control Module: Missing
87 Message

CONFIRMED

Disclaimer: This information is provided without warranty and is subject to the Terms of Use posted at www.bluedriver.com/eula.html. Reproduction of this information or any portion thereof constitutes infringement of copyright.