SERVICE HISTORY FOR:

VIN: JTHBE262865007948

131449 MILES

REPAIR# 0308210 REPORTED BY: Germain Lexus of Easton

SERVICE: BODY ELECTRICAL DESCRIPTION: BODY ELECTRICAL ~|~FOUND RT SIDE MARKER BULB INOP.. ~|~ ~|~REPLACED

SERVICE: ENGINE OIL DESCRIPTION: ENGINE OIL ~|~OIL & FILTER CHANGE \$49.95 PLS TX AND SHOP SUPPLIES ~|~ ~|~OIL & FILTER CHANGE COMPLETE

SERVICE: INSPECT FOR FLUID LEAKS

SERVICE: CUSTOMER STATES DESCRIPTION: CUSTOMER STATES ~1~CUSTOMER STATES THAT THE TRUNK SHUTS VIOLENTLY ~1~FOUND TRUNK SUPPORT/STRUTS WEAK ~1~REPLACED BOTH TRUNK STRUTS/SUPPORTS

SERVICE: GLH-REPL PANEL AIRBAG MODULE DESCRIPTION: GLH-REPL PANEL AIRBAG MODULE

~!~CUSTOMER STATESSCHEDULE GLH ~!~THE SUBJECT VEHICLES ARE EQUIPPED WITH FRONT PASSENGER AIRBAG INFLATORS PRODUCED BY TAKATA. ACCORDING TO TAKATA TH PROPELLANT IN THESE INFLATORS MAY DEGRADE AFTER PROLONGED EXPOSURE TO HIGH ABSOLUTE HUMIDITY AND FLUCTUATING HIGH TEMPERATURES. DEGRADED PRO ~!~PERFORM REPAIR, REPLACE INSTRUMENT PANEL AIRBAG MODULE BGG23X 4.2

SERVICE: NON WARRANTABLE OPERATION CODE

DESCRIPTION: INSPECT FOR FLUID LEAKS

~|~CUSTOMER STATES THAT THE DRIVER SIDE WHEEL OR TIRE IS LOSING AIR ~|~FOUND SMALL SEEP ON SIDEWALL OF DRIVER REAR TIRE-CANNOT BE R EPAIRED ~|~SEE ADDED LINES

SERVICE: WHEEL BALANCE (TWO WHEELS) DESCRIPTION: WHEEL BALANCE (TWO WHEELS) ~|~MOUNT AND BALANCE TIRES 2 TIRES PER EST ~|~ ~|~REPLACED BOTH REAR TIRES

DESCRIPTION: NON WARRANTABLE OPERATION

CODE ~|~FREE DEALERSHIP COURTESY INSPECTION ~|~BATTERY GOOD-TIRES F-8/32-REAR NEW-BRAKES 3/7MM ~|~SEE MPI

120930 MILES

DATE: 01/31/2017

REPAIR# 0293905

REPORTED BY: Germain Lexus of Easton

SERVICE: BODY ELECTRICAL DESCRIPTION: BODY ELECTRICAL ~|~REPLACE FUSE ~|~ ~|~REPLACED 7.5AMP OBD FUSE .3 **SERVICE:** CUSTOMER STATES

DESCRIPTION: CUSTOMER STATES ~ | ~ CUSTOMER

STATESC/S THAT THEY ARE HAVING ELECTRICAL ISSUES WI TH VEHICLE PLEASE CHECK AND ADVISE. REAR PARK ASIST GOES AT TIMES FOR NO REASON POWER OUTLETS DO NOT WORK ~I~LEFT REAR P/A SENSOR IS GOING OFF. REMOVED BUMPER AND SWAPPED THE L/R AND R/R PA SENSORS AND FOUND THAT IT FOLLOWED TO THE R/R SIDE. RECOMMEND TO START BY REPLACING THE LEFT REAR P/A SENSOR. ~I~GAVE ESTIMATE WAS NOT QUOTED CHECK OUT, 1.0HR

SERVICE: INTERIOR TRIM

96104 MILES

DESCRIPTION: INTERIOR TRIM ~|~INSTALL R/R

DOOR PANEL PROPERLY ~|~~|~REMOVED AND REINSTALLED DRIVER REAR DOOR PANEL DOOR LOCK AND HANDLE ARE BOTH OPERATING PROPERLY NOW., 1.0HR

99135 MILES

REPAIR# 0383646

REPORTED BY: Mungenast Lexus of St. Louis

SERVICE: ENGINE OIL

DESCRIPTION: ENGINE OIL ~|~CUSTOMER

REQUESTS OIL AND FILTER CHANGE SERVICE & RESET MAINTENANCE LIGHT ~|~ ~|~OEM OIL & FILTER CHANGE 06/10

DESCRIPTION: NON WARRANTABLE OPERATION

CODE ~|~FREE DEALERSHIP COURTESY INSPECTION ~|~~|~FB-5MM RB-8MM / TIRES 9-8/32 / BATTERY PASSED

DATE: 08/04/2015

SERVICE: NON WARRANTABLE OPERATION CODE

DESCRIPTION: NON WARRANTABLE OPERATION

SERVICE: SAFETY REMINDER

DESCRIPTION: SAFETY REMINDER ~|~AS A SAFETY REMINDER: ONLY ONE FLOOR MAT AT A TIME SHOULD BE USED ON THE DRIVER'S SIDE. THIS MAT SHOULD BE SECURED. IF YOU CAME IN TODAY WITH MORE THAN ONE MAT, FOR YOUR SAFETY IT WILL BE PLACED IN THE TRUNK. ~|~

REPAIR# 0375752

REPORTED BY: Mungenast Lexus of St. Louis

SERVICE: SAFETY REMINDER

DESCRIPTION: SAFETY REMINDER ~|~AS A SAFETY REMINDER: ONLY ONE FLOOR MAT AT A TIME SHOULD BE USED ON THE DRIVER'S SIDE. THIS MAT SHOULD BE SECURED. IF YOU CAME IN TODAY WITH MORE THAN ONE MAT, FOR YOUR SAFETY IT WILL BE PLACED IN THE TRUNK. ~|~

SERVICE: TIRE PRES WARN LIGHT

DESCRIPTION: TIRE PRES WARN LIGHT

~|~CUSTOMER STATES THAT THE TIRE PRESSURE WARNING LIGHT IS ON WE FIXED ONE TIRE ~|~RIGHT FRONT WHEEL HAS A FIT KIT THAT IS LEAKING. AND THE WHEEL IS ALSO BENT AND COULD BE CAUSING THE LEAK ~|~CLEANED CORROSION FROM THE BEAD SEAL AND REPLACED THE FIT KIT. IF THE TIRE LEAKS AGAIN IT WILL NEED A NEW WHEEL

95798 MILES

DATE: 04/09/2015

REPAIR# 0374678

REPORTED BY: Mungenast Lexus of St. Louis

SERVICE: FUEL PRESSURE SENSOR

DESCRIPTION: FUEL PRESSURE SENSOR

~|~CUSTOMER REQUESTS SAFETY RECALL ELF ~|~POTENTIAL FUEL PRESSURE SENSOR LEAK ~|~PERFORMED SAFETY RECALL ELF

SERVICE: NON WARRANTABLE OPERATION CODE

DESCRIPTION: NON WARRANTABLE OPERATION

SERVICE: SAFETY REMINDER

SERVICE: OTHERS

DESCRIPTION: OTHERS ~|~REPLACED FRONT

BRAKE PADS AND REPLACED FRONT ROTORS ~ |~

DESCRIPTION: SAFETY REMINDER ~|~AS A SAFETY

REMINDER: ONLY ONE FLOOR MAT AT A TIME SHOULD BE USED ON THE DRIVER'S SIDE. THIS MAT SHOULD BE SECURED. IF YOU CAME IN TODAY WITH MORE THAN ONE MAT, FOR YOUR SAFETY IT WILL BE PLACED IN THE TRUNK. ~|~

SERVICE: TIRE-WHEEL DESCRIPTION: TIRE-WHEEL ~|~CUSTOMER REQUESTS WE REPAIR TIRE ~|~FOUND LEFT REAR TIRE TO BE LEAKING FROM BOTH THE BEAD SEAL AND FIT KIT ~|~CLEANED CORROSION FROM THE WHEEL AND REPLACED THE FIT KIT

DATE: 01/08/2015

93273 MILES

REPAIR# 0219443

REPORTED BY: Plaza Lexus

SERVICE: CUSTOMER STATES THE CHECK ENGINE WARNING LIGHT IS ON. CHECK AND ADVISE. DESCRIPTION: CUSTOMER STATES THE CHECK ENGINE WARNING LIGHT IS ON. CHECK AND ADVISE. ~I~CUSTOMER STATES THE CHECK ENGINE WARNING LIGHT IS ON. CHECK AND ADVISE. ~I~ ~I~93273 P0441, P0455. INCORRECT PURGE FLOW AND GROSS LEAK DETECTED. FOUND GAS CAP LOOSE. CLEARED CODES, PERFORMED EVAP SYSTEM CHECK, AND NO CODES RETURNED. SERVICE: LOANER VEHICLE DESCRIPTION: LOANER VEHICLE ~|~LOANER VEHICLE ~|~

SERVICE: LUBE OIL AND FILTER DESCRIPTION: LUBE OIL AND FILTER ~I~LUBE OIL AND FILTER ~I~ ~I~93273 COMPLETED

SERVICE: MULTI POINT INSPECTION DESCRIPTION: MULTI POINT INSPECTION ~|~MULTI POINT INSPECTION ~|~

87497 MILES

DATE: 07/19/2014

REPAIR# 0209961

REPORTED BY: Plaza Lexus

SERVICE: LUBE OIL AND FILTER DESCRIPTION: LUBE OIL AND FILTER ~|~LUBE OIL AND FILTER ~|~~|~87497 PERFORMED OIL CHANGE SERVICE: MULTI POINT INSPECTION DESCRIPTION: MULTI POINT INSPECTION ~|~MULTI POINT INSPECTION ~|~ ~|~87497 WILL NEED FRONT AND REAR BRAKES IF NOT NOW THEN NEXT SERVICE.BRAKES FRONT AND REAR 3-4MM---RF WHEEL IS BENT-----TIRES 8-9/32S FRONT 7/32S REAR

SERVICE: RECOMMEND FRONT AND REAR BRAKES SOON \$259.95 FRONT, \$269.95 REAR DESCRIPTION:

87283 MILES

DATE: 07/07/2014

REPAIR# 0208983

REPORTED BY: Plaza Lexus

SERVICE: MISC REPAIRS DESCRIPTION: MISC REPAIRS ~| ~DID NOT PERFORM ANYTHING - CUSTOMER DID NOT HAVE TIME - WILL RESCHEDULE FOR ANOTHER DAY ~|~

82076 MILES

DATE: 02/01/2014

REPAIR# 0200274

REPORTED BY: Plaza Lexus

SERVICE: CUSTOMER STATES THE LOW TIRE LIGHT IS ON, CHECK AND ADVISE. DESCRIPTION: CUSTOMER STATES THE LOW TIRE LIGHT IS ON, CHECK AND ADVISE. ~!~CUSTOMER STATES THE LOW TIRE LIGHT IS ON, CHECK AND ADVISE. ~!~

82075 MILES

DATE: 01/31/2014

REPAIR# 200072C

REPORTED BY: Plaza Lexus

SERVICE: FREE MULTI- POINT INSPECTION DESCRIPTION: FREE MULTI- POINT INSPECTION ~|~FREE MULTI- POINT INSPECTION ~|~ SERVICE: OIL AND FILTER - CHANGE DESCRIPTION: OIL AND FILTER - CHANGE ~|~OIL AND FILTER - CHANGE ~|~FWS COUPON #7

82076 MILES

DATE: 01/30/2014

REPAIR# 0200072 REPORTED BY: Plaza Lexus

SERVICE: MOVED TO: 200072C LINE: A DESCRIPTION: MOVED TO: 200072C LINE: A ~|~MOVED TO: 200072C LINE: A ~|~

SERVICE: REPLACE CAMSHAFT TIMING GEAR ON IS DESCRIPTION: REPLACE CAMSHAFT TIMING GEAR ON IS ~|~SAFETY RECALL (DLG) VVT ACTUATOR GEAR ~|~DLG CAMPAIGN ~|~82075 COMPLETED DLG SERVICE: MOVED TO: 200072C LINE: B DESCRIPTION: MOVED TO: 200072C LINE: B ~|~MOVED TO: 200072C LINE: B ~|~

77282 MILES

DATE: 08/31/2013

REPAIR# 0192725

REPORTED BY: Plaza Lexus

SERVICE: CLEAR-VIEW ADVANTAGE WIPER

PROGRAM. INSTALL NEW FRONT WIPER INSERTS OR BLADES. C

SERVICE: FUEL INDUCTION SERVICE DESCRIPTION: FUEL INDUCTION SERVICE ~|~FUEL INDUCTION SERVICE ~|~~|~77282 PERFORMED FUEL INDUCTION SERVICE DESCRIPTION: CLEAR-VIEW ADVANTAGE WIPER PROGRAM. INSTALL NEW FRONT WIPER INSERTS OR BLADES. C ~ | ~ CLEAR-VIEW ADVANTAGE WIPER PROGRAM. INSTALL NEW FRONT WIPER INSERTS OR BLADES. COMPLIMENTARY SERVICE EVERY 6 MONTHS ~ | ~ ~ | ~77282 COMPLETE

SERVICE: INSTALL ENGINE AIR FILTER DESCRIPTION: INSTALL ENGINE AIR FILTER ~|~INSTALL ENGINE AIR FILTER ~|~~|~77282 INSTALLED NEW ENGINE AIR FILTER

SERVICE: MISC MAINT REPAIR DESCRIPTION: MISC MAINT REPAIR ~|~ROTATE TIRES

SERVICE: LUBE OIL AND FILTER DESCRIPTION: LUBE OIL AND FILTER ~|~LUBE OIL AND FILTER ~|~~|~77282 PERFORMED OIL AND FILTER SERVICE

SERVICE: MULTI POINT INSPECTION

DESCRIPTION: MULTI POINT INSPECTION ~|~MULTI

POINT INSPECTION ~|~ ~|~77282 PERFORM 27 POINT INSPECTION***BATTERY FAILED LOAD TEST, CABIN FILTER IS DIRTY***

71792 MILES

DATE: 04/10/2013

REPAIR# 0185098

REPORTED BY: Plaza Lexus

SERVICE: DRV SIDE FRT WINDOW MAKING NOISE WHEN ROLLING UP AND DOWN----ADIVE DESCRIPTION: DRV SIDE FRT WINDOW MAKING NOISE WHEN ROLLING UP AND DOWN----ADIVE ~|~DRV SIDE FRT WINDOW MAKING NOISE WHEN ROLLING UP AND DOWN----ADIVE ~|~FOUND SERVICE: EXTERIOR CAR WASH 15.99 VALUE NO CHARGE TO CUSTOMER DESCRIPTION: WINDOW REGULATOR BOLTS TO HAVE COME LOOSE. ~|~71792 FOUND WINDOW REGULATOR BOLTS TO HAVE COME LOOSE. REMOVED LEFT FRONT DOOR PANEL AND TIGHTENED WINDOW REGULATOR BOLTS TO SPEC- WINDOW NOW NO LONGER MAKING NOISE WHILE OPERATING.

SERVICE: MULTI POINT INSPECTION

DESCRIPTION: MULTI POINT INSPECTION ~|~MULTI POINT INSPECTION ~|~~|~71792 PERFORM 27 POINT INSPECTION

SERVICE: R&R BANK 1 & BANK 2 INTAKE

CAMSHAFT GEAR ASSY **DESCRIPTION:** R&R BANK 1 & BANK 2 INTAKE CAMSHAFT GEAR ASSY ~1~CUST STATES THAT THE WHEN FIRST STARTING THE VEH THERE IS A GRINDING TYPE NOISE----ADVISE ON REPAIRS ~1~HEARD GRINDING/RATTLE NOISE ON COLD START UP- REVISED INTAKE CAMSHAFT GEAR DESIGNS AVAILABLE TO CORRECT CONDITION. ~1~71792 HEARD GRINDING/RATTLE NOISE ON COLD START UP- REVISED INTAKE CAMSHAFT GEAR DESIGNS AVAILABLE TO CORRECT CONDITION. REMOVED VALVE COVERS AND INTAKE SURGE TANK- REMOVED CAMSHAFTS AND REPLACED INTAKE CAM GEARS WITH REVISED DESIGN PER L-SB-0156-08. T1 0

SERVICE: PASS SIDE

DESCRIPTION: PASS SIDE ~|~PASS SIDE SPEAKER BLOWN---ADVISE ~|~NO SPEAKER FOUND TO BE BLOWN AT THIS TIME. ~|~71792 NO SPEAKER FOUND TO BE BLOWN AT THIS TIME. ONLY ABNORMAL NOISE HEARD WHEN LISTEN TO SPEAKERS WAS MISCELLANEOUS ITEMS IN PASSENGER FRONT DOOR POCKET RATTLING WHILE SPEAKERS OPERATING- REMOVED BIG ITEMS AND PLACED ON PASSENGER FRONT SEAT- SMALLER ITEM

SERVICE: REMOVE SERRATION PATTERN & INSTALL

NEW WIPER ARM NUTS **DESCRIPTION:** REMOVE SERRATION PATTERN & INSTALL NEW WIPER ARM NUTS ~|~DLA--CAMPAIGN ~|~DLA SSC NEEDED TO BE COMPLETED. ~|~71792 DLA SSC NEEDED TO BE COMPLETED. PERFORMED DLA SSC- REMOVED WIPER ARMS AND CLEANED SPLINE MARKS FROM WIPER ARMS-REINSTALLED WITH NEW NUTS AND TORQUED TO SPEC- NO PROBLEMS. **SERVICE:** REPLACE ENGINE OIL

DESCRIPTION:

SERVICE: REPLACE INTERNAL TRUNK RELEASE LEVER DESCRIPTION: REPLACE INTERNAL TRUNK RELEASE LEVER ~|~DLB---CAMPAIGN ~|~DLB SSC NEEDED TO BE COMPLETED. ~|~71792 DLB SSC NEEDED TO BE COMPLETED. PERFORMED DLB SSC-REPLACED INTERNAL TRUNK RELEASE LEVER.

SERVICE: REPLACE ENGINE OIL FILTER DESCRIPTION:

SERVICE: RESET SERVICE INDICATOR DESCRIPTION:

SERVICE: ROAD TEST DESCRIPTION:

SERVICE: SERVICE - 70,000 MILES DESCRIPTION: SERVICE - 70,000 MILES ~|~SERVICE -70,000 MILES...MAINT PLAN AUTH# 49100485 ~|~ ~|~71792 PERFORMED 70K SERVICE.

66200 MILES

DATE: 10/23/2012

REPAIR# 0177856

REPORTED BY: Plaza Lexus

SERVICE: JMA OIL CHANGE AND ROTATE DESCRIPTION: JMA OIL CHANGE AND ROTATE ~|~JMA OIL CHANGE AND ROTATE ~|~JMA OIL CHANGE ~|~66200 JMA OIL CHANGE JMA OIL CHANGE COMPLETED, NO ROTATE SERVICE: MULTI POINT INSPECTION DESCRIPTION: MULTI POINT INSPECTION ~|~MULTI

POINT INSPECTION ~ | ~ ~ | ~66200 PERFORM 27 POINT INSPECTION

SERVICE: SAFTEY AND EMISSIONS INSPECTION

DESCRIPTION: SAFTEY AND EMISSIONS

INSPECTION ~|~SAFTEY AND EMISSIONS INSPECTION ~|~SAFETY AND EMISSIONS ~|~66200 SAFETY AND EMISSIONS SAFETY AND EMISSIONS COMPLETED

60684 MILES

DATE: 05/09/2012

REPAIR# 0301922

REPORTED BY: Mungenast Lexus of St. Louis

SERVICE: 60000 MILE SERVICE NON WARRANTY

DESCRIPTION: 60000 MILE SERVICE NON

WARRANTY ~1~CUSTOMER REQUESTS 60000 MILE SERVICE RESET MAINTENANCE LIGHT ~1~SCHEDULED MAINTENANCE DUE TO TIME OR MILEAGE ~1~60000 MILE SERVICE PERFORMED REPLACE ENGINE OIL AND OIL FILTER ROTATE,BALANCE AND ADJUST TIRE PRESSURES INSPECT AIR CONDITION FILTER RE TORQUES DRIVE SHAFT FLANGE BOLTS REPLACE BRAKE FLUID REPLACE AIR FILTER REPLACE ENGINE COOLANT REPLACE TRANSMISSION FLU

SERVICE: NEEDS ATTENTION SOON

DESCRIPTION: NEEDS ATTENTION SOON ~ | ~THE

55436 MILES

DATE: 12/22/2011

REPAIR# 0163387

SERVICE: EXTERIOR CAR WASH 15.99 VALUE NO

CHARGE TO CUSTOMER **DESCRIPTION:**

SERVICE: FRONT BRAKE PADS DESCRIPTION: FRONT BRAKE PADS ~|~C/S REPLACE PADS PER LAST VISIT ~|~ ~|~55436 REPLACE FRONT BRAKE PADS

SERVICE: MISC REPAIRS DESCRIPTION: MISC REPAIRS ~|~C/S THE CENTER FRONT CIGAR LIGHTER IS NOT OPERATING ~|~ ~|~55436 REPLACE CIG FUSEMISC REPAIRS ~|~C/S THE FRONT LEFT PARKING AID SENSOR HAS A MALFUNCTION, STATED THIS ON DISPLAY, ADVISE ~|~~|~55436 CK LT FRT SENSOR--WORKING CORRECTLY AT THIS TIME.MAY HAVE DIRT ORSOMETHING ON IT WHEN IT ACTS UP.

SERVICE: MULTI-POINT INSPECTION DESCRIPTION:

SERVICE: REPLACE ENGINE OIL FILTER DESCRIPTION:

SERVICE: ROAD TEST DESCRIPTION:

SERVICE: MULTI POINT INSPECTION DESCRIPTION: MULTI POINT INSPECTION ~|~MULTI POINT INSPECTION ~|~~|~55436 PERFORM 27 POINT INSPECTION

SERVICE: REPLACE ENGINE OIL DESCRIPTION:

SERVICE: RESET SERVICE INDICATOR DESCRIPTION:

SERVICE: SERVICE - 55,000 MILES DESCRIPTION: SERVICE - 55,000 MILES ~|~SERVICE -55,000 MILES ~|~~|~55436 PERFORM 55K SVC

50101 MILES

DATE: 08/06/2011

REPAIR# 0156292 REPORTED BY: Plaza Lexus

SERVICE: CAR WASH DESCRIPTION: CAR WASH ~|~CAR WASH ~|~ ~|~50101 CAR WASH

SERVICE: MULTI-POINT INSPECTION DESCRIPTION:

SERVICE: REPLACE ENGINE OIL FILTER DESCRIPTION:

SERVICE: ROAD TEST DESCRIPTION:

SERVICE: EXTERIOR CAR WASH 15.99 VALUE NO CHARGE TO CUSTOMER DESCRIPTION:

SERVICE: REPLACE ENGINE OIL DESCRIPTION:

SERVICE: RESET SERVICE INDICATOR DESCRIPTION:

AUTHORIZATION AMOUNT \$55.00

SERVICE: SERVICE - 50,000 MILES DESCRIPTION: SERVICE - 50,000 MILES ~ | ~ SERVICE -50,000 MILES ~ | ~ ~ | ~ 50101 PERFORM 50.000 SERVICE WILL NEED BRAKES AT NEXT SERVICE. CAR CARE SERVICE AUTHORIZATION NUMBER 27811347.

45291 MILES

DATE: 04/13/2011

REPAIR# 0790527

REPORTED BY: Plaza Lexus

SERVICE: CAMPAIGNS

SERVICE: ENGINE OIL

DESCRIPTION: CAMPAIGNS ~|~BLA---CAMPAIGN ~|~KC ~|~RETORQUED FUEL SENSOR COMPLETE

SERVICE: NON WARRANTABLE OPERATION CODE DESCRIPTION: NON WARRANTABLE OPERATION CODE ~|~REPLACE AIR FILTER. PART OF 45K SVC ~|~ ~|~COMPLETED.NON WARRANTABLE OPERATION CODE ~|~ ~|~ ~|~COMPLETE **DESCRIPTION:** ENGINE OIL ~ | ~CUSTOMER

REQUESTS LUBE, OIL, & FILTER CHANGE AND ROTATE...30 POINT INSPECTION FWS WARRANTY CAR CARE PLAN ~|~ ~|~OIL & FILTER CHANGE W/ LUBE 2006 AUTH# 28962415 92.00

SERVICE: SEE SECTION

DESCRIPTION: SEE SECTION ~!~INSPECT CABIN AIR FILTER AND REPLACE PART OF 45K SVC ~!~CABIN FILTER DIRTY ~!~REPLACED CABIN AIR FILTER AS REQSEE SECTION ~!~CK AND MAKE SURE A/C IS COOLING PROPERLY....ADVISE IF REPAIRS ARE NEEDED ~!~CENTER VENT BLOWING 40 DEGREE ~!~EVAC AND RECHARGE NOT REC AT THIS TIME COMPLETE

SERVICE: VACU FLUSH DECARB DESCRIPTION: VACU FLUSH DECARB ~1~#01661 CUSTOMER REQUESTS COMPLETE VACU FLUSH DECARB SERVICE ~1~ROUTINE MAINTENANCE ~1~PERFORMED COMPLETE VACU FLUSH DECARB SERVICE, SPRAYED THROTTLE BODY, AND INSTALLED PREMIUM TANK ADDITIVE

43448 MILES

DATE: 02/08/2011

REPAIR# 0776264

REPORTED BY: Plaza Lexus

SERVICE: ENGINE OIL

DESCRIPTION: ENGINE OIL ~|~LUBE, OIL, AND

FILTER CHANGE ~|~ ~|~OIL AND FILTER CHANGE CAR CARE SERVICE PLAN - AUTH# 29601675

DESCRIPTION: NON WARRANTABLE OPERATION

CODE ~ | ~ ~ | ~ ~ | ~ 27 POINT INSPECTION

39894 MILES

DATE: 09/29/2010

REPAIR# 0748624

REPORTED BY: Plaza Lexus

SERVICE: CAMPAIGNS

DESCRIPTION: CAMPAIGNS ~|~ALE ~|~PERFORM

ALE CAMPAIGN ~| ~COMPLETED ALE CAMPAIGN KC

38924 MILES

DATE: 08/31/2010

REPAIR# 0743089

REPORTED BY: Plaza Lexus

SERVICE: ENGINE OIL

DESCRIPTION: ENGINE OIL ~|~CUSTOMER

REQUESTS LUBE, OIL, & FILTER CHANGE ~|~ ~|~OIL & FILTER CHANGE W/ LUBE 2006 WR

SERVICE: NON WARRANTABLE OPERATION CODE

DESCRIPTION: NON WARRANTABLE OPERATION

CODE ~ | ~ ~ | ~ ~ | ~ 27 POINT INSP.

REPAIR# 0725872

REPORTED BY: Plaza Lexus

SERVICE: LEXUS BODYSHOP

DESCRIPTION: LEXUS BODYSHOP ~|~REPLACE REAR OTR PARKING SENSOR UNIT. REPAIR LT QTR PANEL, REAR BUMPER.

SERVICE: LEXUS REPAIR DESCRIPTION: LEXUS REPAIR ~ | ~ WASH AND CLEAN FOR DELIVERY SERVICE: LEXUS REFINISH DESCRIPTION: LEXUS REFINISH ~ | ~ REFNISH LT QTR PANEL, REAR BUMPER COVER.

DATE: 04/16/2010

33908 MILES

REPAIR# 0713792

REPORTED BY: Plaza Lexus

SERVICE: ACCESSORY

DESCRIPTION: ACCESSORY ~|~C/S THE CLOCK WILL NOT STAY SET, ADVISE ~|~CLOCK IS WORKING PROPERLY AT THIS TIME ~|~COULD NOT FIND ANY ISSUES WITH CLOCK KEEPING TIME. CHECKED FOR TSBS

SERVICE: MULTIPOINT INSPECT DESCRIPTION: MULTIPOINT INSPECT ~|~PERFORM MULTIPOINT INSPECTION ~|~~|~PERFORMED MULTI

SERVICE: ENGINE OIL

DESCRIPTION: ENGINE OIL ~|~CUSTOMER REQUESTS LUBE, OIL, & FILTER CHANGE ATTN: CAR CARE SERVICE PLAN APPLIES ~|~~|~OIL & FILTER CHANGE W/ LUBE 2006 WR

SERVICE: PEDAL MOD & REFLASH DESCRIPTION: PEDAL MOD & REFLASH ~|~SPECIAL SERVICE CAMPAIGN ACC PEDAL ~|~FLOOR MATT

30780 MILES

DATE: 12/31/2009

REPAIR# 0692340 REPORTED BY: Plaza Lexus

SERVICE: 30000 MILE SERVICE NON WARRANTY

DESCRIPTION: 30000 MILE SERVICE NON WARRANTY ~|~CUSTOMER REQUESTS 30000 MILE SERVICE ~|~SCHEDULED MAINTENANCE DUE TO TIME OR MILEAGE ~|~30000 MILE SERVICE PERFORMED WR

SERVICE: DELAYED TRANS SHIFT

DESCRIPTION: DELAYED TRANS SHIFT

~!~CUSTOMER STATES THAT THE TRANSMISSION SHIFT IS DELAYED WHEN LEAVING A STOP LIGHT AND GOING FROM LIGHT TO HEAVY THROTTLE, ADVISE ~!~ ~!~CHECKED TRANS OPERATION ON TEST DRIVE FOR PILLING ISSUE. TRANS SHIFTS NORMAL AT THIS TIME. HOLDING GEARS LONGER IS NORMAL WHEN ACCELERATING RAPIDLY.

SERVICE: FRONT/REAR BODY

DESCRIPTION: FRONT/REAR BODY ~|~C/S PLEASE RESECURE REAR DRIVER SIDE CHIP SHIELD ~|~ ~|~SECURED LEFT AND RIGHT SIDE GRAVEL SHIELDS

SERVICE: ABNORMAL BRAKE NOISE

DESCRIPTION: ABNORMAL BRAKE NOISE

~|~CUSTOMER STATES ABNORMAL BRAKE NOISE WHEN APPLIED USUALLY AT SLOW SPEEDS, LIGHT BRAKING ~|~ ~|~PERFORMED TSB L-SB-0015-09 WR

SERVICE: ENGINE OIL

DESCRIPTION: ENGINE OIL ~|~ATTN: CAR CARE SERVICE PLAN FOR OIL SERVICE AND ROTATE ~|~ ~|~NO ROTATE...IS350 WR

SERVICE: MULTIPOINT INSPECT DESCRIPTION: MULTIPOINT INSPECT ~ | ~ PERFORM MULTIPOINT INSPECTION

SERVICE: SEE SECTION DESCRIPTION: SEE SECTION ~|~C/S REPLACE CABIN AIR FILTER IF NEEDED ~|~CABIN FILTER DIRTY ~|~REPLACED CABIN AIR FILTER AS REQ WR

SERVICE: VEHICLE PULLS RIGHT

DESCRIPTION: VEHICLE PULLS RIGHT

~ | ~ CUSTOMER STATES VEHICLE PULLS RIGHT WHILE DRIVING ADVISE ~ | ~ ~ | ~ TEST DROVE VEHICLE ON 370, TESTED IN ALL LANES. RIGHT LANE IT WENT RIGHT, CENTER LANES WENT STRAIT, LEFT LANES WENT LEF T. VEHICLE WAS ALIGNED LAST VISIT WHEN STEERING RACK WAS REP LACED. WIDE LOW PROFILE TIRES WITH STIFF SIDEWALLS WILL TEND TO FOLLOW THE

26714 MILES

DATE: 06/23/2009

REPAIR# 0651395

REPORTED BY: Plaza Lexus

SERVICE: 1LB (SSC)

DESCRIPTION: 1LB (SSC) ~|~9LC ~|~ ~|~9LC STEERING LINK HT

SERVICE: CAMPAIGNS DESCRIPTION: CAMPAIGNS ~|~9LA ~|~ ~|~9LA HT SERVICE: ACCESSORY DESCRIPTION: ACCESSORY ~1~C/S BOTH KEY BATTERYS LOW ~1~ ~1~REPLACED KEY BATTERS WR

SERVICE: ENGINE OIL DESCRIPTION: ENGINE OIL ~|~CUSTOMER REQUESTS 25000 MILE SERVICE ~|~SCHEDULED MAINTENANCE DUE TO TIME OR MILEAGE ~|~LOF ONLY WR

SERVICE: SPECIAL SERVICE CAMPAIGN

SERVICE: WHEEL ALIGNMENT

DESCRIPTION: SPECIAL SERVICE CAMPAIGN ~|~9LB

~|~~|~9LB HT

DESCRIPTION: WHEEL ALIGNMENT ~|~PULLS

HARD TO RIGHT ~ |~ ~ |~ALIGNMENT WAS DONE WITH STEERING LINK

22814 MILES

DATE: 01/08/2009

REPAIR# 0617906

REPORTED BY: Plaza Lexus

SERVICE: NON WARRANTABLE OPERATION CODE

DESCRIPTION: NON WARRANTABLE OPERATION

CODE ~|~CUSTOMER REQUEST LOF AND TIRE ROTATE FEDILITY WARR LOF ~|~AUTH# 90080362 ~|~PERFORMED LOF AND TIRE ROTOTE HT

21114 MILES

REPAIR# 0599143

REPORTED BY: Plaza Lexus

SERVICE: NON WARRANTABLE OPERATION CODE DESCRIPTION: NON WARRANTABLE OPERATION CODE ~!~CUSTOMER REQUEST STATE INSPECTION AND EMISSIONS ~!~WR ~!~STATE INSPECTION COMPLETED. SAFETY AND EMISSIONS PRINOUT ON RF SEAT **DATE:** 10/08/2008

20506 MILES

REPAIR# 0593126

REPORTED BY: Plaza Lexus

SERVICE: ACCESSORY DESCRIPTION: ACCESSORY ~1~C/S CD IS IN-OP CD'S STUCK IN PLAYER ~1~CD PLAYER WILL NOT EJECT OR PLAY CDS. ~1~REPLACED CD PLAYER. PLAYER OPERATES CORRECTLY AT THIS TIME. RA#717232/RA

19576 MILES

DATE: 07/23/2008

REPAIR# 0583069

REPORTED BY: Plaza Lexus

SERVICE: 20000 MILE SERVICE NON WARRANTY-

NON OEM

DESCRIPTION: 20000 MILE SERVICE NON

WARRANTY-NON OEM ~|~CUSTOMER REQUESTS 20000 MILE SERVICE SEE ATTACHED SHEET FOR CAR CARE PLAN COVERAGE ~|~SCHEDULED MAINTENANCE DUE TO TIME OR MILEAGE ~|~20000 MILE SERVICE PERFORMED HT SERVICE: RADIO TUNER ASSEMBLY DESCRIPTION: RADIO TUNER ASSEMBLY ~| ~CD PLAYER INOP----CK AND ADVISE ON REPIARS NEEDED ~| ~CD PLAYER WILL NOT LOAD CDS. CD PLAYER INOP. ~| ~ORDERED NEW CD PLAYER.

SERVICE: WHEELS & TIRES

DATE: 09/09/2008

DESCRIPTION: WHEELS & TIRES ~ | ~CUST STATES THAT THE VEH PULLS TO THE LEFT AT HWY SPEEDS --PERFORM ALIGNMENT IF NEEDED ~ | ~NO PROBLEM FOUND. ~ | ~TEST DROVE VEHICLE, VEHICLE DROVE STRAIGHT DOWN CENTER LANE. TIRES ARE NOT ROTATED DUE TO SIZES. WILL NEED FRONT TIRES IN 5-10K MILES. RECOMMEND ALIGNMENT AFTER NEW TIRES ARE INSTALLED.

14186 MILES

DATE: 10/24/2007

REPAIR# 0525776

REPORTED BY: Plaza Lexus

SERVICE: 15000 MILE SERVICE NON WARRANTY

DESCRIPTION: 15000 MILE SERVICE NON

WARRANTY ~|~CUSTOMER REQUESTS 15000 MILE SERVICE DEDUCT THE LOF AND TIRE ROTATION FROM THIS SERVICE ~|~SCHEDULED MAINTENANCE DUE TO TIME OR MILEAGE ~|~PERFORMED 15000 MILE SERVICE DELETED LOF AND ROTATE HT

SERVICE: NON WARRANTABLE OPERATION CODE DESCRIPTION: NON WARRANTABLE OPERATION CODE ~!~PERFORM MAINTENANCE PER CAR CARE SERVICE PLAN LUBE, OIL, FILTER CHANGE AND TIRE

ROTATION ~|~AUTH# 72970981 CAR CARE SERVICE PLAN ~|~OIL & FILTER CHANGE W/ LUBE 2006 HT

9952 MILES

DATE: 05/25/2007

REPAIR# 0492633

REPORTED BY: Plaza Lexus

SERVICE: 10000 MILE SERVICE NON WARRANTY-NON OEM DESCRIPTION: 10000 MILE SERVICE NON WARRANTY-NON OEM ~|~CUSTOMER REQUESTS 10000 MILE SERVICE ~|~SCHEDULED MAINTENANCE DUE TO TIME OR MILEAGE ~|~10000 MILE SERVICE PERFORMED NO ROTATE HT

5464 MILES

DATE: 10/18/2006

REPAIR# 0447938

REPORTED BY: Plaza Lexus

SERVICE: 5,000 MILE SERVICE

DESCRIPTION: 5,000 MILE SERVICE ~|~5000 SVC--

RESET MAINT LIGHT ~|~SCHEDULED MAINTENANCE DUE TO TIME OR MILEAGE ~|~5000 MILE SERVICE PERFORMED WR

10 MILES

DATE: 05/25/2006

REPAIR# 0416918

REPORTED BY: Plaza Lexus

SERVICE: NON WARRANTABLE OPERATION CODE

DESCRIPTION: NON WARRANTABLE OPERATION

CODE ~|~PRE-DELIVERY SUPPLEMENT ~|~ ~|~PDIS HT SERVICE: PRE-DELIVERY SERVICE FOR USA ALL ALTITUDES DESCRIPTION: PRE-DELIVERY SERVICE FOR USA ALL ALTITUDES ~|~~|~PDI HT

TERMS AND CONDITIONS

INFORMATION ACCURACY

Information presented on this website is summarized and standardized from repair orders completed at the time of service and submitted by Lexus dealers. When reviewing a vehicle's service history, please note that all information is provided by the Lexus Dealer that conducted the service, and that dealer is solely responsible for the accuracy, completeness or authenticity of any information contained in this site. Lexus provides this site and all information and materials contained herein 'as is? without warranty of any kind. Any questions or concerns regarding this information should be addressed to the applicable Lexus dealer.

L/CERTIFIED OWNER INFORMATION

Dealer-reported service history records are linked to a vehicle's Vehicle Identification Number (VIN). All owner-reported service history records will be made available to the person who input the information on the site, but will not be shared with future owners of the vehicle.

OWNER-REPORTED INFORMATION AND PRIVACY TERMS

Lexus makes every effort to ensure the secure collection and transmission of sensitive user information using industry-accepted data collection and encryption methodologies. The information you provide is used by Lexus and its vendors and dealers to help improve the services we render. It is occasionally provided to Lexus dealers for their marketing use. Lexus will never sell your personally identifiable information to any other company. To learn more about our privacy policies and practices with respect to this website, please <u>click here</u> (//www.lexus.com/privacy/online-statement).