

LS430 – Known Problems

04 only – Transmission TSB

Mirrors – folding, aiming, auto fold, switch

Center console lid – closing, latch

Steering [wheel](#) – tilt & telescoping motors, etc.

Steering [wheel](#) – cracked wood

Subwoofer and other speakers blown out

Audio and other controls from steering wheel

Air Suspension

Door Lock actuator

Park Assist

Rear sunshade

Trunk & hood lifters

Headlight Leveling system

High Mileage

Suspension bushings, ball joints, etc.

Engine, transmission, & differential mounting bushings

Engine oil seals & Valve cover gaskets

Infrequent

Nav screens sometimes have issues where they short out, and say connection error.

NAV DVD drive

Touch screen

Passenger seat groaning

AC vents flow

Windshield wiper noise

Audio Amplifier

Power Door Closers

Glass delamination