



# Original Customer Requests

P7600

The following is what you requested we perform or investigate regarding your vehicle:

- ✓ 1. AS-IS INSPECTION
- ✓ 2. CHECK FOR OPEN RECALLS AT <https://vinrl.safercar.gov/vin/>



## Package Results

### Tom Wood Basic "As Is" U/C Inspection

#### Passed Tasks

- |                            |  |  |
|----------------------------|--|--|
| ✓ Check engine performance | ✓ Check emissions                                    | ✓ Check idler arm/pitman arm/relay rod           |
| ✓ Check tie rod ends       | ✓ Check ball joints                                  | ✓ Check tires                                    |
| ✓ Check brakes             | ✓ Check brake fluid                                  | ✓ Check for fuel leaks                           |
| ✓ Check for exhaust leaks  | ✓ Check headlamps                                    | ✓ Check tail lamps                               |
| ✓ Check brake lamps        | ✓ Check turn signals                                 | ✓ Check wipers/washers                           |
| ✓ Check windshield         | ✓ Check restraints-seatbelts & airbags (if equipped) | ✓ Check horn                                     |
| ✓ Check mirrors            | ✓ Check defroster                                    | ✓ Check transmission/differentials/transfer case |
| ✓ Check for codes          |  |  |

#### Additional Observations

#### Recommendation

RIGHT HEADLIGHT WASHER CAP MISSING	REPLACE RIGHT FRONT HEADLIGHT WASHER CAP
BRAKE VIBRATION	MACHINE FRONT ROTORS



## Recommended Services

Our technicians recommend the following services for your vehicle.

Original Customer Requests	Status	Cost	Deferred	Approved
1. AS-IS INSPECTION		\$252.80		X
2. CHECK FOR OPEN RECALLS AT <a href="https://vinrl.safercar.gov/vin/">https://vinrl.safercar.gov/vin/</a>		\$0.00		X
<b>Subtotal</b>		<b>\$252.80</b>		<b>\$252.80</b>
Additional Recommendations	Status	Cost	Deferred	Approved
REPLACE RIGHT FRONT HEADLIGHT WASHER CAP (RIGHT HEADLIGHT WASHER CAP MISSING)	Fail	\$65.10		X

Additional Recommendations		Status	Cost	Deferred	Approved
Subtotal			\$65.10		\$65.10
MACHINE FRONT ROTORS (BRAKE VIBRATION)		Caution	\$160.00		X
Subtotal			\$160.00		\$160.00
Totals, Taxes and Fees			Cost	Deferred	Approved
Estimate Subtotal			\$477.90	\$0.00	\$477.90
Shop Fee			\$39.95		\$39.95
Sales Tax			\$8.25		\$8.25
<b>Estimate Total</b>			<b>\$526.10</b>		<b>\$526.10</b>