


## Shift Gear from R back to P



At this point:

- 1.) You can sense there is increase resistance, hold there and do not back off.
- 2.) Count 1,2 \*(about 2 sec timing). Push the gear shift lever follow indicated patch to P.
- 3.) Try to Shift Gear from P back to R, it should be smooth now.
- 4.) If not, try step 1 & 2 for several times for ensure you catch the correct point/timing.