

Vehicle diagnostic report



Shop Name: al taief
Address: al qusais
Telephone: 042670522
Email :
Fax:

Make: LEXUS
Model: LS430
Year: 1998MY
VIN:

Vehicle Software Version: V48.91

Diagnostic Application Version: 3.10.010

Test Time: 2018-02-19 12:43:45

Diagnostic path: 16PIN DLC(Europe and Other) > Automatically Search > w/ Smart Key > System Selection > Powertrain > Engine and ECT

Engine and ECT (14)



Diagnostic Result

P0300	Random/Multiple Cylinder Misfire Detected	Current	Engine and ECT
P0303	Cylinder 3 Misfire Detected	Current	Engine and ECT
P0304	Cylinder 4 Misfire Detected	Current	Engine and ECT
P0305	Cylinder 5 Misfire Detected	Current	Engine and ECT
P0171	System too Lean (A/F Lean Malfunction, Bank 1)	Current	Engine and ECT
P0300	Random/Multiple Cylinder Misfire Detected	History	Engine and ECT
P0303	Cylinder 3 Misfire Detected	History	Engine and ECT
P0304	Cylinder 4 Misfire Detected	History	Engine and ECT
P0305	Cylinder 5 Misfire Detected	History	Engine and ECT
P0171	System too Lean (A/F Lean Malfunction, Bank 1)	History	Engine and ECT
P0300	Random/Multiple Cylinder Misfire Detected	Pending	Engine and ECT
P0304	Cylinder 4 Misfire Detected	Pending	Engine and ECT
P0305	Cylinder 5 Misfire Detected	Pending	Engine and ECT
P0171	System too Lean (A/F Lean Malfunction, Bank 1)	Pending	Engine and ECT