

Last Modified: 4-29-2015	6.6 S	Doc ID: RM000001FH0000X
Model Year: 2006	Model: LS430	Prod Date Range: [07/2005 -]
Title: STEERING COLUMN: POWER TILT AND POWER TELESCOPIC STEERING COLUMN SYSTEM: DIAGNOSTIC TROUBLE CODE CHART; 2006 MY LS430 [07/2005 -]		

DIAGNOSTIC TROUBLE CODE CHART

HINT:

If a trouble code is displayed during the DTC check, inspect the trouble areas listed for that code. For details of the code, refer to the "See page" below.

Power tilt and power telescopic steering column system:

DTC NO.	DETECTION ITEM	TROUBLE AREA	SEE PAGE
B2602	Key Unlock Warning Switch Circuit Malfunction	<ul style="list-style-type: none"> - Unlock warning switch*1 - Steering lock actuator (unlock warning switch)*2 - Unlock warning switch circuit - Transponder key ECU*1 (steering lock ECU*2) - Multiplex tilt and telescopic ECU 	INFO
B2610	Tilt Position Sensor or Tilt Motor Circuit Malfunction	<ul style="list-style-type: none"> - Power tilt motor (w/ tilt position sensor) - Actuator power source circuit - Tilt position sensor or tilt motor circuit - Multiplex tilt and telescopic ECU 	INFO
B2611	Telescopic Position Sensor or Telescopic Motor Circuit Malfunction	<ul style="list-style-type: none"> - Power telescopic motor (w/ telescopic position sensor) - Actuator power source circuit - Telescopic position sensor or telescopic motor circuit - Multiplex tilt and telescopic ECU 	INFO
B2620	ECU Power Source Circuit Malfunction	<ul style="list-style-type: none"> - Battery - ECU power source circuit - Multiplex tilt and telescopic ECU 	INFO
B2621	Communication Interruption	<ul style="list-style-type: none"> - Multiplex communication system - Driver side junction block - Position control ECU and switch (Driver seat ECU) - Turn signal switch - Steering column - Multiplex tilt and telescopic ECU 	INFO

HINT:

*1: w/o Smart access system

*2: w/ Smart access system

