

Subject: **Navigation Micro SD Card Error** Market: **USA**
 Service Category: **Audio/Visual/Telematics** Section: **Navigation/Multi Info Display**
 Applicability: **Generation 8 Navigation**

APPLICABLE VEHICLES

2015-2016	RC F	2015-2016	RC350
2015-2016	NX300H	2015-2016	ES300H
2015-2016	ES350	2015	LS600H
2015	LS460	2014-2016	GX460
2016	RC300	2014-2015	IS250
2015	GS350	2014-2016	CT200H
2014-2016	IS350	2016	IS300
2015-2016	NX200T	2016	IS200T
2015	GS450H	2016	RC200T

CONDITION


Navigation microSD card reads an error when missing or swapped from another vehicle.



Error message when micro SD card is swapped from another vehicle.



Error message when micro SD card is missing.



IS250/350 Micro SD card installation location.

RECOMMENDATIONS

- Do not interchange mSD cards. Each mSD card is "paired" with head unit.
- Once an mSD card is paired with a vehicle, it may not be swapped into a different vehicle.
- A new mSD card is "unpaired" and becomes "paired" when inserted into a vehicle.
- Service exchange radios come in "unpaired" service mode and accept used mSD cards.

Subject

Navigation Micro SD Card Error

Market

USA

Applicability

Generation 8 Navigation

RECOMMENDATIONS

- If an mSD card is swapped, returning it to the original vehicle will remedy the problem.

LINK REFERENCES

This Tech Tip does not contain any link references