

REAR SUSPENSION PARTS(1993 MODELS)

SC400 Part Name	SC400 Part Number	Supra Part Name	Supra Part Number
ARM ASSY, UPPER CONTROL, REAR RH	48770-24020	ARM ASSY, UPPER CONTROL, REAR RH	48770-19025
ARM ASSY, UPPER CONTROL, REAR LH	48790-24020	ARM ASSY, UPPER CONTROL, REAR LH	48790-19025
ARM ASSY, REAR LOWER CONTROL, RH NO.1	48730-30040	ARM ASSY, REAR LOWER CONTROL, RH NO.1	48730-14030
ARM ASSY, REAR LOWER CONTROL, LH NO.1	48740-30060	ARM ASSY, REAR LOWER CONTROL, LH NO.1	48740-14060
ARM ASSY, REAR LOWER CONTROL, RH NO.2	48710-24010	ARM ASSY, REAR LOWER CONTROL, RH NO.2	48710-14110
ARM ASSY, REAR LOWER CONTROL, LH NO.2	48710-24010	ARM ASSY, REAR LOWER CONTROL, LH NO.2	48710-14110
ROD ASSY, STRUT, REAR	48780-24030	ROD ASSY, STRUT, REAR	48780-14030
CARRIER SUB-ASSY, REAR AXLE, RH	42304-24020	CARRIER SUB-ASSY, REAR AXLE CARRIER, RH	42304-14020
CARRIER SUB-ASSY, REAR AXLE, LH	42305-24020	CARRIER SUB-ASSY, REAR AXLE, LH	42305-14020

FRONT SUSPENSION PARTS(1993 MODELS)

SC400 Part Name	SC400 Part Number	Supra Part Name	Supra Part Number
ARM ASSY, FRONT SUSPENSION UPPER, RH	48610-29045	ARM ASSY, FRONT SUSPENSION UPPER, RH	48610-19025
ARM ASSY, FRONT SUSPENSION UPPER, LH	48630-29045	ARM ASSY, FRONT SUSPENSION UPPER, LH	48630-19025
ARM SUB-ASSY, FRONT SUSPENSION, LOWER RH	48068-29165	ARM SUB-ASSY, FRONT SUSPENSION, LOWER RH	48068-14080
ARM SUB-ASSY, FRONT SUSPENSION, LOWER LH	48069-29165	ARM SUB-ASSY, FRONT SUSPENSION, LOWER LH	48069-14080
N/A (N/A IS WHAT THE DIAGRAM INDICATES. I GUESS THE SC400 DOESN'T HAVE ONE)	//////////////////////////////////// //////////////////////////////////// ////////////////////////////////////	STAY, LOWER ARM BRACKET, RH	48657-14020
N/A (N/A IS WHAT THE DIAGRAM INDICATES. I GUESS THE SC400 DOESN'T HAVE ONE)	//////////////////////////////////// //////////////////////////////////// ////////////////////////////////////	STAY, LOWER ARM BRACKET, LH	48658-14020
KNUCKLE, STEERING, RH	43211-24020	KNUCKLE, STEERING, RH	43211-24020
KNUCKLE, STEERING, LH	43212-24020	KNUCKLE, STEERING, LH	43212-24020

Taken from www.toyoDIY.com. If the numbers bare wrong I apologize for such an error.