


Last Modified: 7-13-2007		1.6 A
Service Category: Audio/Visual/Telematics	Section: Park Assist/Monitoring	
Model Year: 2008	Model: ES350	Doc ID: RM000001PYN00EX
Title: PARK ASSIST / MONITORING: CLEARANCE WARNING BUZZER: REMOVAL (2008 ES350)		

REMOVAL

1. REMOVE SHIFT LEVER KNOB SUB-ASSEMBLY [INFO](#)
2. REMOVE UPPER CONSOLE PANEL ASSEMBLY WITH FRONT ASH RECEPTACLE [INFO](#)
3. REMOVE INSTRUMENT PANEL FINISH PANEL END LH [INFO](#)
4. REMOVE INSTRUMENT PANEL FINISH PANEL END RH [INFO](#)
5. REMOVE NO. 2 INSTRUMENT PANEL REGISTER ASSEMBLY [INFO](#)
6. REMOVE INTEGRATION CONTROL PANEL WITH RADIO RECEIVER ASSEMBLY (w/o Navigation System) [INFO](#)
7. REMOVE MULTI-DISPLAY WITH RADIO RECEIVER ASSEMBLY (w/ Navigation System) [INFO](#)
8. REMOVE CLEARANCE WARNING BUZZER



(a) Disconnect the connector.



(b) Disengage the clamp and remove the clearance warning buzzer.