

SERVICE HISTORY FOR: 2002 GS300

VIN: JT8BD69S420172523

85924 miles

DATE: 03/2019

SERVICE:

DESCRIPTION: LOANER VEHICLE PROVIDED AS A COURTESY FROM BRIDGEWATER LEXUS. THANK YOU FOR RETURNING THE VEHICLE ~|~LOANER VEHICLE PROVIDED AS A COURTESY FROM BRIDGEWATER LEXUS. THANK YOU FOR RETURNING THE VEHICLE WITH IN 24 HOURS OF COMPLETION. ~|~LOANER VEHICLE PROVIDED AS A COURTESY FROM BRIDGEWATER LEXUS. THANK YOU FOR RETURNING THE VEHICLE

SERVICE: ARM, CONTROL (FRONT) - REPLACE

DESCRIPTION: ARM, CONTROL (FRONT) - REPLACE ~|~ARM, CONTROL (FRONT) - REPLACE ~|~ ~|~85924 REPLACED LEFT FRONT STRUT ROD ARM.ARM, CONTROL (FRONT) - REPLACE ~|~ARM, CONTROL (FRONT) - REPLACE ~|~ ~|~85924 REPLACED RIGHT FRONT STRUT ROD ARM.

SERVICE: BLADE, WIPER - WINDSHIELD - REPLACE

DESCRIPTION: BLADE, WIPER - WINDSHIELD - REPLACE ~|~BLADE, WIPER - WINDSHIELD - REPLACE ~|~ ~|~85924 REPLACED FRONT WIPER INSERTS.

SERVICE: FUEL ADDITIVE

DESCRIPTION:

SERVICE: MOUNT AND BALANCE 1 TIRE-SPECIAL ORDER MICH ICE X SOP TIRE TO RIGHT FRONT

DESCRIPTION: MOUNT AND BALANCE 1 TIRE-SPECIAL ORDER MICH ICE X SOP TIRE TO RIGHT FRONT ~|~MOUNT AND BALANCE 1 TIRE-SPECIAL ORDER MICH ICE X SOP TIRE TO RIGHT FRONT ~|~ ~|~85924 MOUNT AND BALANCE 1 TIRE. NOW ON RIGHT REAR. OLD DOT # HC3P 022X 5014 NEW DOT # HC3P 04HX 2616

SERVICE: PERFORM ALIGNMENT

DESCRIPTION: PERFORM ALIGNMENT ~|~PERFORM ALIGNMENT ~|~ ~|~85924 PERFORMED FOUR WHEEL ALIGNMENT.

SERVICE: REPLACE ENGINE OIL

DESCRIPTION:

SERVICE: REPLACE ENGINE OIL FILTER

DESCRIPTION:

SERVICE: ROAD TEST

DESCRIPTION:

SERVICE: ROTATE TIRES

DESCRIPTION:

SERVICE: SERVICE - 85,000 MILES

DESCRIPTION: SERVICE - 85,000 MILES ~|~SERVICE - 85,000 MILES ~|~ ~|~85924 PERFORM 85,000 MILE SERVICE AS REQUIRED INCLUDING OIL/FILTER CHANGE, SERVICE INDICATOR RESET, BRAKE INSPECTION, TIRE ROTATION AND TIRE

PRESSURE ADJUSTMENT TO VEHICLE SPECIFICATION, TOP OFF AND ADJUST ALL FLUIDS, AND WIPER BLADE INSPECTION. TIRES L/F

SERVICE: WASHER SOLVENT

DESCRIPTION:

83709 miles

DATE: 11/2018

SERVICE: 1 TIRE

DESCRIPTION: 1 TIRE ~|~ ~|~,CUSTOMER DECLINED SERVICE

SERVICE: MULTI POINT INSP

DESCRIPTION: MULTI POINT INSP ~|~ LEXUS OF BRIDGEWATER MULTI-POINT INSPECTION WITH REPORT CARD ~|~ ~|~COMPLETED MULTI POINT INSPECTION, LR

SERVICE: SUSPENSION CONCERN

DESCRIPTION: SUSPENSION CONCERN ~|~ ~|~,CUSTOMER DECLINED SERVICE

SERVICE: TIRE REPAIR

DESCRIPTION: TIRE REPAIR ~|~REMOVE WHEEL LOCKS AND REPLACE WITH LUG NUTS ~|~ ~|~REMOVED AND REPLACED LOCKS WITH NORMAL LUGS AS REQUESTED.

79997 miles

DATE: 03/2018

SERVICE: 80000 MILE SERVICE NON WARRANTY-NON OEM

DESCRIPTION: 80000 MILE SERVICE NON WARRANTY-NON OEM ~|~CUSTOMER REQUESTS A 80K MILE SERVICE ~|~CUSTOMER REQUESTS A 80K MILE SERVICE ~|~80,000 MILES OR 64 MONTHS SERVICE AT 80000 MILES

SERVICE: MULTI POINT INSP

DESCRIPTION: MULTI POINT INSP ~|~ LEXUS OF BRIDGEWATER MULTI-POINT INSPECTION WITH REPORT CARD ~|~ ~|~COMPLETED MULTI POINT INSPECTION, DW

77937 miles

DATE: 09/2017

SERVICE: *ALIGN 4 WHEELS

DESCRIPTION: *ALIGN 4 WHEELS ~|~CUSTOMER REQUEST PERFORM 4 WHEEL ALIGNMENT ~|~ ~|~ALIGN FOUR WHEELS 95/05

SERVICE: LOWER BALL JOINT ASSY 1-SD

DESCRIPTION: LOWER BALL JOINT ASSY 1-SD ~|~CUSTOMER STATES REPLACE BALL JOINTS ~|~ ~|~REMOVED AND REPLACED BOTH LOWER BALL JOINTS

SERVICE: MULTI POINT INSP

DESCRIPTION: MULTI POINT INSP ~|~LEXUS OF BRIDGEWATER MULTI-POINT INSPECTION WITH REPORT CARD ~|~ ~|~COMPLETED MULTI POINT INSPECTION
SERVICE: SUSPNSN L.ARM 1-SD W/O B.JNT
DESCRIPTION: SUSPNSN L.ARM 1-SD W/O B.JNT ~|~CUSTOMER STATES REPLACE UPPER CONTROL ARMS ~|~ ~|~REMOVED AND REPLACED BOTH UPPER CONTROL ARM BUSHINGS

77912 miles

DATE: 08/2017

SERVICE: EXTERIOR BULB
DESCRIPTION: EXTERIOR BULB ~|~CUSTOMER STATES PASS SIDE HEADLIGHT IS OUT ~|~PASS SIDE HEAD LIGHT OUT. DRIVER OUTER BRAKE LIGHT OUT ~|~REPLACED PASSENGER SIDE HEADLIGHT BULB, REPLACED DRIVER SIDE OUTER BRAKE LIGHT BULB.
SERVICE: MULTI POINT INSP
DESCRIPTION: MULTI POINT INSP ~|~LEXUS OF BRIDGEWATER MULTI-POINT INSPECTION WITH REPORT CARD ~|~ ~|~COMPLETED MULTI POINT INSPECTION
MULTI POINT INSP ~|~LEXUS OF BRIDGEWATER MULTI-POINT INSPECTION WITH REPORT CARD ~|~ ~|~COMPLETED MULTI POINT INSPECTION

75063 miles

DATE: 11/2016

SERVICE: 75000 MILE SERVICE NON WARRANTY
DESCRIPTION: 75000 MILE SERVICE NON WARRANTY ~|~75,000 MILE SERVICE ~|~CUSTOMER REQUESTS A 75K MILE SERVICE ~|~75,000 MILES OR 60 MONTHS SERVICE AT 75000 MILES
SERVICE: FRT PADS & RESURF
DESCRIPTION: FRT PADS & RESURF ~|~CUSTOMER REQUEST REPLACE FRONT BRAKE PADS AND RESURFACE FRONT BRAKE ROTORS ~|~ ~|~REPLACED FRONT BRAKE PADS AND RESURFACED FRONT BRAKE ROTORS
SERVICE: MULTI POINT INSP
DESCRIPTION: MULTI POINT INSP ~|~MULTI POINT INSPECTION ~|~ ~|~COMPLETED MULTI POINT INSPECTION
SERVICE: RENTAL CAR
DESCRIPTION: RENTAL CAR ~|~TECHNICIAN FOUND DURING MULTI-POINT INSPECTION THAT THE BRAKE PADS REQUIRE ATTENTION ~|~ ~|~CLIENT ELECTED NOT TO COMPLETE RECOMMENDED REPAIRS AT THIS TIME
SERVICE: RR BRAKES W/ RESURF
DESCRIPTION: RR BRAKES W/ RESURF ~|~CUSTOMER REQUEST REPLACE REAR BRAKE PADS AND RESURFACE REAR BRAKE ROTORS ~|~ ~|~REPLACED REAR BRAKE PADS AND RESURFACED REAR BRAKE ROTORS
SERVICE: TIMING BELT

DESCRIPTION: TIMING BELT ~|~UPON INSPECTION FOUND TIMING BELT DUE TO AGE AND MILES ~|~ ~|~REMOVED AND REPLACED TIMING BELT AND WATER PUMP

70377 miles

DATE: 12/2015

SERVICE: 70000 MILE SERVICE NON WARRANTY-NON OEM

DESCRIPTION: 70000 MILE SERVICE NON WARRANTY-NON OEM ~|~CUSTOMER REQUESTS A 70K MILE SERVICE ~|~CUSTOMER REQUESTS A 70K MILE SERVICE ~|~70,000 MILES OR 56 MONTHS SERVICE AT 70000 MILES

SERVICE: MULTI POINT INSP

DESCRIPTION: MULTI POINT INSP ~|~LEXUS OF BRIDGEWATER MULTI-POINT INSPECTION WITH REPORT CARD ~|~ ~|~COMPLETED MULTI POINT INSPECTION

66001 miles

DATE: 08/2015

SERVICE: 21 POINT SAFETY INP

DESCRIPTION: 21 POINT SAFETY INP ~|~LEXUS OF EDISON TO PERFORM 21 POINT VEHICLE SAFETY INSPECTION ~|~CHECK AND REPORT TO CLIENT ~|~LEXUS OF EDISON PERFORMED 21 POINT INSPECTION

SERVICE: BATTERY/COIL SPK PLUG

DESCRIPTION: BATTERY/COIL SPK PLUG ~|~CUSTOMER STATES HE LEFT THE DOOR OPEN BY MISTAKE CALLED AAA THEY JUMPED THE CAR BUT THE LIGHT ON THE DASH IS OUT AND THE BATTERY DIED AGAIN CHECK ADVISE ~|~DTC B1271. INTERNAL FAULT IN COMBINATION METER. ~|~CK ALL FUSES AND THEY ARE OK. CK DTC AND GOT B1271. CONFIRMED TACHOMETER, SPEEDOMETER AND ODOMETER DO NOT OPERATE AND ILLUMINATE. METER IS NEEDED FOR REPAIR. LEXUS CANNOT GET NEW COMBO METER. VEHICLE IS TOO OLD FOR SUPPLY. CUSTOMER WOULD HAVE TO SEARCH FO

SERVICE: DISTRIBUTOR/HDLIGHT/T. SGNL

DESCRIPTION: DISTRIBUTOR/HDLIGHT/T. SGNL ~|~CUSTOMER STATES THAT HE HAS A REAR TAIL LIGHT OUT DRIVER SIDE CHECK ADVISE ~|~LR INNER TAIL LAMP BULB BLOWN ~|~REPLACED BULB.

SERVICE: RED LIGHTS

DESCRIPTION: RED LIGHTS ~|~LIGHTS REQUIRE IMMEDIATE ATTENTION ~|~LR INNER TAIL LAMP BULB BLOWN. ~|~REPLACED BULB.

65170 miles

DATE: 10/2014

SERVICE: *MOUNT & BAL - 4

DESCRIPTION: *MOUNT & BAL - 4 ~|~MOUNT & BALANCE 4 WHEELS ~|~ ~|~MOUNT 4 TIRES

SERVICE: 21 POINT SAFETY INP

DESCRIPTION: 21 POINT SAFETY INP ~|~LEXUS OF EDISON TO PERFORM 21 POINT VEHICLE SAFETY INSPECTION ~|~CHECK AND REPORT TO CLIENT ~|~LEXUS OF EDISON PERFORMED 21 POINT INSPECTION

SERVICE: 65K MILE SVC

DESCRIPTION: 65K MILE SVC ~|~CUSTOMER REQUESTS A 65K MILE SERVICE ~|~CUSTOMER REQUESTS A 65K MILE SERVICE ~|~PERFORMED A 65K MILE SERVICE PER CUSTOMER'S REQUEST

SERVICE: WHEEL ALIGNMENT

DESCRIPTION: WHEEL ALIGNMENT ~|~PERFORM 4 WHEEL ALIGNMENT ~|~ ~|~4 WHEEL ALIGNMENT

61950 miles

DATE: 02/2014

SERVICE: 21 POINT SAFETY INP

DESCRIPTION: 21 POINT SAFETY INP ~|~LEXUS OF EDISON TO PERFORM 21 POINT VEHICLE SAFETY INSPECTION ~|~CHECK AND REPORT TO CLIENT ~|~LEXUS OF EDISON PERFORMED 21 POINT INSPECTION

SERVICE: ALIGNMENT CHECK

DESCRIPTION: ALIGNMENT CHECK ~|~PERFORMED FREE WHEEL ALIGNMENT CHECK ~|~PERFORMED FREE WHEEL ALIGNMENT CHECK AND VEHICLE PASSED ~|~.

SERVICE: MISC

DESCRIPTION: MISC ~|~CUSTOMER STATES BATTERY IS DEAD CHECK AND ADVISE. ~|~TECH CHECK ALTERNATOR NOTICE IT WAS CHARGING AT 13.9 VOLTS TEST BATTERY NOTICE IT DIDNT HOLD THE CHARGE,CHARGE BATTERY TEST IT DIDNT PASS RECOMMEND NEW BATTERY ~|~REQUESTED TO INSTAL NEW BATTERY,COMPLETED

SERVICE: NON WARRANTABLE OPERATION CODE

DESCRIPTION: NON WARRANTABLE OPERATION CODE ~|~CUSTOMER HEAR SQUEAKY NOISE UNDER ENGINE COMPARTMENT ~|~TECH CHECK NOISE IT WAS CAMING FROM THE BELT DRIVE RECOMMEND NEW BELT ~|~REQUESTED TO INSTALL NEW BELT,COMPLEETD

60100 miles

DATE: 09/2013

SERVICE: 21 POINT SAFETY INP

DESCRIPTION: 21 POINT SAFETY INP ~|~LEXUS OF EDISON TO PERFORM 21 POINT VEHICLE SAFETY INSPECTION ~|~CHECK AND REPORT TO CLIENT ~|~LEXUS OF EDISON PERFORMED 21 POINT INSPECTION

SERVICE: 60000 MILE SERVICE NON WARRANTY

DESCRIPTION: 60000 MILE SERVICE NON WARRANTY ~|~CUSTOMER REQUESTS
60000 MILE SERVICE ~|~SCHEDULED MAINTENANCE DUE TO TIME OR MILEAGE
~|~60000 MILE SERVICE PERFORMED - TOP OFF FLUIDS; ADJUST TIRE
PRESSURE;INSPECT BELTS & HOSES - ENGINE OIL AND FILTER REPLACEMENT -
AIR FILTER REPLACEMENT - AUTOMATIC TRANSMISSION FLUID REPLACEMENT -
CLEAN & TEST BATTERY, CABLES,AND CHARGING SYSTEM - FLUSH BR
SERVICE: ALIGNMENT CHECK
DESCRIPTION: ALIGNMENT CHECK ~|~PERFORMED FREE WHEEL ALIGNMENT
CHECK ~|~PERFORMED FREE WHEEL ALIGNMENT CHECK AND VEHICLE PASSED
~|~.

57543 miles

DATE: 02/2013

SERVICE: *ROTATE TIRES

DESCRIPTION: *ROTATE TIRES ~|~CUSTOMER REQUESTS TIRE ROTATION ~|~-----
----- -- ~|~ROTATE TIRES & VERIFY WHEEL LOCK
KEY IS PRESENT 95/05

SERVICE: CAR WASH

DESCRIPTION: CAR WASH ~|~CUSTOMER REQUESTS A COMPLIMENTARY CAR
WASH THAT INCLUDES: WASH EXTERIOR, CHAMOIS DRY AND VACUUM FLOOR
MATS. ~|~PERFORM COMPLIMENTARY CAR WASH ~|~COMPLIMENTARY CAR
WASH PERFORMED

SERVICE: CHECK ENGINE LIGHT

DESCRIPTION: CHECK ENGINE LIGHT ~|~CUSTOMER STATES CHECK ENGINE
LIGHT IS ON-DIAGNOSIS REQUESTED -----
~|~UPON INSPECTION THE TECHNICIAN TROUBLE CODE P0161 BANK 2 SENSOR 2
OXYGEN SENSOR FAILING. RECOMMEND REPLACING THE SENSOR -----
----- -- ~|~TECHNICIAN REPLACED THE SENSOR, CLEARED
THE CODES AND TEST DROVE TO VERIFY THE REPAIRS

SERVICE: NON WARRANTABLE OPERATION CODE

DESCRIPTION: NON WARRANTABLE OPERATION CODE ~|~CUSTOMER REQUESTS
LUBE OIL AND FILTER SERVICE ~|~-----
~|~OIL & FILTER CHANGE W/ LUBE-INCLUDES HAZMAT FEE \$1.62 93/05NON
WARRANTABLE OPERATION CODE ~|~WE REQUEST YOU REPLENISH ALL OF THE
FUEL YOU CONSUME. IN THE EVENT YOU DO NOT A \$4.95 PER GALLON
REFUELING CHARGE WILL BE ADDED TO YOUR INVOICE. WE REQUEST YOU
RETURN THE LOANER VEHICLE WITHIN 24 HOURS OF COMPLETION OF YOUR
VEHICLE. IN THE EVENT YOU DO NO ~|~CUSTOMER REQUEST COURTESY
VEHICLE ~|~PROVIDED COURTESY VEHICLE

SERVICE: OTHER INSPECTION

DESCRIPTION: OTHER INSPECTION ~|~FOR YOUR CONVENIENCE OUR LEXUS
CERTIFIED TECHNICAL STAFF WILL BE PERFORMING A VISUAL COURTESY
INSPECTION OF YOUR VEHICLE WHILE IT IS HERE, INCLUDING TIRE PRESSURE
ADJUSTMENT TO THE SPECIFICATION OF THE VEHICLE MANUFACTURER. YOUR
SERVICE CONSULTANT WILL DI ~|~PERFORM COURTESY INSPECTION

~|~INSPECTION COMPLETED INCLUDING SETTING THE TIRE PRESSURE TO THE MANUFACTURER'S SPECIFICATIONS.

SERVICE: OTHERS

DESCRIPTION: OTHERS ~|~UPON INSPECTION THE TECHNICIAN FOUND THE REAR BRAKES MEASURED AT 1.5MM OF PAD REMAINING. RECOMMEND REPLACNIG THE REAR BRAKES ----- ~|~ ~|~TECHNICIAN REPLACED THE REAR BRAKE PADS AND RESURFACED THE ROTORS

53469 miles

DATE: 11/2010

SERVICE: 55000 MILE SERVICE NON WARRANTY-NON OEM

DESCRIPTION: 55000 MILE SERVICE NON WARRANTY-NON OEM ~|~CUSTOMER REQUESTS 55000 MILE SERVICE ~|~SCHEDULED MAINTENANCE DUE TO TIME OR MILEAGE ~|~55,000 MILE OR 44 MONTH SERVICE AT 55000

SERVICE: CAR WASH

DESCRIPTION: CAR WASH ~|~CUSTOMER REQUESTS A COMPLIMENTARY CAR WASH THAT INCLUDES: WASH EXTERIOR AND CHAMOIS DRY VACUUM FLOOR MATS ~|~PERFORM COMPLIMENTARY CAR WASH ~|~COMPLIMENTARY CAR WASH PERFORMED

SERVICE: NON WARRANTABLE OPERATION CODE

DESCRIPTION: NON WARRANTABLE OPERATION CODE ~|~WE REQUEST YOU REPLENISH ALL OF THE FUEL YOU CONSUME. IN THE EVENT YOU DO NOT A \$3.25 PER GALLON REFUELING CHARGE WILL BE ADDED TO YOUR INVOICE. WE REQUEST YOU RETURN THE LOANER VEHICLE WITHIN 24 HOURS OF COMPLETION OF YOUR VEHICLE. IN THE EVENT YOU DO NO ~|~ ~|~.

SERVICE: OTHER INSPECTION

DESCRIPTION: OTHER INSPECTION ~|~FOR YOUR CONVENIENCE OUR LEXUS CERTIFIED TECHNICAL STAFF WILL BE PERFORMING A VISUAL COURTESY INSPECTION OF YOUR VEHICLE WHILE IT IS HERE, INCLUDING TIRE PRESSURE ADJUSTMENT TO THE SPECIFICATION OF THE VEHICLE MANUFACTURER. . TIRE PRESSURE SET TO LF.....R ~|~PERFORM COURTESY INSPECTION ~|~INSPECTION COMPLETED INCLUDING SETTING THE TIRE PRESSURE TO THE MANUFACTURER'S SPECIFICATIONS. FRONT BRAKE PADS HAVE THE FOLLOWING PAD REMAINING:10MM. REAR BRAKE PADS HAVE THE FOLLOWING PAD REMAINING:4MM. THE FRONT TIRES HAVE THE FOLLOWING TREAD REMAINING

SERVICE: WHEEL ALIGNMENT

DESCRIPTION: WHEEL ALIGNMENT ~|~PERFORM A 4 WHEEL ALIGNMENT DUE TO TIME AND MILEAGE ~|~ ~|~ALIGN FOUR WHEELS ALL

48301 miles

DATE: 12/2008

SERVICE: 50000 MILE SERVICE NON WARRANTY-NON OEM

DESCRIPTION: 50000 MILE SERVICE NON WARRANTY-NON OEM ~|~CUSTOMER REQUESTS 50000 MILE SERVICE =====

===== ~|~SCHEDULED MAINTENANCE DUE TO TIME OR MILEAGE
===== ~|~50,000 MILES OR 40 MONTHS AT 50000 FRONT BRAKES ARE AT 8.5 MM..REAR BRAKES ARE AT 5.0 MM..+ TIRES ARE AT 8/32..THANK YOU.ANDY AMENTA

SERVICE: AIR CONDITIONING

DESCRIPTION: AIR CONDITIONING ~|~PERFORM AN AC EVAPORATOR FLUSH
===== ~|~. ~|~TECH PERFORMED AN AC EVAPORATOR FLUSH DUE TO AN ODER COMING FROM THE AC VENTS.

SERVICE: CAR WASH

DESCRIPTION: CAR WASH ~|~CUSTOMER REQUESTS A COMPLIMENTARY CAR WASH THAT INCLUDES: WASH EXTERIOR AND CHAMOIS DRY VACUUM FLOOR MATS ~|~PERFORM COMPLIMENTARY CAR WASH ~|~COMPLIMENTARY CAR WASH PERFORMED

SERVICE: NON WARRANTABLE OPERATION CODE

DESCRIPTION: NON WARRANTABLE OPERATION CODE ~|~WE REQUEST YOU REPLENISH ALL OF THE FUEL YOU CONSUME. IN THE EVENT YOU DO NOT A \$25.00 PER QUARTER TANK CHARGE WILL BE ADDED TO YOUR INVOICE. WE REQUEST YOU RETURN THE LOANER VEHICLE WITHIN 24 HOURS OF COMPLETION OF YOUR VEHICLE. IN THE EVENT YOU DO NOT A ~|~ ~|~LOANER

SERVICE: OTHER INSPECTION

DESCRIPTION: OTHER INSPECTION ~|~REPLACE THE FRONT WIPER INSERTS
===== ~|~ ~|~TECH REPLACED THE FRONT WIPERS.OTHER INSPECTION ~|~FOR YOUR SAFETY AND CONVENIENCE, OUR LEXUS CERTIFIED TECHNICAL STAFF WILL BE PERFORMING A VISUAL COURTESY SAFETY INSPECTION OF YOUR VEHICLE WHILE IT IS HERE. YOUR SERVICE CONSULTANT WILL DISCUSS WITH YOU ANY ITEMS THAT MAY NEED ATTENTION AT THIS TIME, OR ~|~PERFORM COURTESY INSPECTION ~|~INSPECTION COMPLETED

43445 miles

DATE: 02/2008

SERVICE: 45000 MILE SERVICE NON WARRANTY

DESCRIPTION: 45000 MILE SERVICE NON WARRANTY ~|~CUSTOMER REQUESTS 45000 MILE SERVICE --- ~|~SCHEDULED MAINTENANCE DUE TO TIME OR MILEAGE --- ~|~PERFORMED SERVICE AS REQUESTED MILIMETERS OF FRONT BRAKE PAD REMAINING: 11 MILIMETERS OF REAR BRAKE PAD REMAINING: 5 1/32"" OF TRED DEPTH REMAINING ON THE FRONT TIRES: 11 1/32"" OF TRED DEPTH REMAINING ON THE REAR TIRES: 11

SERVICE: OTHERS

DESCRIPTION: OTHERS ~|~AT THE LAST SERVICE WE ADVISED THE FRONT AND REAR BRAKES HAD 5MM OF PAD REMAINING. CHECK AND ADVISE. --- ~|~FOUND THE FRONT BRAKES WITH ONLY 3MM OF PAD REMAINING --- ~|~REPLACED THE PADS, SHIMS, AND RESURFACED THE ROTORS.

SERVICE: WHEEL ALIGNMENT

DESCRIPTION: WHEEL ALIGNMENT ~|~PERFORM FOUR WHEEL ALIGNMENT WITH TIRE REPLACEMENT --- ~|~ ~|~PERFORMED ALIGNMENT

SERVICE: WHL DISC/TIRE(1 WHL)DISMOUNT

DESCRIPTION: WHL DISC/TIRE(1 WHL)DISMOUNT ~|~AT THE LAST SERVICE WE ADVISED THE TIRES MAY NEED TO BE REPLACED AT THIS SERVICE. CHECK AND ADVISE. --- ~|~FOUND ALL FOUR TIRES IN NEED OR REPLACEMENT DUE TO WEAR --- ~|~INSTALLED FOUR NEW TIRES

38279 miles

DATE: 05/2007

SERVICE: 40000 MILE SERVICE NON WARRANTY-NON OEM

DESCRIPTION: 40000 MILE SERVICE NON WARRANTY-NON OEM ~|~CUSTOMER REQUESTS 40000 MILE SERVICE ===== ~|~SERVICE COMPLETED AS REQUESTED ===== ~|~BRAKE INSPECTION REPORT FRONT BRAKES REMAINING PADS 5MM REAR BRAKE PADS REMAINING 5MM. ===== MAY NEED BRAKES NEXT SERVICE. ===== TIRES ARE AT 5/32"" BUT INSIDE EDGE WEAR IS LOW- RECOMEND REPLACEMENT SOON. =====

SERVICE: OTHERS

DESCRIPTION: OTHERS ~|~CUSTOMER REPORTS THE CHECK ENGINE LIGHT IS ON-CHECK AND ADVISE. ===== ~|~FOUND UPON INSPECTION O2 SENSOR FAILED BANK 1,SENSOR 2. RECOMEND REPLACEMENT OF SENSOR. ===== CUSTOMER REQUESTS NEW O2 SENSOR ===== ~|~SERVICE COMPLETED AS REQUESTED =====

33281 miles

DATE: 08/2006

SERVICE: 35000 MILE SERVICE NON WARRANTY-NON OEM

DESCRIPTION: 35000 MILE SERVICE NON WARRANTY-NON OEM ~|~CUSTOMER REQUESTS 35000 MILE SERVICE ~|~SCHEDULED MAINTENANCE DUE TO TIME OR MILEAGE ~|~COMPLETED 35K SERVICE BRAKES ARE 6MM FRT & REAR REMAINING TIRES ARE 6/32 FRT & REAR REMAINING

28506 miles

DATE: 09/2005

SERVICE: 30000 MILE SERVICE NON WARRANTY

DESCRIPTION: 30000 MILE SERVICE NON WARRANTY ~|~CUSTOMER REQUESTS 30000 MILE SERVICE ~|~SCHEDULED MAINTENANCE DUE TO TIME OR MILEAGE

~|~PERFORMED 30,000 MILE SERVICE BRAKE INSPECTION FRONT 7MM,REAR
7.5MM TIRE INSPECTION FRONT 6/32"" REAR 7/32""

23274 miles

DATE: 01/2005

SERVICE: 25000 MILE SERVICE NON WARRANTY-NON OEM
DESCRIPTION: 25000 MILE SERVICE NON WARRANTY-NON OEM ~|~CUSTOMER
REQUESTS 25000 MILE SERVICE ~|~SCHEDULED MAINTENANCE DUE TO TIME OR
MILEAGE ~|~PERFORMED 25000 MILE SERVICE BRAKES ARE 7MM FRONT AND
6MM REAR TIRES ARE 6/32 FRONT AND REAR

18309 miles

DATE: 08/2004

SERVICE: 20000 MILE SERVICE NON WARRANTY-NON OEM
DESCRIPTION: 20000 MILE SERVICE NON WARRANTY-NON OEM ~|~CUSTOMER
REQUESTS 20000 MILE SERVICE ~|~SCHEDULED MAINTENANCE DUE TO TIME OR
MILEAGE ~|~COMPLETED 20K SERVICE BRAKES ARE 80% FRT & REA REMAINING

14632 miles

DATE: 12/2003

SERVICE: 15000 MILE SERVICE NON WARRANTY
DESCRIPTION: 15000 MILE SERVICE NON WARRANTY ~|~CUSTOMER REQUESTS
15000 MILE SERVICE ~|~SCHEDULED MAINTENANCE DUE TO TIME OR MILEAGE
~|~15K SERVICE COMPLETED BRAKES 8MM TIRES 8/32

9948 miles

DATE: 08/2003

SERVICE:
DESCRIPTION: TIRE INSPECTION REPORT LF= 9/32IN RF= 9/32IN EDGE=OK LR=
9/32IN RR= 9/32IN EDGE=OK

SERVICE: 10,000 MILE SERVICE-GS300

DESCRIPTION: 10,000 MILE SERVICE

SERVICE: BATTERY INSP. AND SERVICE

DESCRIPTION:

SERVICE: BODY,PAINT AND CORROSION INSPECTION

DESCRIPTION:

SERVICE: BRAKE INSPECTION AND REPORT REMAINING BRAKE PAD 9MM-
FRONT- 8MM-REAR

DESCRIPTION:

SERVICE: CHECK BALL JOINTS AND DUST COVERS

DESCRIPTION:

SERVICE: DRIVE BELT VISUAL INSPECTION

DESCRIPTION:

SERVICE: ENGINE COOLING SYSTEM INSPECTION

DESCRIPTION:

SERVICE: INSPECT AIR FILTER

DESCRIPTION:

SERVICE: INSPECT EXHAUST PIPES AND MOUNTINGS

DESCRIPTION:

SERVICE: INSPECT FLUID LEVELS INSPECT BELTS INSPECT HOSES INSPECT TIRE PRESSURE

DESCRIPTION:

SERVICE: OIL AND FILTER CHANGE

DESCRIPTION:

SERVICE: ROAD TEST

DESCRIPTION:

SERVICE: STEERING GEAR BOX VISUAL CHECK

DESCRIPTION:

SERVICE: STEERING LINKAGE VISUAL CHECK

DESCRIPTION:

SERVICE: TIGHTEN SPECIFIC BODY AND CHASSIS BOLTS

DESCRIPTION:

SERVICE: TIRE INSPECTION AND ROTATION

DESCRIPTION:

4715 miles

DATE: 01/2003

SERVICE: 5,000 MILE SERVICE-GS300

DESCRIPTION: 5,000 MILE SERVICE

SERVICE: BATTERY INSP. AND SERVICE

DESCRIPTION:

SERVICE: CHECK BALL JOINTS AND DUST COVERS

DESCRIPTION:

SERVICE: DRIVE BELT VISUAL INSPECTION

DESCRIPTION:

SERVICE: INSPECT AIR FILTER

DESCRIPTION:

SERVICE: INSPECT EXHAUST PIPES AND MOUNTINGS

DESCRIPTION:

SERVICE: INSPECT FLUID LEVELS INSPECT BELTS INSPECT HOSES INSPECT TIRE PRESSURE

DESCRIPTION:

SERVICE: OIL AND FILTER CHANGE

DESCRIPTION:

SERVICE: ROAD TEST

DESCRIPTION:

SERVICE: STEERING GEAR BOX VISUAL CHECK

DESCRIPTION:

SERVICE: STEERING LINKAGE VISUAL CHECK

DESCRIPTION:

SERVICE: TIRE INSPECTION AND ROTATION

DESCRIPTION:

342 miles

DATE: 09/2002

SERVICE: 30 DAY/1000 MILE SERVICE-GS300

DESCRIPTION: 1,000 MILE SERVICE

SERVICE: BODY,PAINT AND CORROSION INSPECTION

DESCRIPTION:

SERVICE: CHECK BALL JOINTS AND DUST COVERS

DESCRIPTION:

SERVICE: DRIVE BELT VISUAL INSPECTION

DESCRIPTION:

SERVICE: INSPECT EXHAUST PIPES AND MOUNTINGS

DESCRIPTION:

SERVICE: INSPECT FLUID LEVELS INSPECT BELTS INSPECT HOSES INSPECT TIRE PRESSURE

DESCRIPTION:

SERVICE: ROAD TEST

DESCRIPTION:

SERVICE: STEERING GEAR BOX VISUAL CHECK

DESCRIPTION:

SERVICE: STEERING LINKAGE VISUAL CHECK

DESCRIPTION:

SERVICE: TIGHTEN SPECIFIC BODY AND CHASSIS BOLTS

DESCRIPTION:

4 miles

DATE: 08/2002

SERVICE:

DESCRIPTION: DETAIL DETAIL COMPLETED

SERVICE: PRE DELIVERY SERVICE

DESCRIPTION: PDI