


Position of Parts in Instrument Panel




Print

[Exit](#)

Name Meter Mirror Sub-Assembly
 Code H1
 Part Number 90980-12423
 Color White
 Spec

[\[+\]Wire Harness Repair](#)

○All terminals
 ○Select terminal
 show



Location [Instrument Panel Position of Parts](#)
 System [Audio System \(Navigation Receiver Type\)](#)
[Combination Meter](#)
[LEXUS Navigation System](#)
[Multiplex Communication System \(AVC-LAN\)](#)
[Parking Assist \(Back Guide Monitor\) \(Navigation Receiver Type\)](#)
[Parking Assist \(Rear View Monitor\) \(Navigation Receiver Type\)](#)
[Pre-Collision System](#)

© 2012 TOYOTA MOTOR CORPORATION. All Rights Reserved.