

2007 IS350

SERVICE HISTORY

SERVICE HISTORY FOR: 2007 IS350

VIN: JTHBE262372012350

153820 MILES

DATE: 04/11/2017

REPAIR# 0602607

REPORTED BY: Lexus of Austin

SERVICE: 5,000 MILE SERVICE

DESCRIPTION: 5,000 MILE SERVICE ~|~CUSTOMER REQUESTS 5000 MILE SERVICE ~|~SCHEDULED MAINTENANCE DUE TO TIME OR MILEAGE BRAKES: FRONT 6MM REAR 7MM TIRES: LF9 LR8 RF9 RR8 ~|~5000 MILE SERVICE PERFORMED CHECK OIL LEVEL INSPECT TIRE TREAD WEAR, ADJUST PRESSURES ROTATE TIRES UNLESS STAGGERED SIZES INSPECT AND ADJUST FLUIDS INSPECT BRAKE SYSTEM INSPECT WIPER BLADES CHECK INSTALLATION OF DRIVER'S FLOOR MAT RESET MAINTENANCE LIGHT

SERVICE: NON WARRANTABLE OPERATION CODE

DESCRIPTION: NON WARRANTABLE OPERATION CODE ~|~PERFORM QUALITY VEHICLE INSPECTION. ~|~ ~|~QUALITY VEHICLE INSPECTION PERFORMED.

SERVICE: OTHERS

DESCRIPTION: OTHERS ~|~GLG RECALL ~|~OPEN CAMPAIGN GLG ~|~COMPLETED OPEN CAMPAIGN GLG

149667 MILES

DATE: 12/03/2016

REPAIR# 0585688

REPORTED BY: Lexus of Austin

SERVICE: BATTERY LIGHT IS ON

DESCRIPTION: BATTERY LIGHT IS ON ~|~BATTERY LIGHT IS ON CS VEHICLE DIED WHEN DRIVING ~|~ALTERNATOR LOW CHARGING VOLTS 10.87 VOLTS ~|~R&R ALTERNATOR ASSEMBLY

SERVICE: NON WARRANTABLE OPERATION CODE

DESCRIPTION: NON WARRANTABLE OPERATION CODE ~|~PERFORM QUALITY VEHICLE INSPECTION. ~|~ ~|~QUALITY VEHICLE INSPECTION PERFORMED.

SERVICE: OTHERS

DESCRIPTION: OTHERS ~|~BATTERY INSPECTION ~|~BATTERY FAILED LOAD TEST/WILL NO LONGER HOLD CHARGE OFP 00544-MF240-575 ~|~R&R BATTERY ASSEMBLY BATTERY PREVIOUSLY REPLACED ON 8-1-15 MILES: 128453 RO#520875 OTHERS ~|~BATTERY INSPECTION ~|~BATTERY FAILED LOAD TEST/WILL NO LONGER HOLD CHARGE OFP 00544-MF240-575 ~|~R&R BATTERY ASSEMBLY BATTERY PREVIOUSLY REPLACED ON 8-1-15 MILES: 128453 RO#520875

149003 MILES

DATE: 11/21/2016

REPAIR# 0029205

REPORTED BY: Lexus of Lakeway

SERVICE: 25000 MILE SERVICE NON WARRANTY-NON OEM

DESCRIPTION: 25000 MILE SERVICE NON WARRANTY-NON
 OEM ~|~CUSTOMER REQUESTS 25000 MILE SERVICE
 ~|~SCHEDULED MAINTENANCE DUE TO TIME OR MILEAGE
 BRAKES REMAINING FRT 6MM,REAR 7MM-TREAD
 REMAINING FRT TIRES 6/32,REAR 3/32 ~|~25000 MILE SERVICE
 PERFORMED CHECK OIL LEVEL TOP OFF ALL FLUIDS
 INSPECT A/C FILTER INSPECT TIRE TREAD WEAR, ADJUST
 PRESSURES ROTATE TIRES UNLESS STAGGERED SIZES
 INSPECT BRAKE SYSTEM CHECK INSTALLATION OF DRIVER'S
 FLOOR MAT RESET MAINTENANCE REMINDER LIGHT

143500 MILES

DATE: 07/12/2016

REPAIR# 0023674

REPORTED BY: Lexus of Lakeway

SERVICE: 20000 MILE SERVICE NON WARRANTY-NON OEM
DESCRIPTION: 20000 MILE SERVICE NON WARRANTY-NON
 OEM ~|~CUSTOMER REQUESTS 20000 MILE SERVICE
 ~|~SCHEDULED MAINTENANCE DUE TO TIME OR MILEAGE
 BRAKES REMAINING FRT 8MM,REAR 7MM-TIRE TREAD
 REMAINING FRT TIRES 7/32, REAR 5/32 ~|~20000 MILE SERVICE
 PERFORMED CHANGE OIL AND FILTER TOP OFF ALL FLUIDS
 INSPECT AC FILTER INSPECT TREADWEAR, SET PRESSURES
 AND ROTATE TIRES ROAD TEST VEHICLE WASH AND
 VACUUM

138013 MILES

DATE: 03/15/2016

REPAIR# 0551110

REPORTED BY: Lexus of Austin

SERVICE: 15000 MILE SERVICE NON WARRANTY
DESCRIPTION: 15000 MILE SERVICE NON WARRANTY
 ~|~CUSTOMER REQUESTS 15000 MILE SERVICE BRAKES:
 FRONT 9MM REAR 8MM TIRES: LF10 LR9 RF10 RR9
 ~|~SCHEDULED MAINTENANCE DUE TO TIME OR MILEAGE
 ~|~15000 MILE SERVICE PERFORMED OIL AND FILTER
 CHANGE REMOVE TIRES AND INSPECT BRAKES,SET TIRE
 PRESSURES CLEAN AC FILTER INSPECT BRAKE SYSTEM
 INSPECT DRIVE SHAFT BOOTS INSPECT DIFFERENTIAL OIL
 INSPECT EXHAUST SYSTEM INSPECT STEERING LINKAGE
 INSPECT RACK AND

SERVICE: NON WARRANTABLE OPERATION CODE
DESCRIPTION: NON WARRANTABLE OPERATION CODE
 ~|~PERFORM QUALITY VEHICLE INSPECTION. ~|~
 ~|~QUALITY VEHICLE INSPECTION PERFORMED.

SERVICE: OTHERS

DESCRIPTION: OTHERS ~|~CS RF HEARDLAMP INOP
 ~|~FOUND RF HID BULB TO BE INOP ~|~REPLACED RF HID
 BULB

133351 MILES

DATE: 01/30/2016

REPAIR# 0545447

REPORTED BY: Lexus of Austin

SERVICE: CHECK NO START
DESCRIPTION: CHECK NO START ~|~CHECK NO
 START..ORIGINALLY REPLACED 08/01/2015 RO#520875 @128,454
 MILES ~|~

133253 MILES

DATE: 11/25/2015

REPAIR# 0536528**REPORTED BY:** Lexus of Austin**SERVICE:** 5,000 MILE SERVICE

DESCRIPTION: 5,000 MILE SERVICE ~|~CUSTOMER REQUESTS 5000 MILE SERVICE ~|~SCHEDULED MAINTENANCE DUE TO TIME OR MILEAGE BRAKES: FRONT NEW REAR 5MM TIRES: LF8 LR2 RF5 RR2 ~|~5000 MILE SERVICE PERFORMED CHANGE OIL AND FILTER TOP OFF ALL FLUIDS INSPECT TIRES AND ADJUST PRESSURES ROAD TEST VEHICLE WASH AND VACUUM INSPECT BRAKE PADS/CALIPERS/ROTORS

SERVICE: OTHERS

DESCRIPTION: OTHERS ~|~GUEST REPORTS HER DASH AND DOOR PANNELS ARE STICKEY- INSPECT ~|~ ~|~PARTS ON ORDER

SERVICE: BRAKES

DESCRIPTION: BRAKES ~|~BRAKE INSPECTION ~|~FRONT BRAKES WORN ~|~REPLACED FRONT BRAKE PADS AND SHIMS. RESURFACED FRONT ROTORS

128454 MILES

DATE: 08/01/2015

REPAIR# 0520875**REPORTED BY:** Lexus of Austin**SERVICE:** OTHERS

DESCRIPTION: OTHERS ~|~CUST STATES VEHICLE WILL NOT START TODAY-TAKES A JUMP START (LAST REPL 9/23/13 RO#423309 99,192 MILES) 100% WARRANTY ~|~BATTERY FAILED LOAD TEST, BAD CELL WARRANTY CODE AUMR-WOECX-V6RT0 ~|~R&R BATTERY FAIL CODE 00544-MF240-575

128062 MILES

DATE: 07/23/2015

REPAIR# 0519563**REPORTED BY:** Lexus of Austin**SERVICE:** 25000 MILE SERVICE NON WARRANTY-NON OEM

DESCRIPTION: 25000 MILE SERVICE NON WARRANTY-NON OEM ~|~CUSTOMER REQUESTS 25000 MILE SERVICE ~|~SCHEDULED MAINTENANCE DUE TO TIME OR MILEAGE BRAKES: FRONT 5MM REAR NEW TIRES: LF9 LR4 RF6 RR4 ~|~25000 MILE SERVICE PERFORMED CHANGE OIL AND FILTER TOP OFF ALL FLUIDS REMOVE TIRES AND INSPECT BRAKES,SET TIRE PRESSURES ROAD TEST VEHICLE WASH AND VACUUM RESET MAINTENANCE REMINDER LIGHT

SERVICE: BRAKES

DESCRIPTION: BRAKES ~|~BRAKE INSPECTION ~|~FOUND REAR BRAKES AT 3MM AND ROTORS UNDER SPECS ~|~REPLACED REAR BRAKE PADS AND REAR ROTORS

122799 MILES

DATE: 03/16/2015

REPAIR# 0501018**REPORTED BY:** Lexus of Austin**SERVICE:** 120,000 MILE SERVICE**SERVICE:** 1YR ST I W/ EMISSION

DESCRIPTION: 120,000 MILE SERVICE ~|~CUSTOMER REQUESTS 120000 MILE SERVICE BRAAKES; FRONT 4MM REAR 4MM TIRES: LF8 LR6 RF7 RR6 ~|~SCHEDULED MAINTENANCE DUE TO TIME OR MILEAGE ~|~120000 MILE SERVICE PERFORMED CHANGE OIL AND FILTER REPLACE BRAKE FLUID REPLACE AIR FILTER INSPECT ENGINE COOLANT REMOVE TIRES AND INSPECT BRAKES,SET PRESSURES INSPECT BALL JOINTS AND DUST COVERS INSPECT BODY INSPECT BRAKE SYSTEM INSPECT DRIVE SHAFT BOOTS

SERVICE: OTHERS

DESCRIPTION: OTHERS ~|~OPEN CAMPAIGN ELF POTENTIAL FUEL PRESSURE SENSOR LEAK ~|~ ~|~COMPLETED RECALL AS PER LEXUS INSTRUCTION

DESCRIPTION: 1YR ST I W/ EMISSION ~|~STATE INSPECTION WITH EMISSION TEST ~|~REQUIRED BY STATE OF TEXAS AND COUNTY ~|~COMPLETED STATE INSPECT WITH EMISSION TEST

117409 MILES

DATE: 10/17/2014

REPAIR# 0479338

REPORTED BY: Lexus of Austin

SERVICE: 25000 MILE SERVICE NON WARRANTY-NON OEM

DESCRIPTION: 25000 MILE SERVICE NON WARRANTY-NON OEM ~|~115000 MILE SERVICE BRAKES: FRONT 6MM REAR 5MM ~|~SCHEDULED MAINTENANCE DUE TO TIME OR MILEAGE TIRES: LF9 LR8 RF9 RR8 ~|~115000 MILE SERVICE CHANGE OIL AND FILTER TOP OFF ALL FLUIDS REMOVE TIRES AND INSPECT BRAKES,SET PRESSURES ROAD TEST VEHICLE WASH AND VACUUM

SERVICE: LOWER BALL JOINT ASSY 1-SD

DESCRIPTION: LOWER BALL JOINT ASSY 1-SD ~|~INSPECT FORNT BALL LOWER BALL JOINTS ~|~BALL JOINTS LEAKING ~|~REPLACED BOTH FRONT LOWER BALL JOINTS FOR LEAKING.

SERVICE: AUTO DETAILING

DESCRIPTION: AUTO DETAILING ~|~GUEST REPORTS WHEN TRAVELING OVER DIPS, BUMPS THERE IS A THUMPING NOISE FROM THE REAR OF THE VEHICLE. CS SHE IS UNSURE IF IT IS DUE TO ALL THE STUFF SHE HAS IN THE REAR OF THE VEHICLE ~|~LR STRUT BLOWN OUT, RR STRUT LEAKING ~|~REPLACED BOTH REAR STRUTS FOR LEAKING

SERVICE: NON WARRANTABLE OPERATION CODE

DESCRIPTION: NON WARRANTABLE OPERATION CODE ~|~THROTTLE BODY DIRTY ~|~CARBON BUILD UP ~|~COMPLETED THROTTLE BODY SERVICE FOR CARBON BUILDUP THROUGHOUT CHAMBER

112729 MILES

DATE: 06/20/2014

REPAIR# 0462134

REPORTED BY: Lexus of Austin

SERVICE: INTERIOR DETAIL

DESCRIPTION: INTERIOR DETAIL ~|~INTERIOR DETAIL ~|~ ~|~COMPLETE

SERVICE: SI W/ EMISSIONS TEST

DESCRIPTION: SI W/ EMISSIONS TEST ~|~STATE INSPECTION WITH EMISSION TEST ~|~REQUIRED BY STATE OF TEXAS AND COUNTY ~|~COMPLETED STATE INSPECTION WITH EMISSION TEST

SERVICE: NON WARRANTABLE OPERATION CODE

DESCRIPTION: NON WARRANTABLE OPERATION CODE ~|~CUSTOMER REQUESTS FOUR WHEEL ALIGNMENT ~|~ ~|~COMPLETED FOUR WHEEL ALIGNMENT

112039 MILES

DATE: 06/18/2014

REPAIR# 0461601

REPORTED BY: Lexus of Austin

SERVICE: 25000 MILE SERVICE NON WARRANTY-NON OEM

SERVICE: SI W/ EMISSIONS TEST

DESCRIPTION: 25000 MILE SERVICE NON WARRANTY-NON OEM ~|~110000 MILE SERVICE BRAKES: FRONT 6MM REAR 5MM ~|~SCHEDULED MAINTENANCE DUE TO TIME OR MILEAGE TIRES: WORN ON INNER EDGES (REQ REPLACEMENT ASAP) ~|~110000 MILE SERVICE CHANGE OIL AND FILTER TOP OFF ALL FLUIDS REMOVE TIRES AND INSPECT BRAKES,SET PRESSURES ROAD TEST VEHICLE WASH AND VACUUM

DESCRIPTION: SI W/ EMISSIONS TEST ~|~STATE INSPECTION WITH EMISSION TEST ~|~UNABLE TO PASS SI DUE TO CONDITION OF TIRES ~|~GUEST DECLINES TIRES

107759 MILES

DATE: 03/04/2014

REPAIR# 0446400**REPORTED BY:** Lexus of Austin**SERVICE:** 15000 MILE SERVICE NON WARRANTY

DESCRIPTION: 15000 MILE SERVICE NON WARRANTY ~|~105000 MILE SERVICE ~|~SCHEDULED MAINTENANCE DUE TO TIME OR MILEAGE BRAKES: FRONT 8MM REAR 6MM TIRES: LF5 LR3 RF5 RR3 ~|~105000 MILE SERVICE OIL AND FILTER CHANGE REMOVE TIRES AND INSPECT BRAKES,SET TIRE PRESSURES INSPECT BODY INSPECT BRAKE SYSTEM INSPECT DRIVE SHAFT BOOTS INSPECT DIFFERENTIAL OIL INSPECT EXHAUST SYSTEM INSPECT STEERING LINKAGE INSPECT RACK AND PINION FOR L

SERVICE: AUTO DETAILING

DESCRIPTION: AUTO DETAILING ~|~GUEST REPORTS WHEN SHE IS PARKED ON AN INCLINE AND TURNS TO THE LEFT OR RIGHT WHEN BACKING DOWN THERE IS A ERRONIOUS NOISE AND FEELING. SEE HISTORY CS SHE ALSO HEARS NOISE WHEN BACKING OUT OF PARKING SPOTS AND TURNING. ~|~COULD NOT DUPLICATE ANY ABNORMAL NOISE AT THIS TIME. ONLY NOISE HEARD IS FROM FRONT TIRES WHILE TURNED TO LOCK POSITIO LEFT OR RIGHT WHILE BACKING UP OR GOING FORWARD WHICH IS NORMAL. ~|~NO PROBLEM FOUND WITH VEHICLE AT THIS TIME

102688 MILES

DATE: 11/20/2013

REPAIR# 0431769**REPORTED BY:** Lexus of Austin**SERVICE:** 25000 MILE SERVICE NON WARRANTY-NON OEM

DESCRIPTION: 25000 MILE SERVICE NON WARRANTY-NON OEM ~|~100000 MILE SERVICE ~|~SCHEDULED MAINTENANCE DUE TO TIME OR MILEAGE BRAKES: FRONT 9MM REAR 6MM TIRES: LF6 LR4 RF6 RR4 ~|~100000 MILE SERVICE CHANGE OIL AND FILTER TOP OFF ALL FLUIDS REMOVE TIRES AND INSPECT BRAKES,SET PRESSURES ROAD TEST VEHICLE WASH AND VACUUM REPLACE ENGINE COOLANT

SERVICE: OTHER INSPECTION

DESCRIPTION: OTHER INSPECTION ~|~CS SHE WAS BUMPED FROM BEHIND ON THE WAY IN TO DEALER CS CHECK FOR DAMAGE TO REAR ~|~REAR CAMERA IS INTERMITTANTLY INOP ~|~EST. GIVEN GUEST DECLINES REPAIR AT THIS TIME/

SERVICE: OTHERS

DESCRIPTION: OTHERS ~|~CS SHE RAN OVER A DEER IN THE ROAD AND THINKS THERE IS POSSIBLE A PULL. ADVISE ~|~VEHICLE HAS SLIGHT DRIFT TO RIGHT ~|~COMPLETED ALIGNMENT

SERVICE: VVT GEAR UPDATE

DESCRIPTION: VVT GEAR UPDATE ~|~SSC DLG INTAKE VVT ACTUATOR GEAR UPDATE ~|~PER SSC ~|~COMPLETED SSC DLG VVT GEAR UPDATE

100778 MILES

DATE: 10/22/2013

REPAIR# 0427603**REPORTED BY:** Lexus of Austin**SERVICE:** LOW TIRE LIGHT

DESCRIPTION: LOW TIRE LIGHT ~|~CHECK LOW TIRE PRESSURE LIGHT IS ON CS THAT LOW TIRE LIGHT IS FLASHING ~|~TPMS SENSOR ID4 INOP ~|~INSTALLED NEW SENSOR ID4 IN LEFT FRONT TIRES AND REG. ALL SENSORS

AND SET THRESH HOLD-VEHICLE WORKING AS DESIGNED AT THIS TIME.

99192 MILES

DATE: 09/23/2013

REPAIR# 0423309

REPORTED BY: Lexus of Austin

SERVICE: CHECK NO START CHECK NO START

DESCRIPTION: CHECK NO START ~|~CHECK NO START CS
HER VSC LIGHT WAS ON AFTER VEHICLE WOULD NOT START, CS NOW IS OFF. BATTERY PREVIOUSLY REPLACED ON 10-3-11 RO#324783 MILES: 65925 ~|~BAD CELL IN BATTERY ~|~REPLACED BATTERY

96470 MILES

DATE: 07/31/2013

REPAIR# 0415564

REPORTED BY: Lexus of Austin

SERVICE: 25000 MILE SERVICE NON WARRANTY-NON OEM

DESCRIPTION: 25000 MILE SERVICE NON WARRANTY-NON OEM ~|~95000 MILE SERVICE BRAKES: FRONT 10MM REAR 7MM ~|~SCHEDULED MAINTENANCE DUE TO TIME OR MILEAGE TIRES: LF7 LR6 RF7 RR6 ~|~95000 MILE SERVICE CHANGE OIL AND FILTER TOP OFF ALL FLUIDS REMOVE TIRES AND INSPECT BRAKES,SET PRESSURES ROAD TEST VEHICLE WASH AND VACUUM

93779 MILES

DATE: 05/23/2013

REPAIR# 0405768

REPORTED BY: Lexus of Austin

SERVICE: BRAKES SQUEAKING

DESCRIPTION: BRAKES SQUEAKING ~|~GUEST REPORTS SQUEEKING FROM BRAKES UNDER SLOW SPEED BRAKING AS WHEN DRIVING THROUGH A PARKING GARAGE OR PARKING LOT ~|~NOISE COMING FROM FRONT BRAKE ROTORS AND SHIMMS ~|~REPLACED FRONT BRAKE PADS, SHIMS, AND ROTORS AS REQUESTED

SERVICE: SI W/ EMISSIONS TEST

DESCRIPTION: SI W/ EMISSIONS TEST ~|~STATE INSPECTION WITH EMISSION TEST ~|~REQUIRED BY STATE OF TEXAS AND COUNTY ~|~COMPLETED STATE INSPECTION WITH EMISSION TEST

89555 MILES

DATE: 03/08/2013

REPAIR# 0395678

REPORTED BY: Lexus of Austin

SERVICE: 90000 MILE SERVICE NON WARRANTY-NON OEM

DESCRIPTION: 90000 MILE SERVICE NON WARRANTY-NON OEM ~|~CUSTOMER REQUESTS 90000 MILE SERVICE BRAKES: FRONT 7MM REAR 8MM ~|~SCHEDULED MAINTENANCE DUE TO TIME OR MILEAGE TIRES: 8/32 PER ~|~90000 MILE SERVICE PERFORMED CHANGE OIL AND FILTER REPLACE BRAKE FLUID REPLACE AIR FILTER INSPECT ENGINE COOLANT REMOVE TIRES AND INSPECT BRAKES,SET

SERVICE: UPDATE TRUNK RELEASE

DESCRIPTION: UPDATE TRUNK RELEASE ~|~CUSTOMER REQUESTS TRUNK RELEASE LEVER UPDATE ~|~UPDATED TRUNK RELEASE LEVER ~|~REPLACED TRUNK RELEASE LEVER WITH UPDATED COMPONENT

PRESSURES INSPECT BALL JOINTS AND DUST COVERS
INSPECT BODY INSPECT BRAKE SYSTEM INSPECT DRIVE
SHAFT BOOTS

SERVICE: WIPER ARM CAMPAIGN

DESCRIPTION: WIPER ARM CAMPAIGN ~|~CUSTOMER
REQUESTS SSC DLA WIPER ARM CAMPAIGN ~|~FRONT
WIPER ARM CAMPAIGN UPDATE ~|~INSPECT FRONT WIPER
ARMS. REPLACE AND RETORQUE WIPER ARM NUTS

85286 MILES

DATE: 11/26/2012

REPAIR# 0381793

REPORTED BY: Lexus of Austin

SERVICE: OTHERS

DESCRIPTION: OTHERS ~|~RF HEADLAMP BULB INOP
(GUEST RECEIVED WARNING) ~|~R/F LOW BEAM BULB IS
INOP ~|~R&R R/F LOW BEAM BULB ALL OTHER LIGHTS ARE
OPEARATING AS DESIGNED AT THIS TIME

83409 MILES

DATE: 10/19/2012

REPAIR# 0376649

REPORTED BY: Lexus of Austin

SERVICE: 25000 MILE SERVICE NON WARRANTY-NON OEM

DESCRIPTION: 25000 MILE SERVICE NON WARRANTY-NON
OEM ~|~85000 MILE SERVICE ~|~SCHEDULED MAINTENANCE
DUE TO TIME OR MILEAGE BRAKES: FRONT AND REAR 8MM
TIRES: LF1 LR6 RF0 RR6 ~|~85000 MILE SERVICE CHANGE OIL
AND FILTER TOP OFF ALL FLUIDS REMOVE TIRES AND
INSPECT BRAKES,SET PRESSURES ROAD TEST VEHICLE WASH
AND VACUUM

77273 MILES

DATE: 05/15/2012

REPAIR# 0355073

REPORTED BY: Lexus of Austin

SERVICE: 15000 MILE SERVICE NON WARRANTY

DESCRIPTION: 15000 MILE SERVICE NON WARRANTY
~|~75000 MILE SERVICE BRAKES: FRONT 10MM REAR 9MM
~|~SCHEDULED MAINTENANCE DUE TO TIME OR MILEAGE
TIRES: LF6 LR7 RF6 RR7 ~|~75000 MILE SERVICE OIL AND
FILTER CHANGE REMOVE TIRES AND INSPECT BRAKES,SET
TIRE PRESSURES REPLACE AC FILTER INSPECT BRAKE
SYSTEM INSPECT DRIVE SHAFT BOOTS INSPECT
DIFFERENTIAL OIL INSPECT EXHAUST SYSTEM INSPECT
STEERING LINKAGE INSPECT RACK AND PINION F

SERVICE: SI W/ EMISSIONS TEST

DESCRIPTION: SI W/ EMISSIONS TEST ~|~STATE
INSPECTION WITH EMISSION TEST ~|~REQUIRED BY STATE
OF TEXAS AND COUNTY ~|~COMPLETED STATE INSPECTION
WITH EMISSION TEST

71461 MILES

DATE: 01/23/2012

REPAIR# 0340025

REPORTED BY: Lexus of Austin

SERVICE: 25000 MILE SERVICE NON WARRANTY-NON OEM
DESCRIPTION: 25000 MILE SERVICE NON WARRANTY-NON OEM ~|~70000 MILE SERVICE BRAKES ARE NOW NEW FRONT TIRES HAVE 7/32, RIGHT REAR HAS 5/32 ----DRIVER'S SIDE REAR TIRE HAS A BUBBLE IN SIDEWALL---- ~|~SCHEDULED MAINTENANCE DUE TO TIME OR MILEAGE ~|~70000 MILE SERVICE CHANGE OIL AND FILTER TOP OFF ALL FLUIDS REMOVE TIRES AND INSPECT BRAKES,SET PRESSURES ROAD TEST VEHICLE WASH AND VACUUM

SERVICE: BRAKES
DESCRIPTION: BRAKES ~|~ ~|~ ~|~REPLACED FRONT AND REAR BRAKE PADS AND TURNED ALL 4 ROTORS

65925 MILES

DATE: 10/03/2011

REPAIR# 0324783
REPORTED BY: Lexus of Austin

SERVICE: 25000 MILE SERVICE NON WARRANTY-NON OEM
DESCRIPTION: 25000 MILE SERVICE NON WARRANTY-NON OEM ~|~65000 MILE SERVICE FRONT BRAKES HAVE 4MM AND REAR HAVE 3MM PAD REMAINING FRONT TIRES HAVE 8/32, REAR HAVE 7/32 TREAD DEPTH REMAINING ~|~SCHEDULED MAINTENANCE DUE TO TIME OR MILEAGE ~|~65000 MILE SERVICE CHANGE OIL AND FILTER TOP OFF ALL FLUIDS REMOVE TIRES AND INSPECT BRAKES,SET PRESSURES ROAD TEST VEHICLE WASH AND VACUUM

SERVICE: DISTRIBUTOR/HDLIGHT/T. SGNL
DESCRIPTION: DISTRIBUTOR/HDLIGHT/T. SGNL ~|~DRIVER'S SIDE HEADLAMP WILL CUT OFF (VEHICLE HAS HAD REPAIRS IN FRONT) --OK TO REPLACE BULB IF NEEDED ~|~ ~|~REPLACED L/F LOW BEAM BULB

SERVICE: OTHERS
DESCRIPTION: OTHERS ~|~CAR HAS TO BE JUMP STARTED AT TIMES --OK TO REPLACE BATTERY IF NEEDED ~|~ ~|~TESTED & REPLACED BATTERY

60274 MILES

DATE: 06/20/2011

REPAIR# 0311016
REPORTED BY: Lexus of Austin

SERVICE: 60000 MILE SERVICE NON WARRANTY
DESCRIPTION: 60000 MILE SERVICE NON WARRANTY ~|~CUSTOMER REQUESTS 60000 MILE SERVICE FRONT BRAKES HAVE 6MM AND REAR HAVE 4MM PAD REMAINING FRONT TIRES HAVE 8/32, REAR HAVE 7/32 TREAD DEPTH REMAINING ~|~SCHEDULED MAINTENANCE DUE TO TIME OR MILEAGE ~|~60000 MILE SERVICE PERFORMED CHANGE OIL AND FILTER REPLACE BRAKE FLUID REPLACE AIR FILTER INSPECT ENGINE COOLANT REMOVE TIRES AND INSPECT BRAKES,SET PRESSURES INSPECT BALL JOINTS AND DUST COVERS INSPECT BODY INSPECT BRAKE SYSTEM INSPECT DRIVE SHAFT BOOTS

57508 MILES

DATE: 04/18/2011

REPAIR# 0302657
REPORTED BY: Lexus of Austin

SERVICE: SI W/ EMISSIONS TEST
DESCRIPTION: SI W/ EMISSIONS TEST ~|~STATE INSPECTION WITH EMISSION TEST ~|~REQUIRED BY STATE

OF TEXAS AND COUNTY ~|~COMPLETED STATE INSPECTION
WITH EMISSION TEST A00522987

54574 MILES

DATE: 03/01/2011

REPAIR# 0295866

REPORTED BY: Lexus of Austin

SERVICE: 25000 MILE SERVICE NON WARRANTY-NON OEM
DESCRIPTION: 25000 MILE SERVICE NON WARRANTY-NON OEM ~|~50000 MILE SERVICE FRONT BRAKES HAVE 8MM AND REAR HAVE 5MM PAD REMAINING FRONT TIRES HAVE 10/32, REAR HAVE 9/32 TREAD DEPTH REMAINING ~|~SCHEDULED MAINTENANCE DUE TO TIME OR MILEAGE ~|~50000 MILE SERVICE CHANGE OIL AND FILTER TOP OFF ALL FLUIDS REMOVE TIRES AND INSPECT BRAKES,SET PRESSURES ROAD TEST VEHICLE WASH AND VACUUM

SERVICE: NON WARRANTABLE OPERATION CODE
DESCRIPTION: NON WARRANTABLE OPERATION CODE ~|~CUSTOMER REQUESTS FOUR WHEEL ALIGNMENT ~|~ ~|~COMPLETED FOUR WHEEL ALIGNMENT

SERVICE: OTHERS

DESCRIPTION: OTHERS ~|~ENGINE REVS HIGH/CLATTERS LOUD ON START UP ~|~OIL DRAIN OFF FROM VVTI INTAKE CAM GEARS CAUSING DRY START ~|~REPLACED B1 AND B2 INTAKE CAM GEARS PER L-SB-0156-08 OFF(13050-31162)

SERVICE: SPECIAL SERVICE CAMPAIGN
DESCRIPTION: SPECIAL SERVICE CAMPAIGN ~|~SSC BLA FUEL PRESSURE SENSOR ~|~ ~|~INSPECTED AND TORQUED FUEL PRESSURE SENSOR PER SSC BLA

49698 MILES

DATE: 11/11/2010

REPAIR# 0281978

REPORTED BY: Lexus of Austin

SERVICE: 25000 MILE SERVICE NON WARRANTY-NON OEM
DESCRIPTION: 25000 MILE SERVICE NON WARRANTY-NON OEM ~|~50000 MILE SERVICE FRONT BRAKES HAVE 9MM AND REAR HAVE 5MM PAD REMAINING ----TIRES HAVE 4/32, BUT THINNER ON INNER EDGES--- -----RECOMMENDED TIRE REPLACEMENT----- ~|~SCHEDULED MAINTENANCE DUE TO TIME OR MILEAGE ~|~50000 MILE SERVICE CHANGE OIL AND FILTER TOP OFF ALL FLUIDS REMOVE TIRES AND INSPECT BRAKES,SET PRESSURES ROAD TEST VEHICLE WASH AND VACUUM

47344 MILES

DATE: 09/20/2010

REPAIR# 0274453

REPORTED BY: Lexus of Austin

SERVICE: SPECIAL SERVICE CAMPAIGN
DESCRIPTION: SPECIAL SERVICE CAMPAIGN ~|~SSC ALE VALVE SPRING UPDATE ~|~ ~|~REPLACED VALVE SPRINGS AND LIFTERS

44508 MILES

DATE: 08/04/2010

REPAIR# 0269097

REPORTED BY: Lexus of Austin

SERVICE: 15000 MILE SERVICE NON WARRANTY
DESCRIPTION: 15000 MILE SERVICE NON WARRANTY
 ~|~45000 MILE SERVICE FRONT BRAKES ARE NOW NEW, REAR BRAKES HAVE 4MM PAD REMAINING FRONT TIRES HAVE 5 AND 7/32 TREAD DEPTH REMAINING, REAR TIRES HAVE 3 AND 5/32 TREAD DEPTH REMAINING ~|~SCHEDULED MAINTENANCE DUE TO TIME OR MILEAGE ~|~45000 MILE SERVICE OIL AND FILTER CHANGE REMOVE TIRES AND INSPECT BRAKES,SET TIRE PRESSURES REPLACE AC FILTER INSPECT BRAKE SYSTEM INSPECT DRIVE SHAFT BOOTS INSPECT DIFFERENTIAL OIL INSPECT EXHAUST SYSTEM INSPECT STEERING LINKAGE INSPECT RACK AND PINION F

SERVICE: BRAKES
DESCRIPTION: BRAKES ~|~~|~FRONT PADS ARE WORN
 ~|~REPLACED FRONT PADS & ROTORS

38773 MILES

DATE: 04/14/2010

REPAIR# 0254663
REPORTED BY: Lexus of Austin

SERVICE: 25000 MILE SERVICE NON WARRANTY-NON OEM
DESCRIPTION: 25000 MILE SERVICE NON WARRANTY-NON OEM ~|~40000 MILE SERVICE BRAKES HAVE 5MM PAD REMAINING FRONT TIRES HAVE 6/32, REAR HAVE 4 AND 6/32 TREAD DEPTH REMAINING ~|~SCHEDULED MAINTENANCE DUE TO TIME OR MILEAGE ~|~40000 MILE SERVICE CHANGE OIL AND FILTER TOP OFF ALL FLUIDS REMOVE TIRES AND INSPECT BRAKES,SET PRESSURES ROAD TEST VEHICLE WASH AND VACUUM

SERVICE: NON WARRANTABLE OPERATION CODE
DESCRIPTION: NON WARRANTABLE OPERATION CODE
 ~|~REPLACE KEY BATTERY -----COMPLETED ON DRIVE-----

SERVICE: OTHERS
DESCRIPTION: OTHERS ~|~~|~CAMPAIGN 9LG IS OPEN
 ~|~REPLACED ACCELERATOR PEDAL PAD & REPROGRAMMED ECU PER CAMPAIGN 9LG

SERVICE: SI W/ EMISSIONS TEST
DESCRIPTION: SI W/ EMISSIONS TEST ~|~STATE INSPECTION WITH EMISSION TEST ~|~REQUIRED BY STATE OF TEXAS AND COUNTY ~|~COMPLETED STATE INSPECTION WITH EMISSION TEST B03419584

33544 MILES

DATE: 12/09/2009

REPAIR# 0238209
REPORTED BY: Lexus of Austin

SERVICE: 25000 MILE SERVICE NON WARRANTY-NON OEM
DESCRIPTION: 25000 MILE SERVICE NON WARRANTY-NON OEM ~|~35000 MILE SERVICE BRAKES HAVE 6MM PAD REMAINING FRONT TIRES HAVE 8-9/32, REAR HAVE 8 AND 8/32 TREAD DEPTH REMAINING ~|~SCHEDULED MAINTENANCE DUE TO TIME OR MILEAGE ~|~35000 MILE SERVICE CHANGE OIL AND FILTER TOP OFF ALL FLUIDS REMOVE TIRES AND INSPECT BRAKES,SET PRESSURES ROAD TEST VEHICLE WASH AND VACUUM

SERVICE: AUTO DETAILING
DESCRIPTION: AUTO DETAILING ~|~PASS FT TIRE LOOSING AIR ~|~LEFT REAR TIRE HAS A NAIL IN MIDDLE OF THREAD. ~|~PATCHED TIRE + BALANCED.

311717 MILES

DATE: 10/28/2009

REPAIR# 0232938
REPORTED BY: Lexus of Austin

SERVICE: CODE
DESCRIPTION:

SERVICE: INSTALL NAV UPDATE
DESCRIPTION: INSTALL NAV UPDATE ~|~INSTALL NAVIGATION UPDATE DISC ~|~~|~COMPLETED

SERVICE: NON WARRANTABLE OPERATION CODE

SERVICE: NON WARRANTABLE OPERATION CODE

SERVICE: NON WARRANTABLE OPERATION

DESCRIPTION:

SERVICE: NON WARRANTABLE OPERATION CODE

DESCRIPTION: NON WARRANTABLE OPERATION CODE

~|~CK ENGINE VSC AND TRAC LIGHTS ARE ON ~|~P2195 OXYGEN (A/F) SENSOR SIGNAL STUCK LEAN (BANK 1 SENSOR 1) P# 89467-30010 ~|~CONNECTED TECHSTREAM & OBSERVED SENSOR OPERATION. REPLACED BANK 1 SENSOR 1, CLEARED CODE, & TEST DROVE ACCORDING TO REPAIR MANUAL DRIVE PATTERN.

28189 MILES

DATE: 08/03/2009

REPAIR# 0222012

REPORTED BY: Lexus of Austin

SERVICE: 30000 MILE SERVICE NON WARRANTY

DESCRIPTION: 30000 MILE SERVICE NON WARRANTY ~|~CUSTOMER REQUESTS 30000 MILE SERVICE FRONT BRAKES HAVE 8MM AND REAR HAVE 6MM PAD REMAINING REAR TIRES HAVE 5 AND 9/32, 1 FRONT TIRE IS NOW NEW AND 1 HAS 8/32 TREAD DEPTH REMAINING ~|~SCHEDULED MAINTENANCE DUE TO TIME OR MILEAGE ~|~30000 MILE SERVICE PERFORMED CHANGE OIL AND FILTER REPLACE BRAKE FLUID REPLACE AIR FILTER INSPECT ENGINE COOLANT REMOVE TIRES AND INSPECT BRAKES,SET PRESSURES INSPECT BALL JOINTS AND DUST COVERS INSPECT BODY INSPECT BRAKE SYSTEM INSPECT DRIVE SHAFT BOOTS

SERVICE: FLAT TIRE

DESCRIPTION: FLAT TIRE ~|~CHECK FLAT TIRE ---PATCH IF NEEDED ~|~TIRE HAD A CUT IN IT--NON-REPAIRABLE ~|~REPLACED TIRE

SERVICE: REARVIEW MIRROR

DESCRIPTION: REARVIEW MIRROR ~|~CK REAR VIEW MIRROR IS LOOSE/VIBRATES WHILE DRIVING ---SEE HISTORY --SEE PAUL ~|~EXCESSIVE FREPLAY, UPDATED TSIB# L-SB=0072-09 CONCERNS ~|~R&R RER VIEW MIRROR & WIRE HARNESS 87810-53120 62 43

25388 MILES

DATE: 06/17/2009

REPAIR# 0216069

REPORTED BY: Lexus of Austin

SERVICE: LOW TIRE LIGHT

DESCRIPTION: LOW TIRE LIGHT ~|~NAIL IN OUTER EDGE OF RT REAR TIRE- TIRE LIGHT HAS NOT COME ON YET ~|~NAIL IN SIDEWALL OF R/R TIRE NOT REPAIRABLE ~|~R&R R/R TIRE WITH BALANCE

22641 MILES

DATE: 04/29/2009

REPAIR# 0209959

REPORTED BY: Lexus of Austin

SERVICE: 25000 MILE SERVICE NON WARRANTY-NON OEM

DESCRIPTION: 25000 MILE SERVICE NON WARRANTY-NON OEM ~|~CUSTOMER REQUESTS 25000 MILE SERVICE FRONT BRAKES HAVE 10MM AND REAR HAVE 7MM PAD REMAINING FRONT TIRES HAVE 9/32, REAR HAVE 5/32 TREAD DEPTH REMAINING ~|~SCHEDULED MAINTENANCE DUE TO TIME OR MILEAGE ~|~25000 MILE SERVICE PERFORMED CHANGE OIL AND FILTER TOP OFF ALL FLUIDS

SERVICE: ACCESSORY

DESCRIPTION: ACCESSORY ~|~INSTALL PASSPORT RADAR DETECTOR SYSTEM PARTS TAGGED--SEE MARTY ---ATTN BRIAN #1281 ~|~ ~|~INSTALLED WITH PRIDE OPTIONAL CONCEALED INSTALLATION COMPLETED ALSO

REMOVE TIRES AND INSPECT BRAKES,SET TIRE PRESSURES
ROAD TEST VEHICLE WASH AND VACUUM

SERVICE: FRONT/REAR BODY

DESCRIPTION: FRONT/REAR BODY ~|~CK INTERRIOR REAR
VIEW MIRROR VIBRATES WHILE DRIVING ~|~INNER REAR
VIEW MIRROR LOOSENING, FALLING OFF DUE TO EXCESSIVE
CLEARANCE OR BACK LASH ~|~R&R INNER REAR VIEW
MIRROR OFP:87810-53120

20212 MILES

DATE: 02/21/2009

REPAIR# 1476317

REPORTED BY: Sewell Lexus

SERVICE: 9LA REPLACE FUEL DELIVERY PIPES FOR IS250/350

DESCRIPTION: 9LA REPLACE FUEL DELIVERY PIPES FOR
IS250/350 ~|~9LA ~|~PERFORMED 9LA CAMPAIGN ~|~20212
8506FJ 330 COMPLETED

TERMS AND CONDITIONS

INFORMATION ACCURACY

Information presented on this website is summarized and standardized from repair orders completed at the time of service and submitted by Lexus dealers. When reviewing a vehicle's service history, please note that all information is provided by the Lexus Dealer that conducted the service, and that dealer is solely responsible for the accuracy, completeness or authenticity of any information contained in this site. Lexus provides this site and all information and materials contained herein ?as is? without warranty of any kind. Any questions or concerns regarding this information should be addressed to the applicable Lexus dealer.

L/CERTIFIED OWNER INFORMATION

Dealer-reported service history records are linked to a vehicle's Vehicle Identification Number (VIN). All owner-reported service history records will be made available to the person who input the information on the site, but will not be shared with future owners of the vehicle.

OWNER-REPORTED INFORMATION AND PRIVACY TERMS

Lexus makes every effort to ensure the secure collection and transmission of sensitive user information using industry-accepted data collection and encryption methodologies. The information you provide is used by Lexus and its vendors and dealers to help improve the services we render. It is occasionally provided to Lexus dealers for their marketing use. Lexus will never sell your personally identifiable information to any other company. To learn more about our privacy policies and practices with respect to this website, please [click here](http://www.lexus.com/privacy/online-statement) (//www.lexus.com/privacy/online-statement).