

430 IN FL

SERVICE HISTORY**SERVICE HISTORY FOR:** 430 IN FL**VIN:** JTHBN36F655005364

38330 MILES**DATE:** 11/04/2016**REPAIR#** 0540316**REPORTED BY:** Lexus of West Kendall**SERVICE:** INSPECT BATTERY CHARGE LEVEL**DESCRIPTION:** INSPECT BATTERY CHARGE LEVEL ~I~CUIST STATES ENGINE NO CRANK AND VEH MAKING CLICKING NOISE SEE HISTORY FOR PRORATION ~I~PERFORM TEST, TEST SHOWS BATTERY NEEDS TO BE CHARGED AND RETESTED ~I~PERFORM BATTERY CHARGE WITH GR8 AFTER CHARGE AND RETEST TEST SHOWS GOOD BATTERY CUST ELECTED TO HAVE BATTERY REPLACED ANYWAYS

35860 MILES**DATE:** 01/12/2016**REPAIR#** 0824403**REPORTED BY:** JM Lexus**SERVICE:** ELECTRICAL**DESCRIPTION:** ELECTRICAL ~I~VEHICLE NEEDS TO RETURN TO THE JOSE AND STEVE AND CHECK THE RADAR SYSTEM INSTALLED ~I~ ~I~CUSTOME CREATIONS HAVE TAKEN CARE OF THE CUSTOMERS CONCERNS.**SERVICE:** NAVIGATION COMPUTER**DESCRIPTION:** NAVIGATION COMPUTER ~I~CUSTOMER REQUESTS NAVIGATION MAP UPDATES CUSTOMER PURCHASED PART AT PARTS BOUTIQUE. LABOR DUE. ~I~UPDATE VEHICLE NAVIGATION SYSTEM WITH VERSION 15.1 - 20% POINTS OF INTEREST HAVE CHANGED OR RELOCATED - 42 NEW FULLY NAVIGABLE COUNTIES - 200,000+ MILES OF NEW ROADS - 50+ NEW METROPOLITAN AREAS, INCLUDES MANY NEW SUBDIVISIONS - INCLUDES 6 MILLION MILES OF ~I~UPDATE VEHICLE NAVIGATION SYSTEM WITH VERSION 15.1 NAV SYSTEM UPDATE COMPLETED. THANK YOU!!! CUSTOMER PURCHASED PART AT PARTS BOUTIQUE. LABOR DUE.**SERVICE:** OTHERS**DESCRIPTION:** OTHERS ~I~CUSTOMER STATES THAT THE CARPETING NEXT TO THE FRONT CONSOLE NEEDS TO BE RE.ALIGNED. ~I~. ~I~READJUST CARPET.

35483 MILES**DATE:** 11/27/2015

REPAIR# 0810374**REPORTED BY:** JM Lexus**SERVICE:** FRONT/REAR BODY

DESCRIPTION: FRONT/REAR BODY ~|~GUEST STATES DASH IS COMING APART BRIAN HAS NEW DASHBOARD.. LEXUS WILL PAY FOR 50% AND THE GUEST WILL TAKE CARE OF THE OTHER 50% FOR PARTS AND LABOR. GOOD WILL PORTION APPROVED BY DSPM. ~|~DASH IS CRACKED DUE TO HEAT AND HUMIDITY REASON ~|~REPLACE DASH PAD ASSY. GOOD WILL PORTION APPROVED BY DSPM. FRONT/REAR BODY ~|~GUEST STATES DASH IS COMING APART BRIAN HAS NEW DASHBOARD.. LEXUS WILL PAY FOR 50% AND THE GUEST WILL TAKE CARE OF THE OTHER 50% FOR PARTS AND LABOR. GOOD WILL PORTION APPROVED BY DSPM. ~|~DASH IS CRACKED DUE TO HEAT AND HUMIDITY REASON ~|~REPLACE DASH PAD ASSY. GOOD WILL PORTION APPROVED BY DSPM.

35483 MILES**DATE:** 10/28/2015**REPAIR#** 0807127**REPORTED BY:** JM Lexus**SERVICE:** FRONT/REAR BODY

DESCRIPTION: FRONT/REAR BODY ~|~CUSTOMER STATES WOULD LIKE NEW HEADLIGHTS AND FOG LIGHTS IN- STALLED PARTS HAVE ALREADY BEEN ORDERED AND ARE WITH DERBY ~|~ ~|~R&R FRONT BUMPER.REPLACE BOTH FOG LAMP ASSEMBLIES

35478 MILES**DATE:** 10/27/2015**REPAIR#** 0805225**REPORTED BY:** JM Lexus**SERVICE:** AFTERMARKET

DESCRIPTION: AFTERMARKET ~|~FULL RADAR INSTALL ~|~

35477 MILES**DATE:** 09/30/2015**REPAIR#** 0796860**REPORTED BY:** JM Lexus**SERVICE:** AUTO DETAILING

DESCRIPTION: AUTO DETAILING ~|~CUSTOMER REQUESTS PRESIDENTIAL DETAIL PACKAGE. ~|~INTERIOR INCLUDES: VACUUM INTERIOR, SHAMPOO CARPETS, SEATS, & FLOOR MATS; DETAIL DASH, CONSOLE & AIR VENTS; CLEAN & CONDITION LEATHER SEATS, SIDE PANELS & DOORS; CLEAN WINDOWS ~|~PRESIDENTIAL PACKAGE ALL

SERVICE: TIRE-WHEEL

DESCRIPTION: TIRE-WHEEL ~|~CUSTOMER REQUESTS REPLACEMENT OF ALL FOUR TIRES RF OLD TIRE: DEPTH..... DOT#..... RR OLD TIRE: DEPTH..... DOT#..... LF OLD TIRE: DEPTH..... DOT#..... LR OLD TIRE: DEPTH..... DOT#..... ~|~MOUNT AND BALANCE 4 TIRES. ~|~MOUNT & BALANCE 4 TIRES 4 WHEELS AFTER MOUNTING OLD TIRES ON NEW RIM

33491 MILES**DATE:** 12/04/2014

REPAIR# 0704810**REPORTED BY:** JM Lexus**SERVICE:** AUTO DETAILING

DESCRIPTION: AUTO DETAILING ~|~CUSTOMER REQUESTS PRESIDENTIAL DETAIL PACKAGE. ~|~INTERIOR INCLUDES: VACUUM INTERIOR, SHAMPOO CARPETS, SEATS, & FLOOR MATS; DETAIL DASH, CONSOLE & AIR VENTS; CLEAN & CONDITION LEATHER SEATS, SIDE PANELS & DOORS; CLEAN WINDOWS ~|~PRESIDENTIAL PACKAGE ALL

SERVICE: OTHERS

DESCRIPTION: OTHERS ~|~PURCHASE AND PROGRAM 1 MASTER REMOTE KEY (KEY HAS BEEN ORDERED BY DEBORAH B. IN PARTS) ~|~. ~|~COMPLETED

SERVICE: CCSP CPN D3

DESCRIPTION: CCSP CPN D3 ~|~CUSTOMER REQUESTS 60,000 MILE SERVICE PER JMA/FIDELITY CAR CAR SERVICE PLAN. COUPON CODE D3 (1.9 HRS) ~|~REPLACE SYN BLEND ENGINE OIL, FILTER & GASKET. ROTATE FOUR TIRES AND ADVISE ON WEAR. REPLACE ENGINE AND AC CABIN FILTER. INSPECT ENGINE COOLANT. REPLACE FRONT WIPER INSERTS. REPLACE BRAKE FLUID. REPLACE REMOTE KEYLESS ENTRY REMOTE BATTERIES. COMPLETE TRAN ~|~THANK YOU FOR CHOOSING JM LEXUS TO SERVICE YOUR VEHICLE! AUTHORIZATION #56690888

32620 MILES**DATE:** 08/19/2014**REPAIR#** 0065930**REPORTED BY:** Lexus of West Kendall**SERVICE:** CAR WASH

DESCRIPTION: CAR WASH ~|~COMPLEMENTARY CAR WASH ~|~. ~|~COMPLETE..

31738 MILES**DATE:** 03/26/2014**REPAIR#** 0999816**REPORTED BY:** Lexus of West Kendall**SERVICE:** NON WARRANTABLE OPERATION CODE

DESCRIPTION: NON WARRANTABLE OPERATION CODE
~|~CUSTOMER IS IN A SERVICE @ 35.00PER DAY ~|~AUTH#59201755A
~|~DONE!!!!!!!!!!!!!!

SERVICE: RADIO SPKR ASSY, REAR 1-SIDE

DESCRIPTION: RADIO SPKR ASSY, REAR 1-SIDE ~|~CUSTOMER STATES, THAT THE REAR SPEAKER IS MAKING A LOUD RATTLING NOISE WHEN AUDIO IS IN USEAGE. (CHECK & REPORT) ~|~PERFORMED INSPECTION ON RATTLING NOISE COMING FROM AUDIO SYSTEM CONCERN, FOUND REAR SUB-WOOFER SPEAKER ASSEMBLY WITH AN INTERNAL MALFUNCTION. AUTH# 59201755A ~|~PERFORMED REPALCEMENT ON THE REAR SUB-WOOFER SPEAKER ASSEMBL

SERVICE: OTHERS

DESCRIPTION: OTHERS ~|~CUSTOMER STATES, THAT THE VSC LIGHT IS ON. (CHECK & REPORT) \$125.00+TAXSC ~|~PERFORMED CHECK ON ENGINE LIGHT CONCERN, FOUND DTC CODES (P0455) SMALL LEAK COMING FROM FUEL SYSTEM. FUEL CAP SEAL WRAP.. AUTH#5920156A ~|~PERFORMED REPLACEMENT ON FUEL CAP ASSEMBLY. PERFORMED RECHEC ON ENGINE FUEL CONCERN, RESET & UP DATA ALL DATA, ROAD TEST VEHICLE, AT THIS TIME FUEL SYSTEM HAS A NO LEAKS COMING SYSTEM. OTHERS ~|~CUSTOMER REQUEST TO DO A REAR BRAKE ON VEHICLE AS PER ESTIMA ~|~UPON VEHICLE INSPECTION FOUND REAR BRAKE PADS BELOW FACTORY SPEC... (REAR PADS @2MM) ~|~PERFORMED REAR BRAKE JOB SERVICE COMPLETE... REFURBISH REAR ROTORS REPLACE REAR BRAKE PADS PERFORMED CLEANING & LUBING ON CALPIER SLIDES & PINS PERFORMED BLEEDING BRAKE LINES ROAD TEST VEHICLE

SERVICE: WATER PUMP

DESCRIPTION: WATER PUMP ~|~CUSTOMER REQUEST TO REPLACE THE WATER PUMP ASSEMBLY AS PER ESTIMATE... ~|~UPON VEHICLE INSPECTION FOUND WATER LEAK COMING FROM THE WATER PUMP ASSEMBLY.. AUTH# 59201757A ~|~PERFORMED REPLACEMENT ON THE WATER PUMP ASSEMBLY.

31149 MILES**DATE:** 02/19/2014

REPAIR# 0990588

REPORTED BY: Lexus of West Kendall

SERVICE: NON WARRANTABLE OPERATION CODE

DESCRIPTION: NON WARRANTABLE OPERATION CODE

~|~CUSTOMER HAS A FREE WASH & VACC.. ~|~

~|~DONE!!!!!!!!!!!!!!!!!!!!!!!!!!!!!!

30619 MILES

DATE: 01/22/2014

REPAIR# 0972219

REPORTED BY: Lexus of West Kendall

SERVICE: NON WARRANTABLE OPERATION CODE

DESCRIPTION: NON WARRANTABLE OPERATION CODE

~|~CUSTOMER IS IN A SERVICE LOANER @ \$35.00PER DAY

~|~AUTH# 59831420A ~|~DONE!!!!!!!!!!!!!!!!!!!!!!

SERVICE: SEE SECTION

DESCRIPTION: SEE SECTION ~|~CUSTOMER STATES, THAT THE AUTOMATIC A/C VENTS DOESN'T MOVE BACK & FORWARD. (CHECK & REPORT) ~|~PERFORMED CHECK ON THE IONTERIOR TRIM CONCERN, FOUND AUTOMATIC SWING REGISTER MOTOR ASSEMBLY WITH AN INTERNAL MALFUNCTION.. AUTH# 59831415A ~|~PERFORMED REPLACEMENT ON THE A/C VENT AUTOMATIC SWING REGISTER MOTOR ASSEMBLY. RECHECK A/C UNIT CONCERN, ALL VENTS WORKING AS PER DESIGN... SEE SECTION ~|~CUSTOMER STATES, THAT THERE IS BLACK OBJECTS COMING OUT THE A/C VENTS. (CHECK & REPORT).. ~|~PERFORMED CHECK ON A/C UNIT CONCERN, FOUND THE INLET AIR SERV-O MOTOR ASSEMBLY WITH AN INTERNAL MALFUNCTION.. AUTH# 59831415A ~|~PERFORMED REPLACEMENT ON THE A/C UNIT SERV-O INLET AIR MOTOR ASSEMBLY..

29283 MILES

DATE: 11/16/2013

REPAIR# 0948782

REPORTED BY: Lexus of West Kendall

SERVICE: OTHERS

DESCRIPTION: OTHERS ~|~CUSTOMER REQUEST TO REPLACE THE REAR MAIN SEAL ASSEMBLY.. AS PER ESTIMATE. ~|~UPON VEHICLE INSPECTION FOUND OIL LEAK COMING FRO ENGINE REAR MAIN SEAL ASSEMBLY.. AUTH# 46931572A ~|~PERFORMED REPLACEMENT ON THE ENGINE CRANK SHAFT REAR MAIN SEAL ASSEMBLY.

29009 MILES

DATE: 10/18/2013

REPAIR# 0934998**REPORTED BY:** Lexus of West Kendall**SERVICE:** 10000 MILE SERVICE NON WARRANTY-NON OEM

DESCRIPTION: 10000 MILE SERVICE NON WARRANTY-NON OEM
 ~|~CUSTOMER REQUESTS 10000 MILE SERVICE ##VEHICLE HAS PRE-PAID MAINTENANCE## REPLACE ENGINE OIL AND FILTER, RESET MAINT REMINDER ROTATE & BALANCE TIRES INSPECT ENGINE AIR FILTER INSPECT BRAKE PADS, LININGS, DISCS/DRUMS INSPECT STEERING LINKAGE INSPECT DRIVE ~|~SCHEDULED MAINTENANCE DUE TO TIME OR MILEAGE AUTH# 47190834
 ~|~10000 MILE SERVED COMPLETED.

SERVICE: MISC

DESCRIPTION: MISC ~|~CUSTOMER STATES, THAT THERE IS ELECT. PROBLEM OCCURRING WITH THE DRIVER'S FRONT SEAT & SIDE VIEW MIRRORS. CUSTOMER STATES, WHEN SELECTING POSITION NUMBER ONE THE SEAT STARTS GOING CRAZY, BOTH SIDE VIEW MIRRORS START MAKING LOUD KNOCKI NOISE, AND THE STEERI ~|~PERFORMED CHECK ON EXTERIOR ELECT TRM CONCERN, FOUND PASSENGER SIDE VIEW MIRROR WITH AN INTERNAL MALFUNCTION OCCURRING... AUTH# 47182650A
 ~|~PERFORMED REPLACEMENT ON PASSENGER SIDE VIEW MIRROR ASSEMBLY...

SERVICE: DISTRIBUTOR/HDLIGHT/T. SGNL

DESCRIPTION: DISTRIBUTOR/HDLIGHT/T. SGNL ~|~CUSTOEMR STATES, THAT THE PASSENGER HEADLIGHT ASSEMBLY GETS DIME WHEN DRIIVING. (CHECK & REPORT) ~|~PERFORMED CHECK ON EXTERIOR TRIM CONCERN, FOUND DTC CODES (B2418) PASSENGER HEADLIGHT BEAM LEVEL CONTROL MOTOR HAS AN INTERNAL MALFUNCTION OCCURRING. AUTH#47182650A
 ~|~PERFORMED REPLACEMENT ON PASSENGER HEADLIGHT ASSEMBLY RECEHCK EXTERIOR TRIM CONCERN, BOTH HEADLIGHT WORKING TO FACTORY SPEC...

28319 MILES**DATE:** 09/16/2013**REPAIR#** 0913080**REPORTED BY:** Lexus of West Kendall**SERVICE:** DISTRIBUTOR/HDLIGHT/T. SGNL

DESCRIPTION: DISTRIBUTOR/HDLIGHT/T. SGNL ~|~CUSTOMER STATES, THAT THE BOTH HEADLIGHT ASSEMBLY GETS DIME WHEN DRIVING. (CHECK & REPORT) ~|~PERFORMED CHECK ON EXTERIOR TRIM CONCERN, FOUND DRIVER'S HEADLIGHT LEVEL SYSTEM WITH AN INTERNAL MALFUNCTION OCCURRING AUTH#47610937A ~|~PERFORMED REPLACEMENT ON DRIVER'S HEADLIGHT ASSEMBLY

SERVICE: MISC

DESCRIPTION: MISC ~|~CUSTOMER STATES, THAT THE STEERING MOTOR ASSEMBLY DOESN'T RETRACK UP NOR DOWN. (CHECK & REPORT) ~|~PERFORMED CHECK ON INTERIOR TRIM CONCERN, FOUND STEERING WHEEL TILT MOTOR ASSEMBLY WITH AN INTERNAL MALFUNCTION. AUTH#47610937A ~|~PERFORMED REPLACEMENT ON STEERING WHEEL TILT MOTOR ASSEMBLY RECHECK CONCERN, ROAD TEST VEHICLE, STEERING WHEEL TILT ASSEMBLY WORKING AS PER DESIGN.

28020 MILES**DATE:** 08/08/2013**REPAIR#** 0903145**REPORTED BY:** Lexus of West Kendall**SERVICE:** MISC

DESCRIPTION: MISC ~|~CUSTOMER STATES, THAT THE PASSENGER FRONT DOOR LOCK ASSEMBLY IS RESPONDING AT TIMES. (CHECK & REPORT) ~|~PERFORMED CHECK ON EXTERIOR TRIM ELECT. CONCERN, FOUND PASSENGER FRONT DOOR LOCK ASSEMBLY WITH AN INTERNAL MALFUNCTION OCCURRING. AUTH# 47933198A (1.3) ~|~PERFORMED REPLACEMENT ON THE PASSENGER FRONT DOOR LOACK ASSEMBLY. RECHECK EXTERIOR TRIM CONCERN, AT THIS TIME LOCK ASSEMBLY WORKING TO FACTORY SPEC..

SERVICE: NON WARRANTABLE OPERATION CODE

DESCRIPTION: NON WARRANTABLE OPERATION CODE
 ~|~CUSTOMER REQUEST TO DO AO FULL DETAILLING ON VEHICLE ~|~ ~|~PERFORMED FULL DETAILLING ON VEHICLE

25765 MILES**DATE:** 04/06/2013**REPAIR#** 0848683**REPORTED BY:** Lexus of West Kendall

25469 MILES

DATE: 03/01/2013

SERVICE: DISTRIBUTOR/HDLIGHT/T. SGNL**DESCRIPTION:** DISTRIBUTOR/HDLIGHT/T. SGNL ~1-CUSTOMER

STATES, THAT THE HEADLIGHT ASSEMBLY IS GOES WHILE DRIVING. CUSTOMER ALSO STATES, THAT THEY REPLACE BULB.

REPAIR# 0638069**REPORTED BY:** Lexus of West Kendall

~1-PERFORMED CHECK ON EXTERIOR TRIM CONCERN, FOUND DRIVER'S HEADLIGHT BALLIST ASSEMBLY WITH AN INTERNAL

SERVICE: 10000 MILE SERVICE NON WARRANTY-NON OEM**DESCRIPTION:** 10000 MILE SERVICE NON WARRANTY-NON OEM

CONCERN, ROAD TEST VEHICLE, BOTH HEADLIGHT ASSEMBLY

~1-CUSTOMER REQUESTS 25000 MILE SERVICE ##VEHICLE HAS

WORKING AS PER DESIGN.## REPLACE ENGINE OIL AND FILTER,

RESET MAINT REMINDERE ROTATE & BALANCE TIRES INSPECT

ENGINE AIR FILTER INSPECT BRAKE PAD, LININGS, DISCS/DRUMS

INSPECT STEERING LINKAGE INSPECT DRIVE ~1-SCHEDULED

MAINTENANCE DUE TO TIME OR MILEAGE AUTH#4941228 ~1-25000

MILE SERVICE COMPLETED

SERVICE: NON WARRANTABLE OPERATION CODE**DESCRIPTION:** NON WARRANTABLE OPERATION CODE

~1-CUSTOMER STATES, THAT THE TRUNK SHOCK ARE NOT HOLDING PRESSURE. (CHECK & REPORT) ~1-PERFORMED CHECK ON EXTERIOR TRIM CONCERN, FOUND TRUNK SHOCK ASSEMBLY NOT HOLDING THE PRESSURE.. AUTH#4908602A ~1-PERFORMED SERVICE WITH TRUNK SHOCKS ASSEMBLY

DESCRIPTION: SEE SECTION ~1-CUSTOMER STATES, THAT THE

A/C UNIT NOT COOLING LIKE NORMAL (CHECK & REPORT)

~1-PERFORMED CHECK ON A/C UNIT CONCERN, FOUND A/C

TEMP. CONTROL AIR MIXER SERV-O MOTOR ASSEMBLY..

AUTH#49402172A ~1-PERFORMED REPLACEMENT ON A/C TEMP.

CONTROL AIR MIXER SERV-O MOTOR ASSEMBLY. RECHECK

CONCERN, ROAD TEST VEHICLE, A/C UNIT WORKING AS PER

DESIGN...

24239 MILES

DATE: 03/30/2012

REPAIR# 0705766**REPORTED BY:** Lexus of West Kendall**SERVICE:** INSPECT BATTERY CHARGE LEVEL INSPECT BATTERY CHARGE LEVEL**DESCRIPTION:** INSPECT BATTERY CHARGE LEVEL ~1-VEHICLE

GIVES OFF A WEAK CRANKING WHEN TRYING TOO START

~1-PERFORMED CHECK ON ELECT. CONCERN FOUND BATTERY

WITH BAD CEL OPER.#190011A (0.6) ~1-REPLACED BAD BATTERY

SERVICE: MISC**DESCRIPTION:** MISC ~1-CUSTOMER STATES, THAT THE VEHICLE

GIVES OFF A WEAKING CRANKING WHEN TRYING TOO START.

CUSTOMER ALSO STATES, VEHICLE SHUTS OFF WHEN TRYING

TOO START. (CHECK & REPORT) ~1-PERFORMED CHECK ON

ELECTRICAL CONCERN, FOUND ALTERNATOR ASSEMBLY NOT

HOLDING CHARGE ON LOAD..... AUTH#39111525A (1.3)

~1-REPLACED ALTERNATOR ASSEMBLY// RECHECK CONCERN

EVERYTHING WORKING TOO FACTORY SPEC....

SERVICE: NON WARRANTABLE OPERATION CODE**DESCRIPTION:** NON WARRANTABLE OPERATION CODE

~1-PERFORM 4 WHEEL ALIGNMENT. \$129.99+TAXSC ~1-

~1-PERFORMED FOUR WHEEL ALIGNMENT NON WARRANTABLE

OPERATION CODE ~1-CUSTOMER IS IN A SERVICE LOANER ~1-

~1-DONE!!!

SERVICE: OTHERS**DESCRIPTION:** OTHERS ~1-CUSTOMER REQUEST TOO DO A

FRONT BRAKE JOB ~1-UPON VEHICLE INSPECTION, FOUND

FRONT BRAKE PADS @ 3MM. ~1-PERFORMED FRONT BRAKE JOB

SERVICE REPLACED FRONT BRAKE PADS REFURBISH ROTORS

REPLACED CALIPLER BOLTS LUBE CALIPLER SLIDES & PINS BLEEDS

BRAKE LINES TEST DROVE VEHICLE

23927 MILES

DATE: 11/23/2011

REPAIR# 0645099**REPORTED BY:** Lexus of West Kendall**SERVICE:** 10000 MILE SERVICE NON WARRANTY-NON OEM**DESCRIPTION:** 10000 MILE SERVICE NON WARRANTY-NON OEM

~1-CUSTOMER REQUESTS 25000 MILE SERVICE ##VEHICLE HAS

PRE-PAID MAINTENANCE## REPLACE ENGINE OIL AND FILTER,

RESET MAINT REMINDERE ROTATE TIRES INSPECT ENGINE AIR

FILTER INSPECT BRAKE PAD, LININGS, DISCS/DRUMS INSPECT

STEERING LINKAGE INSPECT DRIVE BELTS INSP ~1-SCHEDULED

MAINTENANCE DUE TO TIME OR MILEAGE ~1-25000 MILE SERVICE

COMPLETED AUTH#26760376

SERVICE: MISC MISC**DESCRIPTION:** MISC ~1-CUST STATES VEH SOMETIMES HARD TO

START PLEASE CK AND ADVISE ~1-TESTED ELECTRICAL SYSTEM

FOUND BATT NOT HOLDING CHARGE NEEDS BATT. ~1-REPLACED

BATT OPCODE#190011A

23353 MILES

DATE: 04/27/2011

REPAIR# 0520902**REPORTED BY:** Lexus of West Kendall**SERVICE:** NON WARRANTABLE OPERATION CODE

DESCRIPTION: NON WARRANTABLE OPERATION CODE ~|~CUST STATES DRIVER SIDE MIRROR WILL NOT ADJUST UP OR DOWN ~|~FOUND OUTER DRIVER SIDE MIRROR INTERNAL FAILURE ~|~NECESSARY TO REPLACE DRIVER SIDE DOOR MIRROR FIDELITY AUTH#28950217A

22964 MILES**DATE:** 02/24/2011**REPAIR#** 0492775**REPORTED BY:** Lexus of West Kendall**SERVICE:** 15000 MILE SERVICE NON WARRANTY

DESCRIPTION: 15000 MILE SERVICE NON WARRANTY ~|~CUSTOMER REQUESTS 30000 MILE SERVICE ##VEHICLE HAS PRE-PAID MAINTENANCE## REPLACE ENGINE OIL AND FILTER REPLACE ENGING AIR FILTER ROTATE TIRES INSPECT A/C AIR FILTER INSPECT STEERING LINKAGE INSPECT BALL JOINTS AND DUST COVERS INSPECT BODY/CHASSIS NUTS AN ~|~SCHEDULED MAINTENANCE DUE TO TIME OR MILEAGE ~|~30000 MILE SERVICE COMPLETED

SERVICE: OTHERS

DESCRIPTION: OTHERS ~|~C/S THE CHECK ENGINE VSC AND TRAC OFF LIGHTS ARE ON ~|~BRAKE MASTER CYCLINDER NOT HOLDING PRESURE ~|~REPLACED BRAKE MASTER CYCLINDER

SERVICE: NON WARRANTABLE OPERATION CODE

DESCRIPTION: NON WARRANTABLE OPERATION CODE ~|~PERFORM TOP ENGINE CLEAN SERVICE ~|~CARBON BUILD UP IN SYSTEM ~|~JOB COMPLETED,CLEANED OUT THROTTLE BODY AND FLUSHED FUEL INJECTORS

22118 MILES**DATE:** 09/25/2010**REPAIR#** 0326214**REPORTED BY:** JM Lexus**SERVICE:** 19 PT INSPECTION

DESCRIPTION: 19 PT INSPECTION ~|~COMPLIMENTARY 19-POINT VEHICLE INSPECTION

SERVICE: MANIFOLD-MUFFLER

DESCRIPTION: MANIFOLD-MUFFLER ~|~VEHICLE DUE FOR 5,000 MILE INTERVAL SERVICE. (5M,10M,20M...85M,95M,100M,1 10M) THIS IS STANDARD SERVICE PERFORMED EVERY 5,000 MILE INTERVAL ~|~INCLUDES ALL ITEMS LISTED ABOVE. ~|~5,000 MILE SVC

21692 MILES**DATE:** 08/31/2010**REPAIR#** 0318190**REPORTED BY:** JM Lexus**SERVICE:** FUEL TANK SUBASSEMBLY FUEL TANK SUBASSEMBLY

DESCRIPTION: FUEL TANK SUBASSEMBLY ~|~CUSTOMER STATES SLOW CRANK TO START ~|~RATED CCA: 582 MEASURED CCA: 438 MEASURED VOLTS: 12.64 WARRANTY CODE: C1CP ~|~REPLACED BATTERY. Z=EXCHANGE FEE R/R BATT ON 167090 01/19/2009 15275

21550 MILES**DATE:** 06/07/2010

REPAIR# 0300311**REPORTED BY:** JM Lexus**SERVICE:** CCSP CPN C9

DESCRIPTION: CCSP CPN C9 ~1~CUSTOMER REQUESTS 40,000 MILE SERVICE PER JMA/FIDELITY CAR CARE SERVICE PLAN. COUPON CODE C9 AUTH # 18430782 ~1~LUBE, OIL AND FILTER CHANGE, REPLACE A/C FILTER, ROTATE TIRES, MULTI-POINT INSPECTION, AND ROAD TEST VEHICLE. ~1~THANK YOU FOR CHOOSING JM LEXUS TO SERVICE YOUR VEHICLE!

18512 MILES**DATE:** 01/20/2010**REPAIR#** 0262560**REPORTED BY:** JM Lexus**SERVICE:** CCSP CPN C5

DESCRIPTION: CCSP CPN C5 ~1~CUSTOMER REQUESTS 20,000 MILE SERVICE AS PER JMA/FIDELITY CAR CARE SERVICE PLAN. COUPON CODE C5 ~1~LUBE, OIL AND FILTER CHANGE, CLEAN A/C FILTER, ROTATE TIRES, MULTI-POINT INSPECTION, AND ROAD TEST VEHICLE. ~1~THANK YOU FOR CHOOSING JM LEXUS TO SERVICE YOUR VEHICLE!

SERVICE: NON WARRANTABLE OPERATION CODE

DESCRIPTION: NON WARRANTABLE OPERATION CODE ~1~REPLACE 4 TIRES LS430 MICHELIN MXV4 225/55R17 06852 ~1~ ~1~REPLACED ALL FOUR TIRES AND BALANCED LCCS CREDIT \$350 AUTH# 1-SR8HL REF CASE# 1001128282 NON WARRANTABLE OPERATION CODE ~1~CUSTOMER REQUESTS 4 WHEEL ALIGNMENT ~1~ ~1~PERFORMED 4-WHEEL ALIGNMENT ON VEHICLE

18074 MILES**DATE:** 11/20/2009**REPAIR#** 0244837**REPORTED BY:** JM Lexus**SERVICE:** DETAIL PKG 3

DESCRIPTION: DETAIL PKG 3 ~1~CUSTOMER REQUESTS CAR CARE ANNIVERSARY DETAIL. ~1~INCLUDES: COMPLETE INTERIOR DETAIL INCLUDES SHAMPOOING OF CARPETS & SEATS, EXTERIOR HAND WASH AND WAX, TIRES DRESSED, AND WINDOWS CLEANED. ~1~THANK YOU FOR CHOOSING THE JM LEXUS SERVICE DEPARTMENT!

17777 MILES**DATE:** 10/19/2009**REPAIR#** 0235200**REPORTED BY:** JM Lexus**SERVICE:** FRONT/REAR BODY

DESCRIPTION: FRONT/REAR BODY ~1~CUSTOMER STATES FINISH PEELING OFF WIPER ARMS ~1~WIPER ARM ASSEMBLY FINISH PEELING TO POOR ADHESION ~1~REPLACED WIPER ARM ASSEMBLY REFER TP PREV RO# 209912 7/01/09 MO-16885

16886 MILES**DATE:** 07/02/2009

11775 MILES

DATE: 10/08/2007

REPAIR# 0038270
REPORTED BY: JM Lexus

SERVICE: 10000 MILE SERVICE NON WARRANTY-NON OEM
DESCRIPTION: 10000 MILE SERVICE NON WARRANTY-NON OEM
~1-CUSTOMER REQUESTS 10000 MILE SERVICE JMA CONT #31002234
SVS CODE 01 SCHED C3 \$134.00 ~1-SCHEDULED MAINTENANCE
DUE TO TIME OR MILEAGE ~1-10000 MILE SERVICE PERFORMED

10999 MILES

DATE: 08/10/2007

REPAIR# 0020262
REPORTED BY: JM Lexus

SERVICE: FRONT/REAR BODY
DESCRIPTION: FRONT/REAR BODY ~1-C/S BUTTONS ON
STEERING WHEEL NOT FUNCTIONING WHEN PRESSED
~1-BUTTONS SHORTED ON STEERING WHEEL ~1-REPLACE
STEERING WHEEL

10742 MILES

DATE: 07/03/2007

REPAIR# 0010742
REPORTED BY: JM Lexus

SERVICE: FRONT/REAR BODY
DESCRIPTION: FRONT/REAR BODY ~1-C/S DRIVER DOOR STEP
MOULDING WITH LOGO COMING LOOSE AND FADING
~1-MOULDING LEXUS LOGO SEPERATED ~1-REPLACE L FRT STEP
MOULDING FRONT/REAR BODY ~1-C/S KEY RING TRIM FADING
~1-RING TRIM DEFORMED ~1-REPLACE KEY RING TRIM

9531 MILES

DATE: 02/27/2007

REPAIR# 0969288
REPORTED BY: JM Lexus

SERVICE: NON WARRANTABLE OPERATION CODE
DESCRIPTION: NON WARRANTABLE OPERATION CODE
~1-BUTTONS ON STEERING WHEEL DO NOT LOOK CORRECT
~1-BUTTONS ON STEERING WHEEL HAVE A DEFORMATION
~1-REPLACE BUTTONS ON STEERING WHEEL

8278 MILES

DATE: 11/15/2006

REPAIR# 0939870
REPORTED BY: JM Lexus

SERVICE: FRONT/REAR BODY
DESCRIPTION: FRONT/REAR BODY ~1-C/S THAT THE REAR
PRIVACY CURTAIN GOES UP ON ONE SIDE ONLY AT TIMES.
~1-CURTAIN DEFORMED AND IS BINDING INSIDE OF THE REAR
SUNSHADE ASSEMBLY. ~1-REPLACED REAR SUNSHADE
ASSEMBLY, OPERATED TO VERIFY CORRECT- ION.

3122 MILES

DATE: 10/02/2004

REPAIR# 0913780
REPORTED BY: JM Lexus

SERVICE: NON WARRANTABLE OPERATION CODE
DESCRIPTION: NON WARRANTABLE OPERATION CODE
~|~CHECK VEHICLE FOR VIBRATION C/S VIBRATION FELT IN STEERING AT 45MPH AND ABOVE ~|~ROAD TEST VEHICLE TO VERIFY CUST. CONCERN AND FOUND ST. SHAKES AND VEHICLE VIB. AT HIGHER SPEEDS, NEEDS TIRE'S BAL. TIRES OUT OF BALANCE ~|~PERFORM 4 WHEEL TIRE BALANCE, ROAD TEST VEHICLE AND ALL OK AT THIS TIME.

SERVICE: NON WARRANTABLE OPERATION CODE NON WARRANTABLE OPERATION CODE
DESCRIPTION:

4801 MILES

DATE: 01/23/2006

REPAIR# 0851470
REPORTED BY: JM Lexus

SERVICE: NON WARRANTABLE OPERATION CODE
DESCRIPTION: NON WARRANTABLE OPERATION CODE
~|~CUSTOMER TO GET SOP CHROME WHEELS. SEE SINGH IN PARTS ~|~CUSTOMER REQUEST CHROME RIMS. ~|~REPLACE ORIGINAL RIMS WITH CHROME RIMS. NON WARRANTABLE OPERATION CODE ~|~WINDOW TINT DRIVERS FRONT WINDOW IS PEELING. ~|~RE-TINT WINDOW AFTER INSPECTION. TINT WARRANTY. NO CHARGE.

4180 MILES

DATE: 12/26/2005

REPAIR# 0839515
REPORTED BY: JM Lexus

SERVICE: 5,000 MILE SERVICE
DESCRIPTION: 5,000 MILE SERVICE ~|~CUSTOMER REQUESTS 5000 MILE SERVICE ~|~SCHEDULED MAINTENANCE DUE TO TIME OR MILEAGE ~|~5000 MILE SERVICE PERFORMED

SERVICE: FRONT/REAR BODY
DESCRIPTION: FRONT/REAR BODY ~|~C/S THAT THE PRIVACY NET ON THE REAR DECK INSIDE CAR IS NOT GOING BACK UP. ~|~CUSTOMER HAD REAR CURTAIN BUTTON DE-ACTIVATED. ~|~RE-ACTIVATED REAR CURTAIN USING BUTTON ON CENTER CONSOLE.

SERVICE: NON WARRANTABLE OPERATION CODE
DESCRIPTION: NON WARRANTABLE OPERATION CODE
~|~SERVICE RESERVATION MADE BY J M LEXUS SERVICE RESERVATIONS

SERVICE: NON-OEM THEFT DETERRENT SYSTEM INSTALL/R&R
DESCRIPTION: NON-OEM THEFT DETERRENT SYSTEM INSTALL/R&R ~|~C/S THAT KEYLESS ENTRY FOR VEHICLE IS NOT WORKING. REMOTE BUTTON HAS TO BE PRESSED BEFORE DOOR OPENS. ~|~CUSTOMER HAD SECOND MASTER KEY STORED IN GLOVE COMPARTMENT. REMOTE ACCESS WILL NOT WORK IF SMART KEY IS PRESENT IN CAR. ~|~ADVISE CUSTOMER TO ENSURE THAT NO OTHER KEYS ARE KEPT INSIDE VEHICLE IF KEYLESS ENTRY IS TO WORK EFFECTIVELY.

3633 MILES

DATE: 08/31/2005

REPAIR# 0815286
REPORTED BY: JM Lexus

SERVICE: MISC
DESCRIPTION: MISC ~|~C/S THAT CIGARETTE LIGHTER IN FRONT IS INOP. ~|~CIG.LIGHTER FUSE WAS BURNT ~|~REPLACED FUSE

18 MILES

DATE: 12/30/2004

REPAIR# 0751128

REPORTED BY: JM Lexus

SERVICE: PRE-DELIVERY SERVICE FOR USA ALL ALTITUDES

DESCRIPTION: PRE-DELIVERY SERVICE FOR USA ALL ALTITUDES

~|~PERFORM PRE DELIVERY INSPECTION. ~|~|~PERFORMED PRE DELIVERY INSPECTION

TERMS AND CONDITIONS

INFORMATION ACCURACY

Information presented on this website is summarized and standardized from repair orders completed at the time of service and submitted by Lexus dealers. When reviewing a vehicle's service history, please note that all information is provided by the Lexus Dealer that conducted the service, and that dealer is solely responsible for the accuracy, completeness or authenticity of any information contained in this site. Lexus provides this site and all information and materials contained herein as is? without warranty of any kind. Any questions or concerns regarding this information should be addressed to the applicable Lexus dealer.

L/CERTIFIED OWNER INFORMATION

Dealer-reported service history records are linked to a vehicle's Vehicle Identification Number (VIN). All owner-reported service history records will be made available to the person who input the information on the site, but will not be shared with future owners of the vehicle.

OWNER-REPORTED INFORMATION AND PRIVACY TERMS

Lexus makes every effort to ensure the secure collection and transmission of sensitive user information using industry-accepted data collection and encryption methodologies. The information you provide is used by Lexus and its vendors and dealers to help improve the services we render. It is occasionally provided to Lexus dealers for their marketing use. Lexus will never sell your personally identifiable information to any other company. To learn more about our privacy policies and practices with respect to this website, please [click here](http://www.lexus.com/privacy/online-statement) ([//www.lexus.com/privacy/online-statement](http://www.lexus.com/privacy/online-statement)).