CaliJosh / 2008 LEXUS LS 600h L

Edit

Service History for VIN: JTHDU46F785001264							
Sort By:							
SERVICE TYPE	DATE	SERVICE PROVIDER	MILEAGE	REPAIR #	DESCRIPTION		
Dealer Reported	06/08/2015	Arrowhead Lexus	67743	0365564	*ROTATE & BALANCE PERFORM ROAD FORCE BALANCE OF ALL FOUR TIRES NO ROTATION HAS VIBRATION 20 - 40 MPH - RECHECKED FRONT TIRES,LEFT FRONT 16 LBS ROAD FORCE,RIGHT FRONT 19 LBS ROAD FORCE. MOUNTED NEW TIRES IN ON REAR LEFT REAR 7LBS ROAD FORCE,MOUNTED ON LEFT FRONT. RIGHT TIRE 44LBS ROAD FORCE,ROTATED ON WHEEL 180 DEGREES,NOW 16LBS ROAD FORCE, MOUNTED ON RIGHT		
Dealer Reported	04/20/2015	Arrowhead Lexus	67517	0360711	4 WHEEL SPIN BALANCE - CUSTOMER SUPPLIED TIRES - COMPLETE ROAD FORCE MEASUREMENTS.LF:12LBS,RF:17LBS,LR:38LBS RR:49LBS, BOTH REAR TIRES EXCESSIVE.		
Dealer Reported	03/12/2015	Arrowhead Lexus	63807	0356469	*REAR DIFF SERVICE SERVICE DIFFERENTIAL - CHANGED FLUID IN FRONT DIFFERENTAIL.REAR DIFFERENTIAL AND TRANSFER CASE		
Dealer Reported	03/12/2015	Arrowhead Lexus	63807	0356469	*BRAKE FLUID EXCH BRAKE SYSTEM FLUID EXCHANGE - PERFORMED HYDRAULIC BRAKE SYSTEM FLUID EXCHANGE		
Dealer Reported	03/12/2015	Arrowhead Lexus	63807	0356469	OTHERS CUSTOMER STATES THAT THE CHECK ENGINE AND VSC LIGHTS ARE ON - NO CHECK ENGINE LIGHT ON,ONLY BRAKE AND SVC LIGHTS. CODES C1241 AND C1343 STORED WITH KEY ON AND ENGINE NOT IN READY MODE CAUSING LOW VOLTAGE.CLEARED CODES AND CONFIRMED PROPER OPERATING VOLTAGE WITH ENGINE RUNNING. TEST DROVE,NO NEW CODES.		
Dealer Reported	03/09/2015	Arrowhead Lexus	63129	0355990	CRUISE CNTRL MAIN SWTCH ASSY CUSTOMER STATES THAT THE VEHICLE WILL NOT - HYBRID SERVICE PLUG NOT IN ALL THE WAY		
Dealer Reported	03/09/2015	Arrowhead Lexus	63129	0355990	SAFETY RECALL ELF INSPECT FOR FUEL PRESSURE SENSOR LEAK, CAMPAIGN ELF - REPLACED FUEL PRESSURE SENSOR PER ELF CAMPAIGN		
Dealer Reported	03/09/2015	Arrowhead Lexus	63129	0355990			
Dealer Reported	02/25/2015	Arrowhead Lexus	62849	0354902	WHEEL ALIGNMENT PERFORM FOUR WHEEL ALIGNMENT - PERFORMED FOUR WHEEL ALIGNMENT		
Dealer Reported	01/05/2015	Arrowhead Lexus	62737	0349564	RADIO TUNER ASSEMBLY CUSTOMER STATES THAT THE RIGHT FRONT DASH SPEAKER RATTLES - FOUND CLIP BEHIND RIGHT DASH SPEAKING MAKING A CREAKING NOISE WHILE DRIVING - INSOLATED CLIP AND SURROUNDING AREA AND TEST DROVE NO NOISE HEARD AFTER TEST DRIVE		
Dealer Reported	01/05/2015	Arrowhead Lexus	62737	0349564	FRONT AXLE CUSTOMER STATES THAT THERE IS A RATTLE NOISE FROM THE FRONT SUSPENSION - FOUND FRONT STRUTS TO BE MAKING A RATTLE TYPE NOISE WHILE DRIVING AND OR TURNING UPON INSPECTION		

SERVICE TYPE	DATE	SERVICE PROVIDER	MILEAGE	REPAIR #	DESCRIPTION
					FOUND UPPER CONTROL ARM BUSHINGS TORN - FRONT AIR STRUTS, UPPER CONTROL ARMS AND ALINGMENT REC.
Dealer Reported	06/30/2014	Arrowhead Lexus	62015	0331046	WHEEL ALIGNMENT PERFORM FOUR WHEEL ALIGNMENT - PERFORMED FOUR WHEEL ALIGNMENT
Dealer Reported	06/22/2013	Arrowhead Lexus	64322	0297579	NON WARRANTABLE OPERATION CODE MOUNT AND BALANCE FOUR TIRES CUSTOMER REQUEST MOUNT OWN TIRES ON WHEELS, LABOR ONLY - INSTALLED FOUR TIRES
Dealer Reported	06/22/2013	Arrowhead Lexus	64322	0297579	NON WARRANTABLE OPERATION CODE MOUNT AND BALANCE ONE TIRE - INSTALLED ONE TIRE
Dealer Reported	11/28/2011	Arrowhead Lexus	55123	0253529	ACCESSORY CUSTOMER STATES THAT THE REAR TV SCREEN IS INOP - FOUND DVD TURNED OFF AT SCREEN SETTING TURNED ON DVD
Dealer Reported	11/14/2011	Arrowhead Lexus	54922	0252528	STEERING WHL/MAIN SHAFT CUSTOMER STATES THAT THERE IS A VIBRATION ON LOW SPEED SHARP TURNSSOP IS IN - PERFORMED LSB 0023 - 11 - REPLACED TRANSFER GEAR
Dealer Reported	11/14/2011	Arrowhead Lexus	54922	0252528	FRONT/REAR BODY CUSTOMER STATES THAT THE DRIVERS WINDOW MAKES A NOISE WHEN CLOSED (LAST TWO INCHES) - ORDERED PART E
Dealer Reported	11/08/2011	Arrowhead Lexus	54806	0251977	LOANER CAR INSTRUCTION/NOTES ARROWHEAD LEXUS HAS PROVIDED A LOANER FOR YOU. WE ONLY ASK A \$10.00 PARTICIPATION TO OFFSET FUEL AND MAINTENANCE COSTS. PLEASE RETURN BY 6PM WHEN YOUR VEHICLE IS FINISHED OR A \$50.00 RENTAL CHARGE PER DAY WILL BE ADDED TO YOUR INVOICE LO - LOANER CAR
Dealer Reported	11/08/2011	Arrowhead Lexus	54806	0251977	STEERING WHL/MAIN SHAFT CUSTOMER STATES THAT AT SLOW SPEEDS AND TIGHT TURNS THERE IS BAD VIBRATION FROM THE STEERING - ORDERED PART
Dealer Reported	11/08/2011	Arrowhead Lexus	54806	0251977	FRONT/REAR BODY CUSTOMER STATES THAT THE DRIVERS WINDOW SQUEAKS WHEN PUT UP (LAST FEW INCHES) - REINSTALLED WINDOW SEAL
Dealer Reported	10/21/2011	Arrowhead Lexus	54637	0250587	NAVIGATION COMPUTER CUSTOMER REQUEST NAV UPDATE USE, CUSTOMER OWN FLASH DRIVE PART COMPLETED
Dealer Reported	10/19/2011	Arrowhead Lexus	54610	0250322	FRONT/REAR BODY GLOVE BOX ON RT SIDE OF DASH RATTLES WHEN DRIVING GLOVE BOX CAME OUT OF ADJUSTMENT ADJUSTED GLOVE BOX. ONE TIME GOOODWILL GESTURE FOR CUST RETENTION.
Dealer Reported	10/17/2011	Arrowhead Lexus	54570	0250133	NONOEM WINDOW TINTING - INSTALL WINDOW TINT SPLIT TINT - COMPLETED
Dealer Reported	10/17/2011	Arrowhead Lexus	54570	0250133	LOANER CAR INSTRUCTION/NOTES ARROWHEAD LEXUS HAS PROVIDED A LOANER FOR YOU. WE ONLY ASK A \$10.00 PARTICIPATION TO OFFSET FUEL AND MAINTENANCE COSTS. PLEASE RETURN BY 6PM WHEN YOUR VEHICLE IS FINISHED OR A \$50.00 RENTAL CHARGE PER DAY WILL BE ADDED TO YOUR INVOICE LO - LOANER CAR
Dealer Reported	10/17/2011	Arrowhead Lexus	54570	0250133	FRONT/REAR BODY CUSTOMER STATES PLEASE CLEAN DASH LOOKS LIKE SOME SPOTS ARE SHINNY AND OTHER ARE DULL,
Dealer Reported	09/30/2011	Sewell Lexus	53345	4108288	PRECERT MAKE READY REQUEST - PRE - CERT MAKE READY REQUEST REFINISH FRT BUMPER TO COVER UP LICENSE PLATE HOLES PER J PRICE

SERVICE TYPE	DATE	SERVICE PROVIDER	MILEAGE	REPAIR #	DESCRIPTION
Dealer Reported	09/30/2011	Sewell Lexus	53345	4108288	
Dealer Reported	09/10/2011	Sewell Lexus	53344	4107362	PAINTLESS DENT REPAIR
Dealer Reported	09/10/2011	Sewell Lexus	53344	4107362	SUBLET TOUCH UP
Dealer Reported	09/08/2011	Sewell Lexus	53343	4107003	CERTIFIED PREOWNED PDI - CERTIFIED PRE - OWNED PDI - 53343 200 COMPLETED LEXUS PRE - CERTIFICATION TIRES F8R9 BRAKES F8R11
Dealer Reported	09/08/2011	Sewell Lexus	53343	4107003	DETAIL SEDAN - 53343 420
Dealer Reported	09/08/2011	Sewell Lexus	53343	4107003	REFINISH 4 WHEELS REPLACE 4 WHEELS - 53343 200 SENT 4 WHEELS OUT FOR REPAIR AND BALANCED
Dealer Reported	09/08/2011	Sewell Lexus	53343	4107003	PRE CERT FOUR WHEEL ALIGNMENT - 53343 160 COMPLETED 4 WHEEL ALIGNMENT
Dealer Reported	09/08/2011	Sewell Lexus	53343	4107003	PRE CERT STATE INSPECTION AND GREENSHEET - 53343 60 STATE AND GREEN COMPLETE
Dealer Reported	09/08/2011	Sewell Lexus	53343	4107003	R & R OUTER REAR VIEW MIRROR ASSY & BOLTS (ONE SIDE) - E - 53343 100 R&R LEFT OUTSIDE MIRROR ASS. TO REPLACE BOLTS
Dealer Reported	09/08/2011	Sewell Lexus	53343	4107003	GLOVE BOX RATTLE NOISE/LOOSE COND. 07 LS460 ADJ GLOVE BOX - 1 - 53343 100 REPAIRED GLOVEBOX TO FIT PROPERLY
Dealer Reported	09/08/2011	Sewell Lexus	53343	4107003	PRE CERT GENERAL REPAIR PRE CERT GENERAL REPAIR R/R MUDFLAP - 53343 50 REPLACED RR MUDFLAP
Dealer Reported	09/07/2011	Sewell Lexus	53302	4107004	REPAIR AND REFINISH FRONT AND REAR BUMPERS REPAIR AND REFINISH FRONT AND REAR BUMPERS JT
Dealer Reported	09/07/2011	Sewell Lexus	53302	4107004	
Dealer Reported	09/06/2011	Sewell Lexus	53344	4107247	LEATHER RECONDITIONING
Dealer Reported	09/06/2011	Sewell Lexus	53344	4107247	SUBLET CARPET/PLASTIC PROTECTION
Dealer Reported	08/31/2011	Sewell Lexus	53296	1708691	MECHANICAL REPAIR CAR WILL NOT START - 53296 100 ADDED 3 GALS OF FUEL. CHECKED BATTERY AND TESTED 100%. CHECKED AND RESET CODES CREATED BY RUNNING VEHICLE OUT OF FUEL (LEAN CONDITION CODES AND BRAKE ACTUATOR CODES).
Dealer Reported	08/31/2011	Sewell Lexus	53296	1708691	ADDED 2 GALLONS GAS ADD 2 GALS OF GAS - 53296 ADDED 3 GALS OF FUEL, 2 WAS NOT ENOUGH
Dealer Reported	05/14/2011	<u>Park Place Lexus</u> <u>Plano</u>	50019	0904488	04 && NEWER 8 CYLMINOR - 50,000 MILE SERVICE - 04 && NEWER 8 CYL 50,000 SERVICE: 50,000 MILE SERVICE ALL MODELS: REPLACE ENGINE OIL AND FILTER; ROTATE TIRES; INSPECT ENGINE AIR FILTER; INSPECT AIR CONDITIONER AIR FILTER; ROAD TEST VEHILCE; INSPECT BRAKES: LININGS, DISCS/DRUMS, LINES, HOSES; INSPECT ST - 50016 THE 50,000 MILE SERVICE IS COMPLETED 100 TIRES LF - 5/32 RF,LR - 4/32 RR - 6/32 / BRAKES FT - 2MM TO THE ELECT SENSOR REAR - 4MM TO THE ELECT SENSOR / STATE 6/11 / REAET ALL THE MAINT LIGHTS
Dealer Reported	05/14/2011	<u>Park Place Lexus</u> Plano	50019	0904488	TIRE GOODWILL DEALER RPR - NAIL FOUND ON SIDEWALL OF RIGHT REAR TIRE. DOT # U2LNFMR5007 / PART # 040645DUL. CLAIM # 437296 PER CHRISTINA \$391.71 TOTAL - 50019 NAIL HOLE COULD NOT BE REPAIRED / REPLACED TIRE OP - TR7OO2 T1 - 64 T2 - 48 FP - 040645DU 70 NEW DOT - U2LNFM7R5110

SERVICE TYPE	DATE	SERVICE PROVIDER	MILEAGE	REPAIR #	DESCRIPTION
					/ OLD TIRE HAD 6/32
Dealer Reported	05/14/2011	<u>Park Place Lexus</u> Plano	50019	0904488	CUSTOMER STATES: BLEMISHES NOTED: 1 SCRATCH, 1 CHIPPED - 50016 HAS BODY DAMAGE ON THE RTSIDE ON THE ROCKER PANEL AT THE RR DOOR AND AT THE BUMPER SKIM BEHIND THE RR WHEEL. BOTH RT WHEELS ARE SCRAPED TOO
Dealer Reported	05/14/2011	<u>Park Place Lexus</u> Plano	50019	0904488	NEEDS TIRES TO PASS STATE INSP CLIENT STATES: OBD II (1996 - 2002) STATE INSPECT - 50016 WILL NEED TIRES BEFOR IT WILL PASS THE STATE INSPECTION THE STATE INSPECTION WAS NOT DONE.
Dealer Reported	05/14/2011	<u>Park Place Lexus</u> Plano	50019	0904488	CLIENT AUTHORIZES PARK PLACE LEXUS TO WASH THE VEHICLE AFTER REPAIRS. PARK PLACE CLIENT STATES: CLIENT AUTHORIZES PARK PLACE LEXUS TO WASH THE VEHICLE AFTER REPAIRS. PARK PLACE LEXUS IS NOT RESPONSIBLE FOR VALUABLES LEFT IN THE VEHICLE OR BODY DAMAGE OF ANY TYPE.
Dealer Reported	05/14/2011	<u>Park Place Lexus</u> <u>Plano</u>	50019	0904488	IN ORDER TO PROVIDE OUTSTANDING SERVICE FOR OUR CLIENTS ALL LOAN CARS ARE DUE BA CLIENT STATES: IN ORDER TO PROVIDE OUTSTANDING SERVICE FOR OUR CLIENTS ALL LOAN CARS ARE DUE BACK AT CLOSE OF BUSINESS EACH DAY, ONCE YOUR VEHICLE IS READY. A FINE OF 79.95 WILL BE CHARGED FOR EACH DAY AFTER.
Dealer Reported	05/14/2011	<u>Park Place Lexus</u> <u>Plano</u>	50019	0904488	CLIENT REQUESTS PARK PLACE LEXUS TO PERFORM MULTIPOINT COURTESY VEHICLE INSPECT - CLIENT STATES: CLIENT REQUESTS PARK PLACE LEXUS TO PERFORM MULTI - POINT COURTESY VEHICLE INSPECTION.
Dealer Reported	10/20/2010	<u>Park Place Lexus</u> <u>Plano</u>	42446	0861993	ALE REPL COMP SPRINGS & LASH ADJUSTERS FOR GS460, ALE CAMPAIGN - ALE - 42446 THE ALE IS COMPLETED 0528FU 1320 REPLACED THE VALVE SPRINGS AND THE LIFTERS
Dealer Reported	10/20/2010	<u>Park Place Lexus</u> <u>Plano</u>	42446	0861993	NO PRIOR BLEMISHES NOTED
Dealer Reported	10/20/2010	<u>Park Place Lexus</u> <u>Plano</u>	42446	0861993	C/S THE RF TIRE HAS A NAIL IN IT/REPAIR - 42446 REPAIRED THE RF TIRE 50
Dealer Reported	10/20/2010	<u>Park Place Lexus</u> Plano	42446	0861993	CLIENT STATES: CLIENT AUTHORIZES PARK PLACE LEXUS TO WASH THE VEHICLE AFTER REPA CLIENT STATES: CLIENT AUTHORIZES PARK PLACE LEXUS TO WASH THE VEHICLE AFTER REPAIRS. PARK PLACE LEXUS IS NOT RESPONSIBLE FOR VALUABLES LEFT IN THE VEHICLE OR BODY DAMAGE OF ANY TYPE.
Dealer Reported	08/05/2010	<u>Park Place Lexus</u> Plano	41005	0847115	LS 460 40,000 SERVICE: 40,000 MILE SERVICE: REPLACE ENGINE OIL AND FILTER; ROTAT LS 460 40,000 SERVICE: 40,000 MILE SERVICE: REPLACE ENGINE OIL AND FILTER; ROTATE TIRES; INSPECT ENGINE AIR FILTER; INSPECT AIR CONDITIONER AIR FILTER; ROAD TEST VEHILCE; INSPECT BRAKES: LININGS, DISCS/DRUMS, LINES, HOSES; INSPECT STEERING LINKAGES; INSPE - 41005 MAINTENANCE 100 COMPLETE 40,000 MILE SERVICE. STATE EXP. 6/11. BRAKE PAD THICKNESS 10.5MM REAR, 8.5MM FRONT. TIRE TREAD DEPTH AFTER ROTATE: LR=5/32"", RR=7/32"", LF=7/32"", RF=6/32"". ACTUAL START MILEAGE=40,099. ACTUAL OUT MILEAGE=40,105.
Dealer Reported	08/05/2010	<u>Park Place Lexus</u> <u>Plano</u>	41005	0847115	DIRTY UNABLE TO INSPECT - DIRTY - UNABLE TO INSPECT
Dealer Reported	08/05/2010	<u>Park Place Lexus</u> <u>Plano</u>	41005	0847115	CLIENT STATES: NEED TODAY
Dealer Reported	08/05/2010	<u>Park Place Lexus</u> <u>Plano</u>	41005	0847115	CLIENT STATES: CLIENT AUTHORIZES PARK PLACE LEXUS TO WASH THE VEHICLE AFTER REPA CLIENT STATES: CLIENT AUTHORIZES

SERVICE TYPE	DATE	SERVICE PROVIDER	MILEAGE	REPAIR #	DESCRIPTION
					PARK PLACE LEXUS TO WASH THE VEHICLE AFTER REPAIRS. PARK PLACE LEXUS IS NOT RESPONSIBLE FOR VALUABLES LEFT IN THE VEHICLE OR BODY DAMAGE OF ANY TYPE 41005 IN WASH 10:42AM 8/5/10, PT 4:30PM 8/5/10, TECH 541.
Dealer Reported	08/05/2010	<u>Park Place Lexus</u> <u>Plano</u>	41005	0847115	CLIENT STATES: IN ORDER TO PROVIDE OUTSTANDING SERVICE FOR OUR CLIENTS ALL LOAN CLIENT STATES: IN ORDER TO PROVIDE OUTSTANDING SERVICE FOR OUR CLIENTS ALL LOAN CARS ARE DUE BACK AT CLOSE OF BUSINESS EACH DAY, ONCE YOUR VEHICLE IS READY. A FINE OF 79.95 WILL BE CHARGED FOR EACH DAY AFTER.
Dealer Reported	12/01/2009	<u>Park Place Lexus</u> Plano	32171	0797582	CLIENT STATES: 30,000 MILE SERVICE (2004 & NEWER): REPLACE ENGINE OIL AND FILTER CLIENT STATES: 30,000 MILE SERVICE (2004 & NEWER): REPLACE ENGINE OIL AND FILTER; ROTATE TIRES; REPLACE ENGINE AIR FILTER; REPLACE AIR CONDITIONER AIR FILTER; REPLACE BRAKE FLUID; ROAD TEST VEHILCE; INSPECT BRAKES: LININGS, DISCS/DRUMS, LINES, HOSES; INSP - 32171 30K SERVICE 250 COMPLETE 30K SERVICE, LF TIRE 7/32 RF NEW WITH 10/32, RR 7/32 LR 8/32, FRONT BRAKES AT 4MM TO WEAR SENSOR, REAR BRAKES AT 6.5MM TO WEAR SENSOR. STATE INSP. EXPIRES 6/10.
Dealer Reported	12/01/2009	<u>Park Place Lexus</u> Plano	32171	0797582	CLIENT STATES: THE LOW TIRE LIGHT IS ON. PLEASE ADJUST THE TRESHOLD TO BE LOWER CLIENT STATES: THE LOW TIRE LIGHT IS ON. PLEASE ADJUST THE TRESHOLD TO BE LOWER THAN NOW 32166 SET ALL TIRE PRESSURES, ADJUSTED THE THRESHOLD TO A LOWER PSI.
Dealer Reported	12/01/2009	<u>Park Place Lexus</u> <u>Plano</u>	32171	0797582	MOUNT AND BALANCE 1 18 INCH TIRE MOUNT AND BALANCE (1) TIRE - 32171 TIRE ON RIGHT REAR WAS SHOWING CORD ON INSIDE EDGE AND TIRE AT 3/32 070 MOUNT AND BALANCED ONE NEW 19 IN. DUNOP SPORT MAXX TIRE, IS NOW ON RIGHT FRONT.
Dealer Reported	12/01/2009	<u>Park Place Lexus</u> <u>Plano</u>	32171	0797582	CLIENT STATES: CLIENT AUTHORIZES PARK PLACE LEXUS TO WASH THE VEHICLE AFTER REPA CLIENT STATES: CLIENT AUTHORIZES PARK PLACE LEXUS TO WASH THE VEHICLE AFTER REPAIRS. PARK PLACE LEXUS IS NOT RESPONSIBLE FOR VALUABLES LEFT IN THE VEHICLE OR BODY DAMAGE OF ANY TYPE.
Dealer Reported	12/01/2009	<u>Park Place Lexus</u> <u>Plano</u>	32171	0797582	CLIENT STATES: IN ORDER TO PROVIDE OUTSTANDING SERVICE FOR OUR CLIENTS ALL LOAN CLIENT STATES: IN ORDER TO PROVIDE OUTSTANDING SERVICE FOR OUR CLIENTS ALL LOAN CARS ARE DUE BACK AT CLOSE OF BUSINESS EACH DAY, ONCE YOUR VEHICLE IS READY. A FINE OF 79.95 WILL BE CHARGED FOR EACH DAY AFTER.
Dealer Reported	06/30/2009	<u>Park Place Lexus</u> <u>Plano</u>	25317	0767023	CLIENT STATES: REPLACE WINDSHIELD WIPER INSERTS 25317 20 REPLACED WIPER INSERTS
Dealer Reported	06/30/2009	<u>Park Place Lexus</u> <u>Plano</u>	25317	0767023	CLIENT STATES: PERFORM 25,000 MILE SERVICE PER LEXUS GUIDELINES: REPLACE ENGINE CLIENT STATES: PERFORM 25,000 MILE SERVICE PER LEXUS GUIDELINES: REPLACE ENGINE OIL AND FILTER; ROTATE TIRES; INSPECT ENGINE AIR FILTER; INSPECT AIR CONDITIONER AIR FILTER; ROAD TEST VEHILCE; INSPECT BRAKES: LININGS, DISCS/DRUMS, LINES, HOSES; INSPECT STE - 25317 100 PERFORMED 25K SERVICE TIRES ARE NEW IN FRONT AND REAR HAVE 8/32 L/R AND 6/32R/R BRAKES ARE APPOX. 7MM

SERVICE TYPE	DATE	SERVICE PROVIDER	MILEAGE	REPAIR #	DESCRIPTION
Dealer Reported	06/30/2009	<u>Park Place Lexus</u> <u>Plano</u>	25317	0767023	CLIENT STATES: OBD II (19962002) STATE INSPECT - CLIENT STATES: OBD II (1996 - 2002) STATE INSPECT - 25317 50 PERFORMED STATE
Dealer Reported	06/30/2009	<u>Park Place Lexus</u> <u>Plano</u>	25317	0767023	CLIENT STATES: DETAIL INTERIOR, CLEAN LEATHER AND CLEAN WINDOWS - 25317 200 DETAIL INTERIOR, CLEAN LEATHER AND CLEAN WINDOWS
Dealer Reported	06/30/2009	<u>Park Place Lexus</u> <u>Plano</u>	25317	0767023	MOUNT AND BALANCE (2) TIRES 25317 100 REPLACED FRONT TIRES
Dealer Reported	06/30/2009	<u>Park Place Lexus</u> <u>Plano</u>	25317	0767023	***FOUR WHEEL ALIGNMENT SPECIAL*** - 25317 180 PERFORMED ALIGNMENT SHEET IS IN THE CAR
Dealer Reported	06/30/2009	<u>Park Place Lexus</u> <u>Plano</u>	25317	0767023	CLIENT STATES: CHECK BLUETOOTH, CAN THE VOLUME BE TURNED UP - 25317 YOU CAN ADJUST THE VOLUME I ADJUSTED IT UP ON PAGE 403 AND 411 IN THE OWNERS MANUAL
Dealer Reported	06/30/2009	<u>Park Place Lexus</u> Plano	25317	0767023	CLIENT STATES: IN ORDER TO CONTINUE TO PROVIDE EXCELLENT SERVICE TO OUR CLIENTS CLIENT STATES: IN ORDER TO CONTINUE TO PROVIDE EXCELLENT SERVICE TO OUR CLIENTS PLEASE RETURN YOUR LOAN CAR WITHIN 6 BUSINESS HOURS UPON NOTIFICATION THAT YOUR VEHICLE IS READY OR A \$59.95 PE. EACH DAY AFTER.
Dealer Reported	06/30/2009	<u>Park Place Lexus</u> <u>Plano</u>	25317	0767023	BLEMISHES NOTED: 2 DINGS
Dealer Reported	06/30/2009	<u>Park Place Lexus</u> <u>Plano</u>	25317	0767023	CLIENT STATES: CLIENT AUTHORIZES PARK PLACE LEXUS TO WASH THE VEHICLE AFTER REPA CLIENT STATES: CLIENT AUTHORIZES PARK PLACE LEXUS TO WASH THE VEHICLE AFTER REPAIRS. PARK PLACE LEXUS IS NOT RESPONSIBLE FOR VALUABLES LEFT IN THE VEHICLE OR BODY DAMAGE OF ANY TYPE.
Dealer Reported	02/02/2009	<u>Park Place Lexus</u> <u>Plano</u>	19702	0738592	REPAIR FLAT TIRE TIRE LIGHT IS ON. 1 TIRE INDICATES 28 PSI. AUTH TO REPAIR IF NEEDED - 19702 050 REPAIRED LF TIRE. TK1969 GAYLE
Dealer Reported	02/02/2009	<u>Park Place Lexus</u> <u>Plano</u>	19702	0738592	NO WASH PULL BACK TO THE SERVICE DRIVE
Dealer Reported	12/31/2008	<u>Park Place Lexus</u> <u>Plano</u>	18550	0732124	MOUNT AND BALANCE (1) TIRE LOOSE TIRE/WHEEL - FLAT DROPPED OFF ######TIRE ROAD HAZARD WARRANTY#### - 18550 50 MOUNTED, BALANCED NEW TIRE DOT U2LNFM7R1208 AS A LOOSE WHEEL. WILL PLACE ON VEHICLE. 24545R19 DULOP SPORT MAX. OLD DOT U2LNFM7R1407. TK1969 DAVID GAYLE. 5 AND A HALF 32NDS TREAD.
Dealer Reported	12/29/2008	Sewell Lexus	1824	1463358	SEWELL RESCUE SERVICE VEHICLE HAS A FLAT TIRE (CASE#08132793) - FLAT TIRE - ROADSIDE ASSISTANCE CALLED - 1824 SEWELL RESCUE SERVICE - PUT SPARE TIRE ON CAR
Dealer Reported	10/28/2008	<u>Park Place Lexus</u> Plano	16651	0720854	CLIENT STATES: OIL CHANGE AND FILTER - 16651 MAINT. 50 COF SVC.
Dealer Reported	10/28/2008	<u>Park Place Lexus</u> <u>Plano</u>	16651	0720854	CLIENT STATES: LOW TIRE PRESSURE LIGHT - 16651 SET ALL 5 TIRE AR PRESSURE. PRESSURE WAS LOW IN ALL TIRES
Dealer Reported	10/28/2008	<u>Park Place Lexus</u> <u>Plano</u>	16651	0720854	CLIENT STATES: CLIENT AUTHORIZES PARK PLACE LEXUS TO WASH THE VEHICLE AFTER REPA CLIENT STATES: CLIENT AUTHORIZES PARK PLACE LEXUS TO WASH THE VEHICLE AFTER REPAIRS. PARK PLACE LEXUS IS NOT RESPONSIBLE FOR VALUABLES LEFT IN THE VEHICLE OR BODY DAMAGE OF ANY TYPE.
Dealer Reported	04/09/2008	<u>Park Place Lexus</u> <u>Plano</u>	10286	0679565	10,000 SERVICE FOR ALL MODELS - 10286 MAINT CP 100 10K SERV.BK - 6MM OFF SENSORS FT & REAR.TIRES - 7/32.

SERVICE TYPE	DATE	SERVICE PROVIDER	MILEAGE	REPAIR #	DESCRIPTION
Dealer Reported	04/09/2008	<u>Park Place Lexus</u> <u>Plano</u>	10286	0679565	CLIENT AUTHORIZES PARK PLACE LEXUS TO WASH THE VEHICLE AFTER REPAIRS. PARK PLACE CLIENT AUTHORIZES PARK PLACE LEXUS TO WASH THE VEHICLE AFTER REPAIRS. PARK PLACE LEXUS IS NOT RESPONSIBLE FOR VALUABLES LEFT IN THE VEHICLE OR BODY DAMAGE OF ANY TYPE.
Dealer Reported	11/16/2007	<u>Park Place Lexus</u> <u>Plano</u>	5027	0650502	5,000 MILE SERVICE 5K SERVICE - 5K
Dealer Reported	11/16/2007	<u>Park Place Lexus</u> <u>Plano</u>	5027	0650502	LEXUS SERVICE GENERAL NO WASH
Dealer Reported	08/02/2007	<u>Park Place Lexus</u> <u>Plano</u>	225	0628374	LEXUS PERSONALIZED SETTINGS - PERSONNAL SETTINGS - 225 COMPLETED PERSONALIZED SETTINGS N/A .4 HR. NO CHANGES
Dealer Reported	07/27/2007	<u>Park Place Lexus</u> <u>Plano</u>	16	0626962	PREDELIVERY SERVICE - PRE - DELIVERY SERVICE - PDI - 16 PDI 2.0 TH 2.0
Dealer Reported	07/27/2007	<u>Park Place Lexus</u> <u>Plano</u>	16	0626962	REMOVE TRANSPORTATION RAIL DUST FROM VEHICLE - RAIL DUST - 16 0.8 HRS REMOVED RAIL DUST TK 357
Dealer Reported	07/27/2007	<u>Park Place Lexus</u> Plano	16	0626962	NEW CAR TWO YEAR STATE INSPECT - 16 NEW CAR STATE 0.3 TH 0.3
Dealer Reported	07/27/2007	<u>Park Place Lexus</u> <u>Plano</u>	16	0626962	DETAIL FOR DELIVERY DETAIL WAX EXTERIOR WASH ENGINE - TONY A FRI 7/27 1200PM - 16 2.0 HRS DETAILED FOR DELIVERY TK 357

## Information Accuracy

Information presented on this Web site is summarized and standardized from repair orders completed at the time of service and submitted by Lexus dealers. When reviewing a vehicle's service history, please note that all information is provided by the Lexus dealership that conducted the service and that dealer is solely responsible for the accuracy, completeness or authenticity of any information contained in this site. Lexus provides this site and all information and materials contained herein "as is" without warranty of any kind.

Any questions or concerns regarding this information should be addressed to the applicable Lexus dealer

## **CPO Owner Information**

Dealer-reported service history records are linked to a vehicle's Vehicle Identification Number (VIN). All owner-reported service history records will be made available to the person who input the information on the site but will not be shared with future owners of the vehicle.

## **Owner-Reported Information and Privacy Terms**

Lexus makes every effort to ensure the secure collection and transmission of sensitive user information using industry-accepted data collection and encryption methodologies. The information you provide is used by Lexus and its vendors and dealers to help improve the services we render. It is occasionally provided to Lexus dealers for their marketing use. Lexus will never sell your personally identifiable information to any other company. To learn more about our privacy policies and practices with respect to this Web site, please <u>click here</u>.