

# **UIN 048C7BA**

## **Gasoline Engine**

Unit No.

12 Lexus

Unit: Make

Lexus

Model

Serial No. Site

Compartment:

Name

Gasoline Engine

Make Model Lexus

Serial No.

Capacity:

Ltrs

## **DIAGNOSIS**

All wear rates normal. Abrasive and other contaminant levels are acceptable. Viscosity within specified operating range.

Action: As oil and filter(s) already changed, resample next recommended service interval to further monitor.

DATE SAMPLED		08-Mar-17	18-Jun-15						÷.	
DATE RECEIVED		28-Jul-17	30-Jun-15							
DATE REPORTED		02-Aug-17	01-Jul-15							
LAB NO.		42021030895	42020687247							
SIF NO.		16598248	16259488							
TIME ON UNIT	Mi	45000	36000							
TIME ON OIL	Mi	5000	5000							
OIL BRAND		Toyota	Toyota							
OIL TYPE		Genuine Oil	Genuine Oil							
OIL GRADE OIL ADDED		SAE 0W20	SAE 0W20							
FILTER		Changed	Changed							
OIL CHANGED		Changed	Changed							
WO NUMBER		Onangoa	onangoa							
Metals (ppm)						Million Processor School Schoo	NATIONAL STREET, STREE	Vignoria Control de Vignoria de Constante de Vignoria		
Iron (Fe)		4	4							
Chromium (Cr)		<1	2							
Lead (Pb)		<1	<1							
Copper (Cu)		<1	1							
Tin (Sn)		1	2							
Aluminium (AI)		1	5							
Nickel (Ni)		<1	<1							
Silver (Ag)		<1	<1							
Titanium (Ti)		2	14							
Vanadium (V)		<1	<1							
Contaminants (ppm)										
Silicon (Si)		6	8							
Sodium (Na)		7	15							
Potassium (K)		<1	5							
Additives (ppm)										
Magnesium (Mg)		33	9	3						
Calcium (Ca)		2385	2288							
Barium (Ba)		<1	<1	8.						
Phosphorus (P)		819	711							
Zinc (Zn)		918	840							
Molybdenum (Mo)		70	40			1				
Boron (B)		85	32			9				
Contaminants							CAMPACATE CALL TO THE STATE OF		Marie Ma	
Water (%)		< 0.05	< 0.05							
Coolant		No	No							
Physical Tests								-		-
Viscosity (cSt 100C)		8.3	8.3							
Physical / Chemical			- 1							
Base Number (mgKC	H/g)	6.4	5.0		**					

ANALYST: Jon.Sowers












LEGEND











Since services are based on samples and information supplied by others, and since corrective actions, if any, are necessarily taken by others, these services are rendered without any warranty or liability of any kind beyond the actual amount paid to ALS Tribology for the services. Reported recommendations are based on interpretations of the generated test results and historical data. Certain test results appearing in this report may have been tested at other ALS laboratories within the Tribology divisional network.



### **UIN 048C7BA**

#### U.S. Laboratories

Atlanta, Georgia - 420 3121 Presidential Drive

21 Presidential Drive Atlanta, GA 30340 800.394.3669

800.726.5400 s - 430 Phoenix, Arizona - 440

Kansas City, Kansas - 430

935 Sunshine Road Kansas City, KS 66115 800.332.8055

toad 3319 West Earll Drive 66115 Phoenix, AZ 85017 5 800.445.7930

Portland, Oregon - 401

4943 NW Front Avenue Portland, OR 97210 800.770.4128 **Sparks, Nevada - 400** 1375 Greg Street, Suite 104 Sparks, NV 89431 800.524.7848

Valley View, Ohio - 410

6180 Halle Dr. Suite D

Valley View, OH44125

#### **Canadian Laboratories**

**Burlington, Ontario - 450** 

1240 Burloak Drive, Unit 6 Burlington, ON L7L 6B3 877.732.9559

Edmonton, Alberta - 402

10717-176 Street Edmonton, AB T5S 1K1 888.489.0057

### Sales & Marketing

Houston, Texas

10450 Stancliff Road, Suite 210 Houston, TX 77099 877.835.8437

#### International Locations

#### Australia

Brisbane, Perth, Sydney, Muswellbrook

Europe

Prague

New Zealand Wellington

**South America** 

Santiago de Chile

Southeast Asia Kuala Lumpur, Singapore

0069 v1.5