## **SERVICE** (/lexusdrivers/service) | SERVICE HISTORY

Your vehicle maintenance history can be accessed by any Lexus dealer you visit. You can also use your Lexus Drivers account to view and manually enter additional records should you have service performed elsewhere.

## SERVICE HISTORY FOR YOUR POSSIBLE SC

SELECT YOUR LEX	KUS VEHICLE BELOW			
POSSIBLE SC				
		PRINT	ADD SERVICE	
SERVICE HIS	TORY	_		
SERVICE HISTORY FOR: POSSIBLE SC VIN: JTHFN45Y179011109			Options shown	
		ī	Filter History By Year	
			All	
130399 MILES			<b>DATE</b> : 06/29/2017	
	<b>REPAIR#</b> 0011812			
	<b>REPORTED BY:</b> Lexus of Winter Park			
	SERVICE: MILES OUT:	SERVICE: P	ERFORMED	
	DESCRIPTION: MILES OUT:		ITARY WASH AND	
	- L-TECHNICIAN MIIST DOCUMENT	VACUUM	How is your visit? 🗶	

~|~TECHNICIAN MUST DOCUMENT

MILES OUT WHEN SERVICE IS

COMPLETED ~1~130399 ~1~MILES OUT:

DESCRIPTION: PERFORMED

COMPLIMENTARY WASH AND

VACUUM ~|~PERFORM WASH &

VACUUM AFTER SERVICE ~|~

~|~PERFORMED COMPLIMENTARY

WASH AND VACUUM

**SERVICE: PROVIDED** 

**DESCRIPTION:** PROVIDED ~ | ~

COURTESY VEHICLE - LEXUS LOANER TO GUEST ~|~PROVIDE GUEST WITH COMPLIMENTARY LEXUS LOANER ~|~~|~COURTESY VEHICLE - LEXUS LOANER TO GUEST ~|~~|~PROVIDED **SERVICE:** TEXT MESSAGE

COMMUNICATION AUTHORIZATION

**DESCRIPTION:** TEXT MESSAGE

COMMUNICATION AUTHORIZATION
~I~YOU AGREE THAT WE MAY
CONTACT YOU REGARDING SERVICE
UPDATES OR OFFERS VIA TEXT
MESSAGES AT THE CELL PHONE
NUMBER YOU HAVE PROVIDED. ~I~
~I~TEXT MESSAGE COMMUNICATION
AUTHORIZATION

**SERVICE:** TIGHTEN RIGHT REAR

SENSOR NUT.

**DESCRIPTION:** TIGHTEN RIGHT

REAR SENSOR NUT. ~|~C/S TPS LIGHT IS ON. JUST REPLACED 3 TIRE SENSORS. SEE HISTORY. PLEASE CHECK AND ADVISE ~|~AIR LEAKING FROM RIGHT REAR SENSOR. ~|~TIGHTEN RIGHT REAR SENSOR NUT.

130263 MILES DATE: 06/27/2017

**REPAIR#** 0011028

**REPORTED BY:** Lexus of Winter Park

**SERVICE:** COMPLETED 125,000 MILES

OR 150 MONTHS SERVICE - 2007 SC 430  $\,$ 

(LEXUS

**DESCRIPTION:** COMPLETED 125,000 MILES OR 150 MONTHS SERVICE - 2007 SC 430 (LEXUS ~ | ~125,000 MILES OR 150

**SERVICE:** MILES OUT:

**DESCRIPTION: MILES OUT:** 

~|~TECHNICIAN MUST DOCUMENT MILES OUT WHEN SERVICE IS COMPLETED ~|~130265 ~|~MILES OUT: MONTHS SERVICE - 2007 SC 430 (LEXUS FACTORY MENU) ~ | ~ ~ | ~COMPLETED 125,000 MILES OR 150 MONTHS SERVICE - 2007 SC 430 (LEXUS

**SERVICE:** NEEDS ID#2 AND #4 LEFT FRONT AND REAR.

**DESCRIPTION:** NEEDS ID#2 AND #4 LEFT FRONT AND REAR. ~|~GUEST STATES THE TIRE PRESSURE LIGHT IS FLASHING CHECK AND ADVIS ~|~ ~|~NEEDS ID#2 AND #4 LEFT FRONT AND REAR.

**SERVICE: PERFORMED** 

WASH AND VACUUM

CAA78E1 RIGHT REAR

COMPLIMENTARY WASH AND VACUUM

DESCRIPTION: PERFORMED

COMPLIMENTARY WASH AND

VACUUM ~|~PERFORM WASH &

VACUUM AFTER SERVICE ~|~

~|~PERFORMED COMPLIMENTARY

**SERVICE:** TIRE PRESSURE MONITOR SENSOR, R&R NEW ID#1 CAA78E1 RIGHT REAR

DESCRIPTION: TIRE PRESSURE

MONITOR SENSOR, R&R NEW ID#1

CAA78E1 RIGHT REAR ~ | ~TIRE

PRESSURE MONITOR SENSOR,

R&R/RECOMMEND REPLACING ID#1

AS WELL. ~ | ~ | ~TIRE PRESSURE

MONITOR SENSOR, R&R NEW ID#1

**SERVICE:** TIRE PRESSURE MONITOR SENSOR, R&R/NEW ID#2 CAD48E1 LEFT FRONT **DESCRIPTION:** TIRE PRESSURE MONITOR SENSOR, R&R/NEW ID#2

**SERVICE:** NO CHARGE FOR DIAG. WORK PERFORMED.

**DESCRIPTION:** NO CHARGE FOR

DIAG. WORK PERFORMED.
~|~DIAGNOSTIC CHARGE OF \$79.95
THIS CHARGE WILL BE WAIVED IF
CUSTOMER AGREES TO REPAIR. ~|~
~|~NO CHARGE FOR DIAG. WORK
PERFORMED.

**SERVICE:** TEXT MESSAGE

COMMUNICATION AUTHORIZATION **DESCRIPTION:** TEXT MESSAGE

COMMUNICATION AUTHORIZATION
~|~YOU AGREE THAT WE MAY
CONTACT YOU REGARDING SERVICE
UPDATES OR OFFERS VIA TEXT
MESSAGES AT THE CELL PHONE
NUMBER YOU HAVE PROVIDED. ~|~
~|~TEXT MESSAGE COMMUNICATION
AUTHORIZATION

**SERVICE:** TIRE PRESSURE MONITOR SENSOR, R&R NEW ID#4 A1728E1 LEFT REAR

**DESCRIPTION:** TIRE PRESSURE

MONITOR SENSOR, R&R NEW ID#4
A1728E1 LEFT REAR ~|~TIRE PRESSURE
MONITOR SENSOR, R&R/ID#4 LOW
VOLTAGE LEFT REAR. ~|~~|~TIRE
PRESSURE MONITOR SENSOR, R&R
NEW ID#4 A1728E1 LEFT REAR

SERVICE: VALET PICK UP AND
DELIVERY CHARGE - \$59.95
DESCRIPTION: VALET PICK UP AND
DELIVERY CHARGE - \$59.95

CAD48E1 LEFT FRONT ~|~TIRE PRESSURE MONITOR SENSOR, R&R/ID#2 NOT TRANSMITTING LEFT FRONT. ~|~~|~TIRE PRESSURE MONITOR SENSOR, R&R/NEW ID#2 CAD48E1 LEFT FRONT PICKUP - UNDER 40 MILES ROUNDTRIP- \$59.95 CHARGE ~|~ ~|~VALET PICK UP AND DELIVERY CHARGE - \$59.95

123903 MILES

**DATE:** 12/22/2016

**REPAIR#** 0066875

**REPORTED BY:** Lexus of Winter Park

**SERVICE:** COMPLETED 120,000 MILES OR 144 MONTHS SERVICE - 2007 SC 430 (LEXUS

DESCRIPTION: COMPLETED 120,000
MILES OR 144 MONTHS SERVICE - 2007
SC 430 (LEXUS ~ | ~ 120,000 MILES OR 144
MONTHS SERVICE - 2007 SC 430
(LEXUS FACTORY MENU) ~ | ~
~ | ~ COMPLETED 120,000 MILES OR 144
MONTHS SERVICE - 2007 SC 430
(LEXUS

SERVICE: ELG R&R AIRBAG
INFLATOR
DESCRIPTION: ELG R&R AIRBAG

INFLATOR ~ | ~ ELG R&R AIRBAG INFLATOR ~ | ~ ELG SAFETY RECALL ELG - REMEDY - FRONT PASSENGER AIRBAG INFLATOR MODU ~ | ~ SSC ~ | ~ ELG R&R AIRBAG INFLATOR

**SERVICE:** FLUSH POWER STEERING

**SYSTEM** 

**DESCRIPTION: FLUSH POWER** 

STEERING SYSTEM REMARKS:
PREVENTATIVE MAINTENANCE
~|~PREVENTATIVE MAINTENANCE
~|~FLUSH POWER STEERING SYSTEM

STEERING SYSTEM ~ | ~ FLUSH POWER

**SERVICE:** FRONT LOWER CONTROL

ARM, R&R (ADD ALIGNMENT) **DESCRIPTION:** FRONT LOWER

CONTROL ARM, R&R (ADD
ALIGNMENT) ~I~FRONT LOWER
CONTROL ARM, RIGHT FRONT
BUSHING SPLITTING/ CRACKED ~I~
~I~FRONT LOWER CONTROL ARM,
R&R (ADD ALIGNMENT) FRONT
LOWER CONTROL ARM, R&R (ADD
ALIGNMENT) ~I~FRONT LOWER
CONTROL ARM, LEFT FRONT FRONT
BUSHING SPLITTING/ CRACKED
~I~LEFT FRONT BUSHING SPLITTING/
CRACKED ~I~FRONT LOWER
CONTROL ARM, R&R (ADD
ALIGNMENT)

**SERVICE:** LOANER

**DESCRIPTION:** LOANER ~ | ~

COURTESY VEHICLE - LEXUS LOANER
TO GUEST ~|~PROVIDE GUEST WITH
COMPLIMENTARY LEXUS LOANER
~|~~|~COURTESY VEHICLE - LEXUS
LOANER TO GUEST ~|~~|~LOANER

**SERVICE:** MILES OUT:123907

**DESCRIPTION: MILES OUT:123907** 

~|~TECHNICIAN MUST DOCUMENT

MILES OUT WHEN SERVICE IS

COMPLETED ~ | ~ ~ | ~ MILES OUT:123907

**SERVICE: PERFORMED** 

COMPLIMENTARY WASH AND

VACUUM

**DESCRIPTION: PERFORMED** 

COMPLIMENTARY WASH AND VACUUM ~|~PERFORM WASH & VACUUM AFTER SERVICE ~|~ ~|~PERFORMED COMPLIMENTARY WASH AND VACUUM

**SERVICE:** REPLACED REMOTE KEY

**BATTERY** 

**DESCRIPTION: REPLACED REMOTE** 

KEY BATTERY ~ | ~ REPLACE REMOTE KEY BATTERY- MAINTENANCE REMARKS: OTHER - SEE COMMENTS SECTION ~ | ~ ~ | ~ REPLACED REMOTE

**KEY BATTERY** 

**SERVICE:** TEXT MESSAGE

COMMUNICATION AUTHORIZATION

**DESCRIPTION:** TEXT MESSAGE

COMMUNICATION AUTHORIZATION ~|~YOU AGREE THAT WE MAY CONTACT YOU REGARDING SERVICE UPDATES OR OFFERS VIA TEXT MESSAGES AT THE CELL PHONE NUMBER YOU HAVE PROVIDED. ~|~TEXT MESSAGE COMMUNICATION AUTHORIZATION ~|~TEXT MESSAGE COMM ... READ MORE ()

**SERVICE:** VALET PICK UP AND

**DELIVERY CHARGE - \$79.95** 

**DESCRIPTION:** VALET PICK UP AND

DELIVERY CHARGE - \$79.95 ~|~CUSTOMER REQUESTS VALET PICKUP - UNDER 60 MILES ROUNDTRIP- \$79.95 CHARGE ~|~ ~|~VALET PICK UP AND DELIVERY

CHARGE - \$79.95

117072 MILES DATE: 06/02/2016

**REPAIR#** 0032166

**REPORTED BY:** Lexus of Winter Park

SERVICE: .

**DESCRIPTION:** .~I~CORRECT

MILEAGE ~ | ~ ~ | ~.

**SERVICE:** BATTERY SERVICE

**DESCRIPTION:** BATTERY SERVICE

~|~BATTERY SERVICE. POSITIVE TERMINAL HAS CORROSION

REMARKS: CORROSION ON TERMINALS ~|~POSITIVE TERMINAL HAS CORROSION REMARKS: CORROSION ON TERMINALS ~|~BATTERY SERVICE

SERVICE: DIAGNOSTICS
PERFORMED AS REQUESTED
DESCRIPTION: DIAGNOSTICS

PERFORMED AS REQUESTED
~|~DIAGNOSTIC CHARGE OF \$79.95
THIS CHARGE WILL BE WAIVED IF
CUSTOMER AGREES TO REPAIR. ~|~
~|~DIAGNOSTICS PERFORMED AS
REQUESTED

**SERVICE:** ENGINE MOUNT, R&R **DESCRIPTION:** ENGINE MOUNT, R&R ~I~ENGINE MOUNT, R&R. THI

R&R ~|~ENGINE MOUNT, R&R. THE
RUBBER IS CRACKED. ~|~BOTH
ENGINE MOUNTS RUBBER ARE
CRACKED. ~|~ENGINE MOUNT,
R&R ENGINE MOUNT, R&R
~|~ENGINE MOUNT, R&R.
RECOMMENDED TO REPLACE THE
TRANSMISSION MOUNT TOO
BECAUSE OF THE MILEAGE AND
TIME OF THE VEHICLE.
~|~RECOMMENDED TO REPLACE THE
TRANSMISSION MOUNT TOO
BECAUSE OF THE MILEAGE AND
TIME OF THE VE ... READ MORE ()

SERVICE: FRONT BRAKE JOB, INCLS. REFACING, W/O HARDWARE, R&R DESCRIPTION: FRONT BRAKE JOB, INCLS. REFACING, W/O HARDWARE, R&R ~1~FRONT BRAKE JOB, INCLS. REFACING, W/O HARDWARE, R&R. THE INNER PADS ARE AT 1MM AND STRONG PULSATION. REMARKS: BRAKE PULSATION ~1~THE INNER PADS ARE AT 1MM AND STRONG PULSATION. ... READ MORE ()

**SERVICE:** FUEL INJECTORS, CLEAN **DESCRIPTION:** FUEL INJECTORS, CLEAN. CLEAN ~ I ~ FUEL INJECTORS, CLEAN. MAINTENANCE. ~ I ~ FUEL INJECTOR CLEAN, MAINTENANCE. ~ I ~ FUEL INJECTORS, CLEAN

**SERVICE:** MILES OUT: 117072 **DESCRIPTION:** MILES OUT: 117072

~|~TECHNICIAN MUST DOCUMENT

MILES OUT WHEN SERVICE IS

COMPLETED ~|~~|~MILES OUT: 117072

SERVICE: PERFORM 105,000 MILE SERVICE DESCRIPTION: PERFORM 105,000 MILE SERVICE ~1~PERFORM 105,000 MILE SERVICE ~1~SERVICE DUE

**SERVICE:** PERFORMED

COMPLIMENTARY WASH AND

VACUUM

**SERVICE:** POWER OUTLET 15 AMP FUSE

~I~PERFORM 105,000 MILE SERVICE

**DESCRIPTION:** PERFORMED

COMPLIMENTARY WASH AND

VACUUM ~|~PERFORM WASH &

VACUUM AFTER SERVICE ~|~

~|~PERFORMED COMPLIMENTARY

WASH AND VACUUM

**SERVICE:** R&R COMBINATION

**METER** 

**DESCRIPTION:** R&R COMBINATION
METER ~I~THE COMBINATION METER
IS DAMAGE, THE PLASTIC FRONT
COVER IS BROKE AND THE DIGITAL
DISPLAY FOR THE MILEAGE IS BROKE.
NO MILEAGE DISPLAY. ~I~THE
COMBINATION METER IS DAMAGE,
THE PLASTIC FRONT COVER IS BROKE
AND TH ... **READ MORE ()** 

SERVICE: REPLACE 15 AMP POWER
OUTLET FUSE. THE MEMORY SEAT
FEATURE WAS INSPECTED AND IS
DESCRIPTION: REPLACE 15 AMP
POWER OUTLET FUSE. THE MEMORY
SEAT FEATURE WAS INSPECTED AND
IS ~I~CUSTOMER STATES THE PRESET
FOR SEATS ARE NOT WORKING ~I~15
AMP POWER OUTLET FUSE HAS AN
OPEN CIRCUIT AND THE MEMORY
SEAT SYSTEM IS PART OF THAT
CIRCUIT. ~I~RE ... READ MORE ()

SERVICE: TEMPORARILY OUT OF
STOCK, LOCATED PART IN LEXUS
WAREHOUSE, ORDERED
DESCRIPTION: TEMPORARILY OUT
OF STOCK, LOCATED PART IN LEXUS
WAREHOUSE, ORDERED ~ | ~ ELG
SAFETY RECALL ELG - REMEDY FRONT PASSENGER AIRBAG
INFLATOR MODU ~ | ~ PARTS NOT
AVAILABLE YET ~ | ~ TEMPORARILY
OUT OF STOCK, LOCATED PART IN
LEXUS WAREHOUSE, ORDERED

DESCRIPTION: POWER OUTLET 15

AMP FUSE ~I~CUSTOMER STATES CIG

LIGHTER SOCKET IS NOT WORKING

~I~THE POWER OUTLET 15 AMP FUSE

HAS AN OPEN CIRCUIT. ~I~POWER

OUTLET 15 AMP FUSE

SERVICE: REAR BRAKE JOB, INCLS.
REFACING, W/O HARDWARE, R&R
DESCRIPTION: REAR BRAKE JOB,
INCLS. REFACING, W/O HARDWARE,
R&R ~I~REAR BRAKE JOB, INCLS.
REFACING, W/O HARDWARE, R&R.
THE PADS ARE AT 2MM. REMARKS:
BRAKE PULSATION ~I~THE PADS ARE
AT 2MM. REMARKS: BRAKE
PULSATION ~I~REAR BRAKE JOB,
INCLS. REFAC ... READ MORE ()

**SERVICE:** SEE OTHER LINES. **DESCRIPTION:** SEE OTHER LINES.

~|~CUSTOMER STATES CLUSTER IS
BROKEN AND MILEAGE CAN' SEEN..

~|~~|~SEE OTHER LINES.

SERVICE: THROTTLE BODY
CLEANING SERVICE
DESCRIPTION: THROTTLE BODY
CLEANING SERVICE ~ | ~ THROTTLE
BODY CLEANING SERVICE.
MAINTENANCE. ~ | ~ THROTTLE BODY
CLEANING SERVICE. MAINTENANCE.
~ | ~ THROTTLE BODY CLEANING
SERVICE

**105175 MILES DATE**: 10/13/2015

**REPAIR#** 0085445

**REPORTED BY:** Lexus of Winter Park

**SERVICE:** NO WASH

**DESCRIPTION:** NO WASH ~ | ~\*\*\*\*\*\*

NO WASH \*\*\*\*\*\* ~ | ~ NO WASH ~ | ~ NO

WASH

**SERVICE:** MILES OUT:

**DESCRIPTION: MILES OUT:** 

~I~TECHNICIAN MUST DOCUMENT MILES OUT WHEN SERVICE IS

COMPLETED ~1~105175 ~1~MILES OUT:

**SERVICE: REPLACED ONE TIRE** 

PRESSURE SENSOR, RT REAR ID3 ..

NOTE: THE OTHER THREE TIRES

**DESCRIPTION:** REPLACED ONE TIRE

PRESSURE SENSOR, RT REAR ID3 ..

NOTE: THE OTHER THREE TIRES
~I~CUSTOMER STATE VEHICLE TIRE
ICON CAME ON , NOTE: WE
INSTALLED THE TIRES. ~I~REAR TIRES
WERE LOW 30 PSI , RIGHT REAR TIRE
ID3 NOT READING ~I~REPLACED ONE

TIRE P ... READ MORE ()

**SERVICE:** LPASS

DESCRIPTION: LPASS ~ | ~ "L"PASS -

AUTOMATED VEHICLE RECOGNITION SYSTEM

IDENTIFICATION LABEL HAS BEEN APPLIED TO VEHICLE. ~|~LPASS

~I~LPASS

**SERVICE:** PERFORM WORLD CLASS

INSPECTION ON VEHICLE

**DESCRIPTION: PERFORM WORLD** 

CLASS INSPECTION ON VEHICLE

~|~PERFORM WORLD CLASS

INSPECTION ON VEHICLE ~ | ~ WCI

~|~PERFORM WORLD CLASS

INSPECTION ON VEHICLE

**SERVICE:** TIRE PRESSURE MONITOR

SENSOR, R&R

**DESCRIPTION:** TIRE PRESSURE

MONITOR SENSOR, R&R ~|~TIRE PRESSURE MONITOR SENSOR, R&R RIGHT FRONT TIRE SENSOR ID1 LOW BATTERY VOLTAGE ~|~~|~TIRE PRESSURE MONITOR SENSOR, R&R,CUSTOMER DECLINED SERVICE -RECOMMENDED, NOT DONE-TIRE

PRESSURE MONIT ... **READ MORE**() TIRE PRESSURE MONITOR SENSOR.

R&R ~| ~TIRE PRESSURE MONITOR SENSOR, R&R LEFT FRONT TIRE ID 2

LOW BATTERY VOLTAGE ~ | ~ ~ | ~TIRE

PRESSURE MONITOR SENSOR,

R&R,CUSTOMER DECLINED SERVICE -

RECOMMENDED, NOT DONE-TIRE PRESSURE MONITOR SENS ... READ

MORE () TIRE PRESSURE MONITOR

SENSOR, R&R ~|~TIRE PRESSURE
MONITOR SENSOR, R&R LEFT REAR
TIRE ID4 LOW BATTERY VOLTAGE ~|~
~|~TIRE PRESSURE MONITOR SENSOR,
R&R,CUSTOMER DECLINED SERVICE RECOMMENDED, NOT DONE-TIRE
PRESSURE MONITOR
SENSOR ... READ MORE ()

**SERVICE:** TIRE PRESSURE MONITOR SENSOR, R&R REPLACED RIGHT REAR

TIRE SENSOR ID3 NEW ID#2

**DESCRIPTION:** TIRE PRESSURE

MONITOR SENSOR, R&R REPLACED RIGHT REAR TIRE SENSOR ID3 NEW ID#2 ~1~TIRE PRESSURE MONITOR SENSOR, R&R RIGHT REAR TIRE ID3 NOT READING ~1~ ~1~TIRE PRESSURE MONITOR SENSOR, R&R REPLACED RIGHT REAR TIRE SENSOR ID3 NEW ... **READ MORE ()** 

**103923 MILES DATE**: 09/03/2015

**REPAIR#** 0080340

**REPORTED BY:** Lexus of Winter Park

**SERVICE:** ALIGN FOUR WHEELS

**DESCRIPTION:** ALIGN FOUR

WHEELS ~ | ~ ALIGN FOUR WHEELS ~ | ~

~|~ALIGN FOUR WHEELS

**SERVICE: MILES OUT:** 

**DESCRIPTION: MILES OUT:** 

~|~TECHNICIAN MUST DOCUMENT MILES OUT WHEN SERVICE IS COMPLETED ~|~103923 ~|~MILES OUT: **SERVICE:** LPASS

DESCRIPTION: LPASS ~ I ~ "L"PASS -

AUTOMATED VEHICLE
RECOGNITION SYSTEM
IDENTIFICATION LABEL HAS BEEN
APPLIED TO VEHICLE. ~|~~|~~LPASS

**SERVICE: MOUNT AND BALANCE** 

TIRE (OLD & NEW DOT #

REQUIRED)OLD DOT: EUJX XT8 4311 \*3,

44

**DESCRIPTION: MOUNT AND** 

BALANCE TIRE (OLD & NEW DOT # REQUIRED)OLD DOT: EUJX XT8 4311 \*3, 44 ~ | ~ MOUNT AND BALANCE TIRE + 3

.. CUSTOMER HAS AGREED TO INSTALLING THE BRIDGESTONE DRIVE GUARD 245/40/18 93Y ALL 4 TIRES HAVE INNER SHOULDER WEAR TO SECONDAR ... **READ MORE ()** 

**SERVICE:** NO CHARGE... CUSTOMER

PURCHASED NEW TIRES.

**DESCRIPTION: NO CHARGE...** 

CUSTOMER PURCHASED NEW TIRES. ~|~BALANCE 4 TIRES ~|~ ~|~NO CHARGE... CUSTOMER PURCHASED NEW TIRES.

**SERVICE: PERFORM WORLD CLASS** 

INSPECTION ON VEHICLE

**DESCRIPTION: PERFORM WORLD** 

CLASS INSPECTION ON VEHICLE ~|~PERFORM WORLD CLASS INSPECTION ON VEHICLE ~|~ ~|~PERFORM WORLD CLASS INSPECTION ON VEHICLE

**SERVICE:** PERFORM 100,000 MILE

**SERVICE** 

**DESCRIPTION:** PERFORM 100,000

MILE SERVICE ~|~PERFORM 100,000 MILE SERVICE ~|~~|~PERFORM 100,000

MILE SERVICE

**SERVICE: PERFORMED** 

COMPLIMENTARY WASH AND

VACUUM

**DESCRIPTION: PERFORMED** 

COMPLIMENTARY WASH AND VACUUM ~|~PERFORM WASH & VACUUM AFTER SERVICE ~|~
~|~PERFORMED COMPLIMENTARY

WASH AND VACUUM

**96647 MILES DATE**: 01/30/2015

**REPAIR#** 0045705

**REPORTED BY:** Lexus of Winter Park

SERVICE: '

**DESCRIPTION:** '~|~"L"PASS -

AUTOMATED VEHICLE
RECOGNITION SYSTEM
IDENTIFICATION LABEL HAS BEEN
APPLIED TO VEHICLE. ~|~~|~'

**SERVICE:** ALIGN FOUR WHEELS

**DESCRIPTION: ALIGN FOUR** 

WHEELS ~ | ~ ALIGN FOUR WHEELS ~ | ~

~I~ALIGN FOUR WHEELS

**SERVICE:** BALANCED 4 TIRES

**DESCRIPTION:** BALANCED 4 TIRES

~|~BALANCE 4 TIRES ~|~ ~|~BALANCED 4 TIRES **SERVICE:** BATTERY, R&R

**DESCRIPTION:** BATTERY, R&R

~I~BATTERY, R&R ~I~~I~BATTERY,

R&R

**SERVICE:** MILES OUT: 96647

**DESCRIPTION:** MILES OUT: 96647

~|~TECHNICIAN MUST DOCUMENT MILES OUT WHEN SERVICE IS

COMPLETED ~|~~|~MILES OUT: 96647

**SERVICE: PERFORM WORLD CLASS** 

INSPECTION ON VEHICLE

**DESCRIPTION: PERFORM WORLD** 

CLASS INSPECTION ON VEHICLE ~|~PERFORM WORLD CLASS INSPECTION ON VEHICLE ~|~ ~|~PERFORM WORLD CLASS INSPECTION ON VEHICLE

**SERVICE:** REPLACED RIGHT REAR

SHOCK ASSM

**DESCRIPTION:** REPLACED RIGHT

REAR SHOCK ASSM ~|~R/R SHOCK LEAKING ~|~SHOCK LEAKING LABOR WITH MOUNT ~|~REPLACED RIGHT REAR SHOCK ASSM **SERVICE: PERFORM 95,000 MILE** 

**SERVICE** 

**DESCRIPTION:** PERFORM 95,000

MILE SERVICE ~| ~PERFORM 95,000 MILE SERVICE ~| ~ | ~PERFORM 95,000 MILE SERVICE, TIRE THREAD: LF 5/32

RF 5/32 LR 5/32 RR 5/32 BATTERY: 12.43V BRAKE LINING LF 5MM RF

5MM LR 5MM RR 5MM

**SERVICE:** PERFORMED

**COMPLIMENTARY WASH AND** 

**VACUUM** 

**DESCRIPTION:** PERFORMED

COMPLIMENTARY WASH AND
VACUUM ~|~PERFORM WASH &
VACUUM AFTER SERVICE ~|~
~|~PERFORMED COMPLIMENTARY

WASH AND VACUUM

**SERVICE:** RR UPPER SHOCK/STRUT

INSUL/MNT/SUPP, R&R (ADD

ALIGNMENT)

**DESCRIPTION: RR UPPER** 

SHOCK/STRUT INSUL/MNT/SUPP, R&R (ADD ALIGNMENT) ~|~RR UPPER SHOCK/STRUT INSUL/MNT/SUPP, R&R (ADD ALIGNMENT) RIGHT REAR STRUT ~|~~|~RR UPPER SHOCK/STRUT INSUL/MNT/SUPP, R&R

(ADD ALIGNMENT)

93597 MILES DATE: 10/31/2014

**REPAIR#** 0031752

**REPORTED BY:** Lexus of Winter Park

**SERVICE:** L"PASS - AUTOMATED VEHICLE RECOGNITION SYSTEM IDENTIFICATION LABEL HAS BEEN

**SERVICE:** MILES OUT:93595

**DESCRIPTION:** MILES OUT:93595 ~ | ~TECHNICIAN MUST DOCUMENT

**DESCRIPTION: "L"PASS-**

AUTOMATED VEHICLE
RECOGNITION SYSTEM
IDENTIFICATION LABEL HAS BEEN A
~I~"L"PASS - AUTOMATED VEHICLE
RECOGNITION SYSTEM
IDENTIFICATION LABEL HAS BEEN
APPLIED TO VEHICLE. ~I~"L"PASS AUTOMATED VEHICLE
RECOGNITION SYSTEM

MILES OUT WHEN SERVICE IS COMPLETED ~|~93597 ~|~MILES OUT:93595

**SERVICE: PERFORM WORLD CLASS** 

IDENTIFICAT ... READ MORE ()

INSPECTION ON VEHICLE

**DESCRIPTION: PERFORM WORLD** 

CLASS INSPECTION ON VEHICLE
~|~PERFORM WORLD CLASS
INSPECTION ON VEHICLE
~|~PERFORM WORLD CLASS
INSPECTION ON VEHICLE
~|~PERFORM WORLD CLASS
INSPECTION ON VEHICLE

**SERVICE:** PERFORMED

**COMPLIMENTARY WASH AND** 

VACUUM

**DESCRIPTION: PERFORMED** 

COMPLIMENTARY WASH AND VACUUM ~|~PERFORM WASH & VACUUM AFTER SERVICE ~|~ ~|~PERFORMED COMPLIMENTARY WASH AND VACUUM

**SERVICE:** REPLACE BLOWN FUSE

**DESCRIPTION: REPLACE BLOWN** 

FUSE ~|~CUSTOMER STATES THAT LIGHT STILL DOES NOT WORK ~|~CUSTOMER HAS RADAR DETECTOR IN CIGARETTE LIGHTER ~|~REPLACE BLOWN FUSE **SERVICE:** VEHICLE OPERATING AS

**DESIGNED** 

**DESCRIPTION: VEHICLE** 

OPERATING AS DESIGNED
~|~CUSTOMER STATES VEHICLE HAS
TO BE JUMP STARTED ~|~BATTERY
TESTED GOOD ON GR8 ~|~VEHICLE
OPERATING AS DESIGNED

91917 MILES DATE: 08/28/2014

**REPAIR#** 0022214

**REPORTED BY:** Lexus of Winter Park

**SERVICE:** DRIVE BELTS, ALL, R&R **DESCRIPTION:** DRIVE BELTS, ALL, R&R ~1~DRIVE BELTS, ALL, R&R

**SERVICE:** L"PASS - AUTOMATED VEHICLE RECOGNITION SYSTEM IDENTIFICATION LABEL HAS BEEN

~|~DRIVE BELTS, ALL, R& ~|~DRIVE BELTS, ALL, R&R

AUTOMATED VEHICLE
RECOGNITION SYSTEM
IDENTIFICATION LABEL HAS BEEN A
~|~"L"PASS - AUTOMATED VEHICLE
RECOGNITION SYSTEM
IDENTIFICATION LABEL HAS BEEN
APPLIED TO VEHICLE. ~|~"L"PASS AUTOMATED VEHICLE
RECOGNITION SYSTEM
IDENTIFICAT ... READ MORE ()

**DESCRIPTION: "L"PASS-**

**SERVICE:** MILES OUT:91917 **DESCRIPTION:** MILES OUT:91917

~|~TECHNICIAN MUST DOCUMENT

MILES OUT WHEN SERVICE IS

COMPLETED ~|~91917 ~|~MILES

OUT:91917

SERVICE **DESCRIPTION:** PERFORM 90,000

MILE SERVICE ~|~PERFORM 90,000

MILE SERVICE ~|~PERFORM 90,000

MILE SERVICE ~|~PERFORM 90,000

MILE SERVICE, FRONT PADS =4.0MM

REAR PADS =4.0MM TIRES 5/32

**SERVICE:** PERFORM 90,000 MILE

INSPECTION ON VEHICLE

DESCRIPTION: PERFORM WORLD

CLASS INSPECTION ON VEHICLE

~|~PERFORM WORLD CLASS

INSPECTION ON VEHICLE

~|~PERFORM WORLD CLASS

INSPECTION ON VEHICLE

~|~PERFORM WORLD CLASS

INSPECTION ON VEHICLE

**SERVICE:** PERFORM WORLD CLASS

COMPLIMENTARY WASH AND VACUUM

DESCRIPTION: PERFORMED

COMPLIMENTARY WASH AND

VACUUM ~|~PERFORM WASH &

VACUUM AFTER SERVICE ~|~

~|~PERFORMED COMPLIMENTARY

WASH AND VACUUM

**SERVICE:** PERFORMED

SERVICE: PERFORMED FUEL
INJECTOR CLEANING & THROTTLE
BODY CLEANING SERVICE
DESCRIPTION: PERFORMED FUEL
INJECTOR CLEANING & THROTTLE
BODY CLEANING SERVICE
~|~PERFORM FUEL INJECTION
CLEANING & THROTTLE BODY
CLEANING SERVICE COUPON PRICE
\$189.95 ~|~~|~PERFORMED FUEL

INJECTOR CLEANING & THROTTLE BODY CLEANING SERVICE, ... **READ** 

**SERVICE:** REPLACE BLOWN FUSE **DESCRIPTION:** REPLACE BLOWN

FUSE ~|~C/S THAT BOTH POWER

OUTLETS DO NOT WORK < ADVISE>
~|~BLOWN FUSE ~|~REPLACE BLOWN

FUSE

MORE ()